



## CERTIFICATE OF THOROUGH EXAMINATION

TOWER LIGHT

CERTIFICATE / REPORT NO : CRT-105476

STICKER NO : 87871

JOB NO : WO-28836

EQUIPMENT OWNER : 24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SUDHIR RENTALS -24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
TYPE OF INSPECTION : 314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
PERIODIC VISUAL AND FUNCTIONAL INSPECTIONLOCATION: DAMMAM YARD  
DATE OF INSPECTION : 25-Nov-2023  
Frequency 6 month  
Next Inspection Due 24-May-2024EQUIPMENT DESCRIPTION : 4 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
DIESEL ENGINE POWERED TOWER LIGHT OF WATTAGE CAPACITY 4 X 400 W.MANUFACTURER : VARADA ENERGIES PVT LTD  
MODEL/TYPE : SGL-7.5  
MANUFACTURED YEAR : 2023  
SERIAL NO : VEPL/2023-24/314  
OWNER ID : STL-466  
WORK PROCEDURE NO : SA-WP-06  
REFERENCE STANDARDS : ISO 8528-13:2016  
DATE OF PREVIOUS INSPECTION :  
PREVIOUS INSPECTION DETAILS: NEWWATTAGE: 4 X 400 W  
FUEL TYPE: DIESEL  
LIGHTING TOWER HEIGHT - 8.5 METERS  
MASS - 2800 KG  
RESULT : SATISFACTORY-PASS  
CHECKLIST NO : 44530REMARKS/RECOMMENDATION :  
PRE-OPERATIONAL CHECK FOR GENERAL CONDITION AND WORKING OF THE EQUIPMENT IS RECOMMENDED BEFORE EACH USE.

Reviewed By : MOHAMED ANWAR DEEN

Authorised Inspector : LIJO MATHAI CHERIAN

SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE  
SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SERIAL NO: VEPL/2023-24/314 VALID TILL : 24-May-2024 Report No: CRT-105476 SE

## THIS CERTIFICATE BECOMES INVALID, IF ANY ALTERATION/REPAIR OR MODIFICATION IS MADE TO THE EQUIPMENT

THE CONCERNED INSPECTOR OR REPRESENTATIVE HAS THOROUGHLY EXAMINED THE EQUIPMENT IN ACCORDANCE TO THE RELEVANT STANDARDS. EXAMINATION INDICATES THAT THE SAID EQUIPMENT HAS NO APPARENT DEFECTS OR DEFORMATION WHICH MAY PROVE DANGEROUS DURING NORMAL OPERATION. THE SAID EQUIPMENT IS FOUND TO BE SATISFACTORY FOR FURTHER USE, PROVIDED THERE IS REGULAR MAINTENANCE AND OPERATED BY A CERTIFIED OPERATOR. THIS CERTIFICATE IS GRANTED SUBJECT TO THE CONDITION THAT IS AGREED &amp; UNDERSTOOD THAT STANDARD ARABIA INSPECTION CO. LTD.'S LIABILITY SHALL BE LIMITED TO THE ACTS OF ITS EMPLOYEES ON PREMISES OF SUBCONTRACTORS. UNDER NO CIRCUMSTANCES WHATSOEVER SHALL STANDARD ARABIA INSPECTION CO. LTD. BE LIABLE FOR ANY INJURY OR DAMAGE TO ANY PERSON OR OCCURRING AS A RESULT OF NEGLIGENCE OPERATION OR ANY DEFECT IN MATERIALS, MACHINERY, EQUIPMENT OR SYSTEMS OTHER THAN DEFECTS ASCERTAINABLE DURING ROUTINE INSPECTION. WE HEREBY REPORT THAT THE ALL PARTICULARS IN THIS REPORT ARE CORRECT AT THE TIME OF TEST / INSPECTION &amp; OPERATIONAL MAINTENANCE IS THE SOLE RESPONSIBILITY OF THE EQUIPMENT OWNER.

THIS CERTIFICATE IS GENERATED AND AUTHORIZED ELECTRONICALLY AND CAN BE CONSIDERED AS ORIGINAL. TO VERIFY THE AUTHENTICITY OF THIS CERTIFICATE, PLEASE SCAN THE QR CODE.

