




مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



## Certificate of Thorough Visual and Functional Examination of Backhoe Loader

Certificate No: JHI-198-SAAC-26-C3

Date of Inspection: 15-01-2026

Name of the owner company:  
SUDHIR EQUIPMENT RENTAL COMPANY

Location:  
RIYADH- KSA

Equipment Details: DIESEL ENGINE POWERED HYDRAULIC BACKHOE LOADER

Reference Regulations:

Maker & Date of Manufacture:

SASO ISO 20474-1, SASO-ISO-20474-5, BS EN 474-5:2022

JCB & 2025

| Sticker No. | Owner Id. | Traffic Plate No. | Model No.: | Serial No./Chassis No. |
|-------------|-----------|-------------------|------------|------------------------|
| 012784      | SBAL-014  | 2828 ZAA          | HD-100     | HH2353FV4              |

Description of Test: Visual and Functional Test Were Satisfactory.

Date of Last Examination

Date of Next Examination

N/A

14-01-2027

### RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory.

### IMAGES FOR BACKHOE LOADER



\*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: M.SHEIK ALLAVUDEEN

Surveyor's Name: M.MUHAMED AZARUDEEN

Authorized Signature:

Surveyor's Signature:

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh, Al Malaz Dist. Po. 12831  
CR No: 1010927177, Tel: 0112334900, Email: [info@jhinspection.com](mailto:info@jhinspection.com), [www.jhinspection.com](http://www.jhinspection.com)

# Annex to Certificate of Test and Thorough Examination

Certificate No.: JHI-198-SAAC-26-C3

Date of Inspection: 15-01-2026

| S/No | Description                                  | Condition / Remarks                                      |
|------|----------------------------------------------|----------------------------------------------------------|
| 1    | Equipment Documents                          | Satisfactory                                             |
| 2    | Control lever marking                        | Satisfactory                                             |
| 3    | Linkage                                      | Satisfactory                                             |
| 4    | Attachment Fixing Pins / Locks               | Satisfactory                                             |
| 5    | Hydraulic Cylinders                          | Satisfactory                                             |
| 6    | Stick and Boom Structure                     | Satisfactory                                             |
| 7    | Track Chains / Wheels                        | Satisfactory                                             |
| 8    | Sprockets / Idler Wheels / Track Links       | Satisfactory                                             |
| 9    | Turntable / Slewing assembly                 | Satisfactory                                             |
| 10   | Belt / Hoses                                 | Satisfactory                                             |
| 11   | Gauges in Cab                                | Satisfactory                                             |
| 12   | Doors                                        | Satisfactory                                             |
| 13   | Wind Shield                                  | Satisfactory                                             |
| 14   | Wipers                                       | Satisfactory                                             |
| 15   | Seat belt / Seat Bar                         | Satisfactory                                             |
| 16   | Motion Warning Alarm / Horn                  | Satisfactory                                             |
| 17   | Rotating Warning Light / Reverse Alarm       | Satisfactory                                             |
| 18   | Operation Controls                           | Satisfactory                                             |
| 19   | Electrical Cabling and Fittings              | Satisfactory                                             |
| 20   | Battery Condition / Connections              | Satisfactory                                             |
| 21   | Brakes                                       | Satisfactory                                             |
| 22   | Lights                                       | Satisfactory                                             |
| 23   | Fire Extinguisher                            | Satisfactory                                             |
| 24   | Housekeeping                                 | Satisfactory                                             |
| 25   | Manufacturer's manuals                       | Satisfactory                                             |
| 26   | Capacity Labels                              | Satisfactory                                             |
| 27   | Machine Guard                                | Satisfactory                                             |
| 28   | Hydraulic System                             | Satisfactory                                             |
| 29   | Engine / Engine Compartment                  | Satisfactory                                             |
| 30   | Spark Arrestor                               | Shall be fitted when operating in Highly explosive areas |
| 31   | Is that machine less than 15 years old?      | Satisfactory                                             |
| 32   | Painting/Corrosion / General Status - Visual | Satisfactory                                             |
| 33   | Maintenance Status record                    | Satisfactory                                             |
| 34   | Record of Major Alterations or Repair        | Nil                                                      |

## COMMENTS:

At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: M.MUHAMED AZARUDEEN



Surveyor's Signature: M. Mohamed Azarudeen