


☐ Interim  
☒ Final

## INSPECTION REPORT

### NO. R105220814.01

BV Job nr: KHO.INI.22.SA

PROJECT: Third Party Inspection for GENERATOR

Ref: KHO.INI.22.SA

BV Client: SUDHIR GENSETS

Manufacturer: POWER GENERATION

| SUPPLY / SUBJECT OF INSPECTION  | SN / TAG Nr             | QTY |
|---------------------------------|-------------------------|-----|
| Visual Inspection FOR GENERATOR | I15I210119<br>SG-028-60 | 1   |

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

| Title                              | Reference n° | Rev. | Approved by      |
|------------------------------------|--------------|------|------------------|
| ORIGINAL DECLARATION OF CONFORMITY | -            | -    | POWER GENERATION |

**INSPECTIONS :**Inspection place & Date or Period:**SUDHIR YARD 14 AUGUST 2022**Stage of inspection :

- ☐ Before manufacturing  
☐ During manufacturing  
☒ Final  
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting  
☐ Document and QC record review  
☒ Visual examination, checks  
☐ Witnessing tests  
☐ Manufacturing progress status  
☐ Vendor assessment  
☒ Final inspection  
☐ Packing

(for details see continuation sheet)

Stamping :☒ No☐Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection of 1 unit of GENERATOR was carried out and found satisfactory at the time of Inspection.

**Valid Sticker Number : 01-32387****Next visit scheduled: 13 AUG. 2023**


☐ Interim  
☒ Final

## INSPECTION REPORT

### NO. R105220814.01

#### Description of the inspections carried out:

#### 1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection of 1 unit Of GENERATOR.

#### 2. Attendees :

Mr. Hesham Elsaqa --- BV Inspector

#### 3. Scope of Inspection :

a. Visual & Functional Inspection of GENERATOR



#### 1- General Data

|                |           |
|----------------|-----------|
| Equipment Type | GENERATOR |
| Model          | C60D6(S)  |
| Engine Make    | CUMMINS   |
| YOM            | 2015      |
| Power          | 60        |

#### 2- Inspection and Test Results

| Acceptance criteria                                                                                      | Result | Remarks               |
|----------------------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Previous Report by universal inspection company)                                     | Pass   | Available             |
| 2. Visual inspection of Unit, wear, damage, loose connection/components, corrosion.                      | Pass   | Found good condition. |
| 3. Electrical, (conduct general inspection of wiring and connection cable termination, corrosion, damage | Pass   | Found good condition. |





☐ Interim  
☒ Final

**INSPECTION REPORT**  
**NO. R105220814.01**

➤ **Conclusion:**

The GENERATOR found in good condition at the time of Inspection.

**Inspected by:**

HESHAM ELSAQA  
IVS-Lifting Inspection

*Hesham Elsaqa*



**Checked by:**

*[Signature]*  
Team Leader

Date of issue: 17 AUGUST 2022

**Inspection centre:** BUREAU VERITAS ALKHOBAR