

BUREAU  
VERITAS

## INSPECTION REPORT

NO. R104200601.11

☐ Interim  
☒ Final

BV Job nr: KHO.IVS.17.0004.SA

|                                               |                                         |
|-----------------------------------------------|-----------------------------------------|
| PROJECT: Third Party Inspection for GENERATOR | Ref: KHO.IVS.17.0004.SA                 |
| BV Client: Sudhir Company                     | P/o nr: -<br>(client to BV)             |
| Manufacturer: CUMMINS                         | P/o nr: N/A<br>(client to Manufacturer) |

| SUPPLY / SUBJECT OF INSPECTION                      | SN / TAG Nr               | QTY |
|-----------------------------------------------------|---------------------------|-----|
| VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERATOR | 1609B1950 /<br>SG-094-125 | 1   |

| DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: <input type="checkbox"/> Yes <input type="checkbox"/> No |              |      |             |      |
|------------------------------------------------------------------------------------------------------------------------------------|--------------|------|-------------|------|
| Title                                                                                                                              | Reference n° | Rev. | Approved by | Date |
| QUALITY CERTIFICATE                                                                                                                | -            | -    | -           | -    |

## INSPECTIONS :

Inspection place & Date or Period:

DAMMAM on JUNE 01, 2020

Stage of inspection :

- ☐ Before manufacturing  
☐ During manufacturing  
☒ Final  
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting  
☐ Document and QC record review  
☒ Visual examination, checks  
☐ Witnessing tests  
☐ Manufacturing progress status  
☐ Vendor assessment  
☒ Final inspection  
☐ Packing

(for details see continuation sheet)

Stamping :
☒ No ☐  ☐ 
Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection of one unit of GENERATOR was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number: LFT-S-01-11954

Next visit scheduled: MAY 31, 2021

BUREAU  
VERITAS☐ Interim  
☒ Final**INSPECTION REPORT****NO. R104200601.11****BV Job nr: KHO.IVS.18.028****Description of the inspections carried out:****1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of Sudhir Company on the purpose of Third Party Inspection of one unit of GENERATOR with Model No.: CS125D5P with Serial Number: 1609B1950

**2. Attendees :**

Mohammed Al Homoud - Inspector

**3. Scope of Inspection :**

a. Visual Inspection & Functional Test of **GENERATOR**

**1- General Data**

|                |                  |
|----------------|------------------|
| Equipment Type | <b>GENERATOR</b> |
| Manufacturer   | <b>CUMMINS</b>   |
| Model          | CS125D5P         |
| Serial No.     | 1609B1950        |





BUREAU  
VERITAS
☐ Interim  
☒ Final

## INSPECTION REPORT

NO. R104200601.11

BV Job nr: KHO.IVS.18.028

## 3- Inspection and Test Results

| Acceptance criteria                                                                       | Result | Remarks               |
|-------------------------------------------------------------------------------------------|--------|-----------------------|
| 1. Document review (Original Declaration of Conformity)                                   | Pass   | Available             |
| 2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion. | Pass   | Found good condition. |
| 3. Check operating pressure gauges                                                        | Pass   | Found good condition. |
| 4. Check air filter                                                                       | Pass   | Found good condition. |
| 5. Electrical,(conduct general inspection of electric cord/plug.                          | Pass   | Found good condition. |
| 6. Check belt drive system totally enclosed (front,back,top & sides)                      | Pass   | Found good condition  |
| 7. Check air hoses connection and fittings                                                | Pass   | Found good condition. |

## ➤ Conclusion:

The GENERATOR found in good condition at the time of Inspection.

Inspected by:

Mohammed ALhomoud

IVS- Inspector



Checked by:

IVS- Team Leader

Date of issue: 01 JUNE ,2020

Inspection centre: BUREAU VERITAS ALKHOBAR