


☐ Interim
☒ Final

INSPECTION REPORT

NO. R104220801.10

BV Job nr: KHO.IVS.19.082.SA

PROJECT: Third Party Inspection for GENERAITOR

Ref: KHO.IVS.19.082.SA

BV Client: SUDHIR

P/o nr: N/A
(client to BV)

Manufacturer: CUMMINS

P/o nr: N/A
(client to Manufacturer)

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	Owner ID No.:	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF GENERAITOR	1609B1949	SG-095-125	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by	Date
ORIGINAL DECLARATION OF CONFORMITY	-	-	-	-

INSPECTIONS :

Results of inspection : ☒ Satisfactory ☐ UnsatisfactoryInspection place & Date or Period:

SUDHIR

01 AUG 2022

Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping:☒ NoNon Conformities Reports (NCR):

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)Third party visual inspection of 1 unit of **GENERAITOR** was carried out and found satisfactory at the time of Inspection.

Valid Sticker Number : 01-33607

Next visit scheduled: 31 JULY 2023




☐ Interim
☒ Final

INSPECTION REPORT

NO. R104220801.10

BV Job nr: KHO.IVS.19.082.SA

Description of the inspections carried out:

1. Introduction:

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting/B&F Department at the Request of SUDHIR on the purpose of Third Party Inspection .

2. Scope of Inspection :

a. Visual Inspection & Functional Test of GENERAITOR

1- General Data

Equipment Type	GENERAITOR
Manufacturer	CUMMINS
Model	CS125D5P
Serial No.	1609B1949

2- Inspection and Test Results

Acceptance criteria

	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit, wear, damage, loose connection /components, corrosion.	Pass	Found good condition.
3. Electrical,(conduct general inspection of wiring and connection cable termination, corrosion, damage	Pass	Found good condition.

➤ Conclusion:

The GENERAITOR found in good condition at the time of Inspection.

Inspected by:

MOHAMMED ALHOMOUD
EQUIPMENT INSPECTOR

Checked by:

OPERATION TEAM LEADER

Issued at Al Khobar office on 02 AUG 2022

Riyadh office
P.O. Box 18245 - Riyadh: 11415
Saudi Arabia
Phone: +966 11 230 3283
Fax: +966 11 230 3283

مكتب الرياض
ص ب ١٨٢٤٥ - الرياض : ١١٤١٥
المملكة العربية السعودية
تلفون: +٩٦٦ ١١ ٢٣٠ ٣٢٨٣
فاكس: +٩٦٦ ١١ ٢٣٠ ٣٢٨٣

Al Khobar
P.O.Box 20189
Khobar 31952 - KSA
Tel : +966 13 882 1071
: 1086 / 1089
Fax : +966 13 882 1072

Jeddah
P.O.Box 54091
Jeddah 21514 - KSA
Tel : +966 12 612 0357
: +966 12 605 6028
Fax : +966 12 654 6708

Jubail
P.O.Box 10608
Jubail 31951 - KSA
Tel : +966 13 361 7715
: +966 13 201 6977
Fax : +966 13 361 7715

Yanbu
Saudi Arabia
Tel : +966 14 396 3182
: +966 14 396 3183
Fax : +966 14 396 3184

الجبيل
ص ب ١٠٦٠٨ - الجبيل : ٣١٩٥١
المملكة العربية السعودية
تلفون: +٩٦٦ ١٣ ٣٦١ ٧٧١٥
فاكس: +٩٦٦ ١٣ ٢٠١ ٦٩٧٧

Yanbu
Saudi Arabia
Tel : +966 14 396 3182
: +966 14 396 3183
Fax : +966 14 396 3184

Website: www.bureauveritas.com موقع الانترنت

E-mail: BVKSA.collection@BureauVeritas.com بريد الكتروني