


☐ Interim
☒ Final

INSPECTION REPORT

NO. R108210818.01

BV Job nr: KHO.INI.19.206.SA

PROJECT: Third Party Inspection for Diesel Engine Generator Set	Ref: KHO.INI.19.206.SA
BV Client: SUDHIR RENTAL	P/o nr: N/A (client to BV)
Manufacturer: CUMMINS	

SUPPLY / SUBJECT OF INSPECTION	SN / TAG Nr	QTY
VISUAL EXAMINATION AND FUNCTIONAL TEST OF DIESEL ENGINE GENERATOR SET	1609B1953 / SG-098-125	1

DOCUMENTS OF REFERENCE : See continuation sheet for additional documents: ☐ Yes ☐ No

Title	Reference n°	Rev.	Approved by	Date
EQUIPMENT DATA SHEET	-	-	CUMMINS	2016

INSPECTIONS :**Inspection place & Date or Period:**

SUDHIR Workshop Dammam,
August 18, 2021

Stage of inspection :

- ☐ Before manufacturing
☐ During manufacturing
☒ Final
☐ Packing

Type of inspection:

- ☐ Pre-inspection meeting
☐ Document and QC record review
☒ Visual examination, checks
☐ Witnessing tests
☐ Manufacturing progress status
☐ Vendor assessment
☒ Final inspection
☐ Packing

(for details see continuation sheet)

Stamping :

☒ No ☐ ☐

Results of inspection : ☒ Satisfactory ☐ Unsatisfactory**Non Conformities Reports (NCR):**

o NCR's issued during reported period : N/A

o List of outstanding NCR's : N/A

Main Conclusions & Remarks: (for details see continuation sheet)

Third party visual inspection and functional test of one unit of Diesel Engine Generator Set was carried out with no defects and found satisfactory at the time of Inspection.

Valid Sticker Number : LTF-S-01-27603**Next visit scheduled: August 17, 2022**


☐ Interim
☒ Final

INSPECTION REPORT

NO. R108210818.01

BV Job nr: KHO.INI.19.206.SA

Description of the inspections carried out:**1. Introduction:**

The undersigned surveyor to Bureau Veritas acting within the scope of work along with the General condition which Regulate the intervention of the society IVS-Lifting Department at the Request of **Sudhir** on the purpose of Third Party Inspection of One Diesel Engine Generator Set with Model No.: **CS125D5P** with (GSN): **1609B1953**.

2. Attendees :

- Mr. Mathab

3. Scope of Inspection :

Thorough Visual Examination & Functional Test of Diesel Engine Generator Set.

1- General Data

Equipment Type	Diesel Engine Generator Set
Manufacturer	Cummins
Model	CS125D5P
GSN	1609B1953
Engine Sr. No.	P84327064
Alternator Sr. No.	N16G299995
Asset Number	SG-098-125
Base Rating KVA	125 kVA
Line to Line Voltage	380v
Line to Neutral	220v
Number of Phase	3 Ø
Prime Current @ (0.8Pf)	87 Amp
RPM	1800
Manufacturing Date	2016




☐ Interim
☒ Final

INSPECTION REPORT

NO. R108210818.01

BV Job nr: KHO.INI.19.206.SA

3- Inspection and Test Results

Acceptance criteria	Result	Remarks
1. Document review (Original Declaration of Conformity)	Pass	Available
2. Visual inspection of Unit-leaks, wear, damage, loose connection/components, corrosion.	Pass	Found good condition.
3. Check engine oil level (check for proper oil level)	Pass	Found good condition.
4. Check for Pressure Gauges, all fittings for any damage	Pass	Found good condition.
5. Check for emergency push button for functional test	Pass	Found good condition.
6. Check for oil spillage sensor and fuel monitor for function test	Pass	Found good condition.

➤ **Conclusion:**

The Diesel Engine Generator Set found in good running condition at the time of Inspection.

Inspected by:

Nilo Daray
Equipment Inspector



Checked by:

Team Leader

Date of issue: August 18, 2021

Inspection centre: BUREAU VERITAS ALKHOBAR