

INSPECTION CERTIFICATE

MANLIFT

CLIENT NAME : SUDHIR EQUIPMENT RENTAL CO		WORK ORDER : WR-YAS-428	
EQUIPMENT DESCRIPTION : MANLIFT WITH ARTICULATED BOOM WITH MAXIMUM WORKING HEIGHT OF 16.27 M		CERTIFICATE NO : YAS-CRT-1913	
DATE OF INSPECTION : 04-Oct-2026		STICKER NO : 13711	
PREVIOUS INSPECTION :		NEXT INSPECTION DUE : 03-Apr-2027	
MANUFACTURER : DINGLI		PREVIOUS INSPECTION DETAILS :	
SERIAL NO : BARC025D00127		MODEL/TYPE : BA16CRT2	
CHECKLIST NO. : 1580		OWNER ID : S16AD-2452	
TYPE OF INSPECTION : PERIODIC AND FUNCTIONAL INSPECTION		MANUFACTURED YEAR : 2025	
REFERENCE STANDARDS : BS EN 280-1:2022		LOCATION : RIYADH	
CAPACITY / SWL:	320 KG		
NO OF PERSONS:	2 PERSONS		
TEST LOAD:	N/A		
MAX HORIZONTAL REACH:	8.69 M		
PLATFORM HEIGHT:	14.27 M		
OUTRIGGER:	N/A		
Is this the first examination after installation or assembly at a new site or location ?	☐ Yes ☒ No	Within an interval of Months?	☒ 6 ☐ 12
If the answer to the above question is YES has the equipment been installed correctly ?	☐ Yes ☒ No	In accordance with an examination scheme ?	☐ Yes ☒ No
After the occurrence of exceptional circumstances ?		☐ Yes ☒ No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)		NONE	
Is the above a defect which is of immediate danger to persons		☐ Yes ☒ No	
Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)		NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE)		NONE	
RESULT:	☒ PASS ☐ FAIL	IS THIS EQUIPMENT FIT FOR PURPOSE?	☒ Yes ☐ No
REMARKS/RECOMMENDATION THIS IS TO CERTIFY THAT THE MANLIFT HAS BEEN PERIODICALLY AND FUNCTIONALLY INSPECTED IN ACCORDANCE WITH INTERNATIONALLY RECOGNIZED STANDARDS ON THE INSPECTION DATE. THE EQUIPMENT IS FREE FROM EXTERNAL DAMAGE, AND THE EQUIPMENT IS FOUND TO BE IN SATISFACTORY CONDITION.			
Date Of Report: 4/10/2026			

Approved By : ABDUL HALEEM

Authorized Inspector : AHAMED

WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913



WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913
WORKORDER NO: WR-YAS-428
CERTIFICATE NO: YAS-CRT-1913

Note : This certificate becomes void if the equipment is altered, repaired, or modified without authorization. The equipment owner is solely responsible for safe operation and maintenance. The company accepts no liability for damages or failures arising from negligence, poor maintenance, or conditions not detectable during routine inspection.