



REPORT OF A THOROUGH EXAMINATION

Issue Date: 17-May-2026

Certificate Number: ECI/SA/C-01720/26 Rev. No: 00	Report Number: 132624	Sticker Number: 109750
Date of Thorough Examination: 14-May-2026	Date of Expiration: 13-Nov-2026	S.O.#: 110 Ref.#: N/A

Client: MARAKEB ELJANOUB TRADING COMPANY	Address of Premises at Which the Examination Was Made: REMAH
--	--

Description and Identification of the Equipment:	Load Test Detail	Safe Working Load(s)	Applied Load(s)
Equipment / Type : DUMP TRUCK / DUMPER Location of the Equipment : REMAH Equipment ID No : 7731 VXA Equipment Serial No : LZZ1CCVD2TJ420978 Model : -- Manufacturer / Date of Manufacture : CNHTC / 2026 Applied Standard : SASO-ISO-20474-6 - 2017 & BS EN 474-6 - 2022	N/A	24 m³	N/A

Examination after installation / In-Services		Was the Examination carried out Within an interval of					
☐ Initial ☒ Periodic Inspection ☐ Re-Inspection after Major Repair / Modification Or Overhaul		☐ 3 Months ☒ 6 Months ☐ 12 Months ☐ After the exceptional circumstances					
Additional Information about the equipment and Information / Description of the Parts / attachments with the equipment.							
Description of the Load Test : N/A							
Pre Load Test NDT done by : N/A		% of Load Applied : N/A		Post Load Test NDT done by : N/A			
Result				PASS	☒	FAIL	
Is the above a defect which is of immediate danger to persons?				YES		NO	☒
Is the above a defect which is not yet but could become a danger to persons?				YES by :		NO	☒
Particulars of any repair, renewal or alteration required to remedy the defect identified above: N/A							
Is this equipment safe to operate?				YES	☒	NO	

Note: We thus attest that the aforementioned equipment has undergone a thorough Visual Inspection and /or Functional Test conducted by a qualified inspector in accordance with Engineering Corner for Inspection (E.C.I.) procedure / local / international standards.

Liability: The client or this assignee or supervisor in interest agrees to identify and hold harmless **Engineering corner for inspection Co.Ltd.** from and against any all claims, demands, lawsuits or actions for damages including legal fees to persons and/or property tangible, intangible or otherwise which may be against, **Engineering corner for inspection Co.Ltd.** incidental to, arising out of or in connection with the work to be done, services to be performed or material to be furnished hereunder except for those claims caused solely and completely by the negligence of **Engineering corner for inspection Co.Ltd.** its directors, others, employees or sub-contractors.

Inspected by: RAKAN AL YAMI	Approved & Reviewed By: ALVARO	QR Code:
Signature:		



Engineering Corner for Inspection Company Limited

INSPECTION CHECKLIST

Dumpers

Doc. No.	ECIR - LFT - 83
Rev. No.	03
Rev. Date	17-FEB-2026
Page No.	2 of 5

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	MARAKEB ELJANOUB TRADING COMPANY /	Report No. & Date	132624 14-May-2026
Manufacturer / Year	CNHTC / 2026	Location	REMAH
Type / Model	DUMP TRUCK / DUMPER / --	Equipment ID. No.	7731 VXA
Inspection Date	14-May-2026	Equipment Sr. No.	LZZ1CCVD2TJ420978
Inspector Name	RAKAN AL YAMI	Capacity / SWL	24 m ³
Standard	BE EN 474-1-2022, BS EN 474-6-2022, SASO ISO 20474-1-2017 & SASO ISO 20474-6-2017	Expiration Date	13-Nov-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
GENERAL REQUIREMENTS & DOCUMENTATION					5.5	Cylinder rods show no significant scoring, pitting, or leakage	☒		
1.1	Operator's manual and machine documentation available in appropriate language	☒			5.6	Hydraulic oil cooler is clean and undamaged	☒		
1.2	Previous inspection reports are checked and reviewed	☒			5.7	Check valves / holding valves for tipping cylinder are functional	☒		
1.3	Machine identification plate legible and secure (serial no., weight, year)	☒			5.8	Quick-release couplings (if equipped) show no leaks			☒
1.4	Operator is trained and authorized for dumper operation	☒			5.9	Hydraulic filter condition indicator (if equipped) is within limits			☒
1.5	Fire extinguisher is in place, accessible, and properly charged	☒			DUMP BODY & CHASSIS				
1.6	Safety signs and decals are present, legible and not damaged	☒			6.1	Dump body structure shows no cracks, bends, or unauthorized welds	☒		
1.7	Rated capacity/payload chart is displayed and legible	☒			6.2	Body hinge pins and bushings are secure and show no excessive wear	☒		
1.8	Machine weight and maximum speed information is displayed	☒			6.3	Body floor and sides are in serviceable condition (not perforated)	☒		
OPERATOR'S STATION (ROPS/FOPS CAB)					6.4	Tailgate latch mechanism is functional and secure	☒		
2.1	ROPS/FOPS structure certification plate present and structure intact			☒	6.5	Body tipping stops are present and functional	☒		
2.2	Seat belt with warning device is fitted and in good condition	☒			6.6	Body locking device engages securely in transport position	☒		
2.3	All control levers and pedals are clearly marked and function smoothly	☒			6.7	Load ejector system (if equipped) operates smoothly	☒		
2.4	Travel direction and gear selection controls function correctly	☒			6.8	Chassis and main frame show no cracks or damage	☒		
2.5	Body tipping control lever functions correctly and is clearly marked	☒			6.9	Body wear plates and liners (if equipped) are serviceable			☒
2.6	Audible warning device (horn) is operational	☒			TYRES / UNDERCARRIAGE & SUSPENSION				
2.7	All gauges and warning indicators are functional	☒			7.1	All tires are serviceable, with correct pressure and no excessive wear/damage	☒		
2.8	Windows and mirrors are clean, secure and not damaged	☒			7.2	Wheel nuts are present, engaged properly, and torqued	☒		
2.9	Wipers and washers are operational for adequate visibility	☒			7.3	Rims are not damaged, cracked or rusted through	☒		
2.10	Entry/exit steps and handholds are secure and skid-resistant	☒			7.4	Tire inflation system (if equipped) is functional and shows no leaks			☒
2.11	Operator's seat adjustments are functional and seat is secured	☒			7.5	Suspension system (if equipped) shows no leaks or damage			☒
2.12	Load indicator system is functional (if equipped)			☒	7.6	Axle mounting bolts are secure	☒		
SAFETY DEVICES & CONTROLS					7.7	Drive shaft bolts and universal joints are secure and not worn	☒		
3.1	Engine emergency stop device is functional and clearly identified	☒			7.8	Hub oil seals show no leaks	☒		
3.2	Backup alarm is operational and audible	☒			7.9	Underside of chassis shows no obvious faults, leaks, or damage	☒		
3.3	Control levers return to neutral when released	☒			LIGHTING & ELECTRICAL SYSTEM				
3.4	Seat-activated start/operation interlock is functional (if equipped)	☒			8.1	Headlights, taillights, and work lights are operational	☒		
3.5	Body support device (for maintenance) is present and functional	☒			8.2	Turning signals and indicators are working correctly	☒		
3.6	Body lock/latch mechanism is functional and secure	☒			8.3	Brake lights are operational	☒		
3.7	Travel speed automatically limited when body is raised (if equipped)			☒	8.4	Beacon/warning light is operational	☒		
3.8	Tip-over warning device is functional (if equipped)			☒	8.5	Reverse lights are operational (if equipped)	☒		
POWERTRAIN, BRAKES & STEERING					8.6	Body raised warning light is operational	☒		
4.1	Engine shows no major leaks (oil, fuel, coolant)	☒			8.7	Battery is secure, terminals are clean, and cover is in place	☒		

	Engineering Corner for Inspection Company Limited INSPECTION CHECKLIST Dumpers	Doc. No.	ECIR - LFT - 83
		Rev. No.	03
		Rev. Date	17-FEB-2026
		Page No.	3 of 5

Issue Number : 02 & Issue Date : 03-FEB-2020

Equipment Owner	MARAKEB ELJANOUB TRADING COMPANY /	Report No. & Date	132624 14-May-2026
Manufacturer / Year	CNHTC / 2026	Location	REMAH
Type / Model	DUMP TRUCK / DUMPER / --	Equipment ID. No.	7731 VXA
Inspection Date	14-May-2026	Equipment Sr. No.	LZZ1CCVD2TJ420978
Inspector Name	RAKAN AL YAMI	Capacity / SWL	24 m ³
Standard	BE EN 474-1-2022, BS EN 474-6-2022, SASO ISO 20474-1-2017 & SASO ISO 20474-6-2017	Expiration Date	13-Nov-2026

Item No	ITEM NAME	PASS	FAIL	N/A	Item No	ITEM NAME	PASS	FAIL	N/A
4.2	Service brakes are operational and effective	☒			8.8	Wiring is secure with no exposed or damaged insulation	☒		
4.3	Parking brake holds the machine securely on maximum incline	☒			8.9	Fuses and circuit breakers are properly rated and functional	☒		
4.4	Secondary emergency brake system is functional (if equipped)	☒			OPERATIONAL CHECKS (With Engine Running)				
4.5	Steering system is responsive with no excessive play or leaks	☒			9.1	No unusual engine, transmission, or hydraulic noises during operation	☒		
4.6	Transmission shows no unusual noises, slipping or overheating	☒			9.2	Body raise/lower functions operate smoothly and hold position	☒		
4.7	Drive axles and final drives show no leaks or damage	☒			9.3	Body locking mechanism engages/disengages properly	☒		
4.8	Engine and transmission mounting bolts are secure	☒			9.4	Machine travels forward and reverse in all ranges without issue	☒		
4.9	Radiator and cooling system show no leaks or damage	☒			9.5	Steering functions correctly in both directions under load	☒		
4.10	Articulation joint and pins show no excessive wear or play (articulated dumpers)			☒	9.6	No excessive drift or creep in raised body	☒		
HYDRAULIC SYSTEM					9.7	Braking performance is adequate in both service and parking brakes	☒		
5.1	Hydraulic tanks, hoses, and lines show no leaks or damage	☒			9.8	Hydraulic system maintains pressure without excessive cycling	☒		
5.2	Hydraulic hose fittings and supports are secure	☒			9.9	Travel speed limitation when body raised functions (if equipped)			☒
5.3	Hydraulic reservoir fluid level is correct and fluid is clean	☒			9.10	Load ejector system operates correctly (if equipped)	☒		
5.4	Tipping cylinder anchor points and pins are secure and not worn	☒			9.11	All warning devices and indicators function as designed			☒

Overall Comments

Inspected By : RAKAN AL YAMI	Customer Representative : MUHAMMAD AKMAL
-------------------------------------	---



شركة ركن الهندسة للفحص والمعاينة المحدودة

ENGINEERING CORNER FOR INSPECTION CO. LTD.

Certificate Number: ECI/SA/C-01720/26





ECI. 109750

Capacity : 24 m³

Equipment No. : 7731 VXA

Serial No. : LZZ1CCVD2TJ420978

Inspected Date : 14-May-2026

Next Inspection : 13-Nov-2026

Inspector : RAKAN AL YAMI

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.: (013) 667-6999 / 667-6895 Fax #:(013) 667-6894

E-mail Address: eci@eccgroupksa.com