

CERTIFICATE NO. : XCMG25SAC00111

DATE . : 2025.01.01

LOADING TEST CERTIFICATE OF XCMG MOBILE CRANE XCR90

This is to certify that the following XCMG crane XCR90 has been duly inspected.

Model: XCR90

VIN NO.: XUG0900RCSAC00111

Item	Working condition 工况	Boom length 臂长	Working radius 工作幅度	Outrigger condition 支腿情况	Remark 备注	Lifting weight 起重量
1	Base boom 基本臂	12.4m	7m	Full-extend 全伸	Boom is over side or rear 起重臂在侧后方	41.4t
2	Full-extended boom 主臂全伸	48m	10m	Full-extend 全伸	Boom is over side or rear 起重臂在侧后方	11.4t

NOTE: Crane operator is fully responsible for the safe operation of the crane and shall ensure that all warnings and instructions supplied are fully understood and observed. XCMG reserves the right of final explanation.

徐州重型机械有限公司

Xuzhou Heavy Machinery Co., Ltd.



徐州重型机械有限公司
Xuzhou Heavy Machinery Co., Ltd.

地址：中国江苏省徐州经济技术开发区高新路 68 号，221004。
Add: No.68, GaoXin Road, Xuzhou Economic Technology Development Zone, Jiangsu China, 221004.

CERTIFICATE NO. : XCMG25SAC00112
DATE . : 2025.01.01

LOADING TEST CERTIFICATE OF XCMG MOBILE CRANE XCR90

This is to certify that the following XCMG crane XCR90 has been duly inspected.
Model: XCR90
VIN NO.: XUG0900RVSAC00112

Item	Working condition 工况	Boom length 臂长	Working radius 工作幅度	Outrigger condition 支腿情况	Remark 备注	Lifting weight 起重量
1	Base boom 基本臂	12.4m	7m	Full-extend 全伸	Boom is over side or rear 起重臂在侧后方	41.4t
2	Full-extended boom 主臂全伸	48m	10m	Full-extend 全伸	Boom is over side or rear 起重臂在侧后方	11.4t

NOTE: Crane operator is fully responsible for the safe operation of the crane and shall ensure that all warnings and instructions supplied are fully understood and observed. XCMG reserves the right of final explanation.


徐州重型机械有限公司
Xuzhou Heavy Machinery Co., Ltd.

