

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	Crane
Brand / Make	SANY
Asset ID	SRC-RT-080-050
Model Number	SRC800T
Serial Number	RC0080CF0560
Capacity	80 TON
Type	ROUGH TERRAIN CRANE
Manufacturing Year	2025

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Rajesh Thakur
Plant Manager
Sudhir Equipment Rental Company



KINGDOM OF SAUDI ARABIA
MINISTRY OF INTERIOR

رخصة سير
VEHICLES REGISTRATION

المملكة العربية السعودية
وزارة الداخلية

المالك شركة سودهير لتأجير المعدات شركة الشخص الواحد

المستخدم

هوية المالك ٧٠١٦١٥٨٣٣٤

رقم الهيكل LFCNR54D1S3000338

رقم اللوحة ٢٥٢٥ م أ أ

نوع التسجيل اشغال عامة 2525 Z A A

طراز المركبة كرين

حمولة المركبة ٢

سنة الصنع ٢٠٢٥

ساركة المركبة سماني

وزن المركبة ٥٢٠٠٠

اللون / ابيض

الرقم التسلسلي ٩٤٢٤٢٩١٢٠





بروج للتأمين التعاوني
Buruj Cooperative Insurance

شهادة التأمين - CERTIFICATE OF INSURANCE

Policy Holder Name	:	Sudhir Equipment Rental Company	:	اسم حامل الوثيقة
Policy Number	:	01/CPM/ 2025/000002	:	رقم الوثيقة
Policy Period	:	05/04/ 2025 to 04/04/2026	:	فترة الوثيقة
Description of Machinery / Equipment	:	SANY-Crane-SRC800T	:	وصف المعدة/ال لة
Chassis / Serial No.	:	RC0080CF0560	:	رقم الهيكل/ التسلسلي
Year of Manufacturing	:	2025	:	سنة الصنع
Asset ID No.	:	SRC-RT-080-050	:	رقم ال صل
Location	:	Kingdom of Saudi Arabia.	:	الموقع

BURUJ Cooperative Insurance Company certifies that above client is holding a Machinery/Equipment Insurance Policy for the above-mentioned Equipment in accordance with the above-mentioned Insurance Policy.

With effect from: 02/06/2025 to 04/04/2026

This Certificate has been issued upon Insured's request as per all terms and conditions, exclusions, warranties mentioned in the policy.

تشهد شركة بروج للتأمين التعاوني بأن السادة أعل ه مؤمنين لديها تأمين المكنن/المعدات المذكورة أعل ه وذلك حسب وثيقة التأمين المذكورة أعل ه

والتي يبدأ تاريخ سريانها من ٢٠٢٥/٠٦/٠٢ إلى ٢٠٢٦/٠٤/٠٤

تم إصدار هذه الشهادة بناءً على طلب المؤمن له وذلك حسب الشروط وال استثناءات وال شتراطات المذكورة في الوثيقة.

Important Notices:

1. This Certificate does not pay any fines, penalties, bonds or cautions that may be imposed.
2. Original certificates are only accepted.
3. Due to the importance of correct information being stated in this certificate, kindly examine the document carefully and advise the Company of any difference.
4. In the event of changes in the above information, kindly contact +966-11-2938383

مل حظات هامة:

- ١) ل تطبق هذه الشهادة التأمين على الغرامات والعقوبات المالية بما في ذلك المخالفات أو الضمانات أو الكفالت التي قد تقرر.
- ٢) تقبل الشهادة ال صلية فقط.
- ٣) نظراً ل همية صحة البيانات الخاصة بكم في هذه الشهادة، الرجاء التأكد منها وإشعار الشركة في حالة وجود أي اختل فات.
- ٤) عند الحاجة إلى تعديل البيانات أعل ه يرجى ال اتصال على شركة بروج للتأمين التعاوني ٢٩٣٨٣٨٣-١١-٩٦٦



BURUJ Cooperative Insurance Company

P.O. Box 51855, Riyadh 11553,
National Address 3385, Al Thomamah Road, An-Nada District.
800 124 0201 | burujinsurance.com

Issue Date: 2 June 2025

800T

蓝白黑

VIN/发动机号确认表格

VIN/Engine Number Verification Form

车辆编码 Vehicle identification	RC0080CF0560	空调 air conditioner	电装
发动机型号 engine model	QSB6.7-C260-31	发动机号 engine identification	93398362
轮胎型号 tire model	29.5-25	排放标准 emission standards	国三



★LFCNR54D1S30000338★



★LFCNR54D1S30000338★

发动机号拓

印

Engine Number
Rubbing

刘亮

2.3

提交人/日

期

Submitted
by/Date

1. Certification No 合格证编号	WDE02025201033			2. Date of Issue 发证日期	2025-02-20	
3. Manufacture 车辆制造企业名称	SANY AUTOMOBILE MANUFACTURING CO., LTD 三一汽车制造有限公司					
4. Make / Category 车辆品牌/车辆名称	Sany 三一牌			Rough Terrain Crane 越野轮胎起重机		
5. Crane Model 车辆型号	SRC800T			6. Vehicle Identification No. 车辆识别代号	LFCNR54D1S3000338	
7. Chassis Type 底盘型号	SRC800T			8. Vehicle Color 车身颜色	BLUE/WHITE/BLACK	
9. Engine Model 发动机型号	QSB6.7			10. Engine No. 发动机号	93398362	
11. Applicable Fuel 燃料种类	DIESEL 柴油			12. Displacement / Rate Power排量 and 功率 (ml/kW)	6690	194
13. Emission Standard 排放标准	EU STAGE III					
14. Crane Overall-dimension (mm)	14600	3340	3930	15. Plates of Leaf Spring 钢板弹簧片数	/	
16. Tires Specifications 轮胎规格	29.5-25			17. Qty of Tires 轮胎数	4	
18. Tires Span (mm) 轮距 (前/后) (mm)	2520	2520		19. Wheelbase (mm) 轴距 (mm)	4265	
20. Axle Load 轴荷 (kg)	27530/24535					
21. Qty of Axles 轴数	2			22. Steering Application 转向形式	STEERING WHEEL 方向盘	
23. Overall Weight (kg) 总质量	52,065			24. Equipment Quality 整备质量 (kg)	52,000	
25. Driver-cabin Passengers Allowed 驾驶室准乘人数	1			26. QR Code 条码		
27. Nominal Max Speed (km/h) 最高设计车速	36			28. Fabrication Date 车辆制造日期	2025-01-31	
Remarks	Upon all due inspection the above-specified crane conforms to the standards of Q/OKTW 052-2025 <Rough Terrain Crane>. Certification is hereby issued for ready delivery. 本产品经过检验,符合Q/OKTW 052-2025《越野轮胎起重机》的要求,准予出厂,特此证明 Manufacture Name: Sany Automobile Manufacturing Co., Ltd. 车辆生产单位名称: 三一汽车制造有限公司 Manufacture Address: Sany Crane Industrial Park, No.168, Jinzhou Avenue, Changsha City, Hunan Province, People's Republic of China. 车辆生产单位地址: 长沙市宁乡市金洲大道西168号 Internal Vehicle Identification Code内部编号: RC0080CF0560					





SANY

Certificate No. (证书编号) : RC0560-1
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0560
Part No. (物料编码) : 12838070

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN1677-2:2000+A1:2008.

Name of Product : 80 t hook
Hook Serial No : TQ25018005015
Safety Working Load : 80 metric tons
Test Load : 100 metric tons
Hook Ass'y Weight : 800 kg
Hook Material : 35CrMo

Certified by:



2025-02-20

Date of inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0560-2
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0560
Part No. (物料编码) : 132702010194A

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected
and passed in accordance with EN1677-2:2000+A1:2008.

Name of Product : 8 t hook
Hook Serial No : ZX25010042
Safety Working Load : 8 metric tons
Test Load : 10 metric tons
Hook Ass'y Weight : 180 kg
Hook Material : 35CrMo

Certified by: _____



2025-02-20

Date of inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0560-1
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0560
To Messers (主机公司) : Sany Automobile Hoisting Machinery Co., Ltd.
Manufacturer (生产厂商) : Juli Sling Co., Ltd.

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN 12385-4. (兹证明下列产品依据 EN 12385-4 标准检验合格)。

Construction (结构) : 35W×K7
Lay (绞丝方式) : Right hand, Lang lay (右旋, 同向捻)
Grade of Strength (强度级别) : 2160N/mm²
Length (长度) : 250m
Total Mass of the Rope (总重) : 469.6kg

Diameter (直径)	Nominal (设计值) : 20mm Actual (实测值) : 20.7mm
Breaking Load (断裂载荷)	Nominal (设计值) : 368kN Actual (实测值) : 386kN

Certified by:

2025-02-20

Date of Inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0560-2
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0560
To Messers (主机公司) : Sany Automobile Hoisting Machinery Co., Ltd.
Manufacturer (生产厂商) : Juli Sling Co., Ltd.

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN 12385-4. (兹证明下列产品依据 EN 12385-4 标准检验合格)。

Construction (结构) : 35W×K7
Lay (绞丝方式) : Right hand, Lang lay (右旋, 同向捻)
Grade of Strength (强度级别) : 2160N/mm²
Length (长度) : 145m
Total Mass of the Rope (总重) : 272.4kg

Diameter (直径)	Nominal (设计值) : 20mm Actual (实测值) : 20.7mm
Breaking Load (断裂载荷)	Nominal (设计值) : 368kN Actual (实测值) : 386kN

Certified by:

2025-02-20

Date of Inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.

吊载测试证明
Certificate of Load Test证书编号
Certificate NO.

3G01202502200007

设备编号
Crane Serial No.

RC0080CF0560

制造单位名称 Manufacture Name		三一汽车制造有限公司 Sany Automobile Manufacturing Co., LTD							
序号 No	工作条件 Working Condition	臂长(米) Boom Length (unit: m)	吊载重量 (吨) Load Weight (unit: t)	幅度半径(米) Amplitude Radius (unit: m)	倍率 Ratio of Line	支腿 Outrigger	配重 counterweigh t	吊载测试 Load test	备注 Remark
1	基本臂 Base Boom	12.2	33.5	8	6	全伸支腿 Full- Extended	全配重 Full Counterweigh t	合格 Qualified	大臂位于侧面 和后方 Boom is over side and rear
2	中间臂 Mid-extended boom	27.6	29.5	5.5	6			合格 Qualified	
3	全伸臂 Full-extended boom	47	11.5	11	4			合格 Qualified	
4	主臂+副臂 Main boom + jib	47+17.5	2.9	主臂 78°, 副臂 0°, Main boom angle 78° and jib offset 0°	1			合格 Qualified	
5	吊载行驶 (≤4 km/h) Travel with Load	12.2	9.5	6.0	4	不伸支腿 Not- Extending	全配重 Full Counterweigh t	合格 Qualified	吊臂在正面 Boom is over front

根据公司内部吊载试验结果, 该产品具备相关起重性能, 吊载精度符合 GB/T 12602, EN 13000, SAEJ159 相关标准。

According to the results of the company's internal loading test, the product has the relevant loading performance, and the loading accuracy meets the relevant standards of GB/T 12602, EN 13000, SAEJ159.

特此颁发证书。

Certification is hereby issued.

Certified by: Zhang Qi Mu

Date: 2025-02-20





CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 2037471	Date of Examination: 12/09/2025	Sticker No.: BV-1310 LOAD TEST
---------------------------	--	---------------------------------------

Name & address of owner of the equipment		Sudhir Equipment Rental Company			
Inspection requested by		Sudhir Equipment Rental Company			
Place of inspection		DMM Yard.			
Type of inspection		LOAD TEST & THOROUGH EXAMINATION			
Relevant regulation / Standard		ASME B30.5			
Date of previous inspection / load test					
Identification & Description of the Equipment	Manufacturer name	SANY			
	Equipment Type	RT Mobile Crane			
	Nature of power	DEISEL POWERED			
	Model / Year	SRC800T/ 2025			
	Serial number	RC0080CF0560			
	Owner ID / Registration number	SRC-RT-080-050			
	Rated Capacity (maximum)	80 Ton			
	Present Configuration	Main hoist current capacity: 80 Ton with 6 FALLS			
		Auxiliary hoist current capacity: 8 Ton with 1 Falls			
	Radius (Mini / Max)	Minimum: 3 Mtr; Maximum: 34 Mtr			
	Length of Boom	Minimum: 12.2 Mtr; Maximum: 47.5 Mtr			
	Counterweight (mass)	Standard from Manufacturer			
	Wire rope specification	20 mm			
	Complementary devices	Fly Jib Was Stowed			

Description of test: Visual & Function Test inspection was carried out, followed by full functional testing. 100 % Of SWL Load Test Was Carried Out	Length of boom (m)	Radius (m)	Reeving (No. of falls)	Test Load	Safe Working Load
	27.6 M	20 M	6 Falls	4800 Kg	4800 Kg
	-	-	-	-	-
	-	-	-	-	-

Result of Examination:

The above mentioned equipment has been found satisfactory at the time of inspection and is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

This is to certify that the Competent Person did attend at the said premises on said date to witness proof load test and/or to carry out thorough examination of the equipment described herein and that all particulars described above were correct at the time of examination. This Certificate becomes void in case of any major repair, modification and /or alteration being un-authorized by issuer of hereof.

Next Proof Load Test Due: 11/09/2030 or After Major Repair/Modifications	Next Inspection Due is on or before: 11/12/2025
---	--

Issued at Al Khobar on 14/09/2025

Inspector to Bureau Veritas
Signature:



Name: MOHAMED OMARA
Position: Senior Inspector



Reviewed by
Signature:



Name: Ahmed Elabady
Position: Reviewer

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This not is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



CHECKLIST OF TEST & THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 2037471	Date of Examination: 12/09/2025
---------------------------	--

SECTION	CONDITION	REMARKS
1. ACCESS		
1.1 Access to the cabin/control station	Satisfactory	
1.2 Access for maintenance operation	Satisfactory	
2. CHASSIS		
2.1 Chassis	Satisfactory	
2.2 Traveling device (tire, crawler)	Satisfactory	
2.3 Outriggers	Satisfactory	
2.4 Outrigger sole (shoe or pad)	Satisfactory	
2.5 None return valve on outrigger	Satisfactory	
2.6 Locking of suspensions	Satisfactory	
2.7 Locking of outriggers rest position	Satisfactory	
3. STRUCTURE OF EQUIPMENT		
3.1 Structure, A frame	Satisfactory	
3.2 Jib, fly jib	Satisfactory	
3.3 Pendants	Satisfactory	
3.4 Counter weight	Satisfactory	
4. MECHANISM		
4.1 Main Hoisting mechanism	Satisfactory	
4.2 Aux. Hoisting mechanism	Satisfactory	
4.3 Hydraulic system	Satisfactory	
4.4 Cylinders	Satisfactory	
4.5 Hoisting brake system	Satisfactory	
4.6 Limitation of the lowering speed	Satisfactory	
4.7 Telescoping mechanism	Satisfactory	
4.8 Luffing mechanism	Not applicable	
4.9 Pivoting joints	Satisfactory	
4.10 Brake of slewing motion	Satisfactory	



4.11 Traveling Brake	Satisfactory	
4.12 Guards for moving parts	Satisfactory	
4.13 Motor	Satisfactory	
4.14 Gear box	Satisfactory	
5. LIFTING SYSTEM		
5.1 Wire rope / chain	Satisfactory	
5.2 Wire/chain rope end termination	Satisfactory	
5.3 Drum, pulley, return pulley	Satisfactory	
5.4 Hooks & hook blocks	Satisfactory	
5.5 Other load handling devices	Satisfactory	
6. ENERGY		
6.1 Main switch locking	Satisfactory	
6.2 Equipment and cabling	Satisfactory	
6.3 Protection of live parts/enclosure	Satisfactory	
6.4 Lighting of the crane/site	Satisfactory	
7. CABIN / CONTROL STATION		
7.1 Structure	Satisfactory	
7.2 Visibility / windows	Satisfactory	
7.3 Heating / AC system	Satisfactory	
7.4 Seat	Satisfactory	
7.5 Fire extinguisher	Satisfactory	
7.6 Identification of the controls	Satisfactory	
7.7 Control dead man type	Satisfactory	
7.8 General stopping device by key	Satisfactory	
7.9 Emergency stop button	Satisfactory	
7.10 Level indicator	Satisfactory	
7.11 Angle Indicator	Satisfactory	
7.12 Horn	Satisfactory	
7.13 Traffic lights	Satisfactory	
7.14 Direction Indicators	Satisfactory	
8. SAFETY DEVICES		



BUREAU
VERITAS



8.1 Hoisting limiter/Anti Two Blocks	Satisfactory	
8.2 Luffing limiter	Not applicable	
8.3 Telescopic limiter	Satisfactory	
8.4 Slewing limiter	Satisfactory	
8.5 Load limiter	Satisfactory	
8.6 Level limiter	Satisfactory	
8.7 Rated capacity indicator (RCI) / ASLI	Satisfactory	
8.8 None return valve on piston	Satisfactory	
8.9 Other limiter or indicator	Satisfactory	
9. MISCELLANEOUS REQUIREMENTS		
9.1 Maker plate	Satisfactory	
9.2 Load chart	Satisfactory	
9.3 Wire rope certificate	Satisfactory	
9.4 General Safety Requirements	Satisfactory	
Notes :		
Next Proof Load Test Due: 11/09/2030 or After Major Repair/Modifications		Next Inspection Due is on or before: 11/12/2025

Inspector to Bureau Veritas
Signature:



Name: MOHAMED OMARA
Position: Senior Inspector

1767786021815

2026-01-07

7016158334

شركة سودهير لتأجير

الرقم المرجعي :

تاريخ إصدار القائمة :

رقم العميل:

اسم العميل:

عدد المركبات في التقرير 1													
تقرير المركبات													
رقم اللوحة	نوع التسجيل	نوع الهيكل	وضع المركبة	الماركة	الطراز	سنة الصنع	الرقم التسلسلي	رقم الهيكل	اللون الأساسي	تاريخ الملكية	تاريخ انتهاء رخصة السير	حالة التأمين	هوية المستخدم الفعلي
أ أ م 2525	معدات ثقيلة		صالحة	ساني	كرين	2025	942429120	LFCNR54D1S3000338	ازرق	1446-11-17	1449-11-17	ساري المفعول	اسم المستخدم الفعلي

**ENGINEERING CORNER for INSPECTION**

P.O.Box 235, Rastanura 31941 Kingdom of Saudi Arabia

Tel. No's : (013)667 6999/6676895 Fax#:(013)667 6894

Email: Address: eci@eccgroupksa.com / info@eccgroupksa.com / Website : www.eccgroupksa.com



LIFTING EQUIPMENT INSPECTION REPORT	Area: RIYAZ NGL SITE , JUBAIL		CRM No. N/A	RPO No: N/A	No: 031445	
			Inspection Date: 16-Feb-2026	Inspection Time:8.30 AM	No. 31122	Issued by: Eci
Department/Contractor SUDHIR EQUIPMENT RENTAL COMPANY	Equipment No. SRC-RT-080-050 / 2525 ZAA		Equipment Location: RIYAZ NGL SITE , JUBAIL	Inspection Result : Pass	New sticker No. 32793	
Manufacturer: SANY	Model: SRC800T	Capacity: 80 t	Type: MOBILE CRANE/ROUGH TERRAIN	Equipment S.No. RC0080CF0560	Sticker Expiration 15-May-2026	

Above Equipment was inspected by Engineering Corner for Inspection in accordance with applicable Saudi Aramco Gi's, ASME and ANSI Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency Should be Noted in the corrective action taken column.

NO.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	ROUGH TERRAIN CRANE PERIODIC VISUAL INSPECTION AND FUNCTIONAL TEST PERFORMED PASSED AS PER ARAMCO G.I.7.030 AND ASME B30.5 STANDARD.	
2	Note : USED 80 t MAIN HOOK BLOCK WITH 6 PART LINES & 8 t AUX HOOK FITTED AT THE TIME OF INSPECTION.	

USER NAME:

A.r.siddiq

TECHNICAL REVIEWER NAME: Admin

INSPECTOR NAME:

ABDUL KHADER, 80019238

Received Date: 16-Feb-2026

SIGNATURE

Reviewed Date: 16-Feb-2026

SIGNATURE

BADGE#: 163

TELEPHONE No. 0540926436

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
1.0	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	☒	☐	☐	
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	☒	☐	☐	
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	☒	☐	☐	
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	☒	☐	☐	
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	☒	☐	☐	
1.6	Work areas chart is available	G.1.7.025ASME B30.5 Sec 5-1.1.3(2)	☒	☐	☐	
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	☒	☐	☐	
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	☒	☐	☐	
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4	☐	☐	☒	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4	☐	☐	☒	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	☒	☐	☐	
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	☒	☐	☐	
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	☒	☐	☐	
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	☒	☐	☐	
2.0	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	☒	☐	☐	
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	☒	☐	☐	
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	☒	☐	☐	
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	☒	☐	☐	
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5 Sec: 5-1.5.1	☐	☐	☒	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	☒	☐	☐	
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3	☐	☐	☒	
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2	☐	☐	☒	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	☒	☐	☐	
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	☒	☐	☐	
2.14	All cab glazings are safety glazing material	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	☒	☐	☐	
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	☒	☐	☐	
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	☒	☐	☐	
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7	☐	☐	☒	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☐	☐	☒	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.23	Boom shut-off or hyraulic relief is provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	☒	☐	☐	
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	☒	☐	☐	
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	☒	☐	☐	
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.27	LMI is fitted, Operational and accurate for boom length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	☒	☐	☐	
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	☒	☐	☐	
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 Sec:5-2.1.3 (d)	☒	☐	☐	
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	☒	☐	☐	
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	☒	☐	☐	
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	☒	☐	☐	
2.34	All tyres are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	☒	☐	☐	
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	☒	☐	☐	
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	☒	☐	☐	
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	☒	☐	☐	
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.52	Rope is free of kinking,crushing,birdcaging,or any other damage resulting in distortion of the rope structure .No more 1 broken wire protruding from the core .There are no reductions from nominal rope diameter of more than 5% for running ropes: .No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 for strand of 1 lay rotation resistance ropes .No more then 2randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters .Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	☒	☐	☐	
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
2.59	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	☒	☐	☐	
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	☒	☐	☐	
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	☒	☐	☐	
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5 Sec: 5-3.2.1.6	☒	☐	☐	
3.2	Crane level indicator is fitted and working	ASME B30.5 Sec: 5-1.9.10.6	☒	☐	☐	
3.3	Engine gauges and associated indicators are working	ASME B30.5 Sec: 5-2.1.3 (g)	☒	☐	☐	
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5 Sec: 5-1.9.12(g)	☒	☐	☐	
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5 Sec: 5-2.1.3 (c)	☒	☐	☐	
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5 Sec: 5-1.7.3 (d)	☒	☐	☐	
3.7	Hook assemblies are equipped with safety latches	ASME B30.5 Sec: 5-1.7.6	☒	☐	☐	
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.9	Hooks weight is clearly marked/printed on the hook	ASME B30.10 Sec: 10-1.10.5 (b)	☒	☐	☐	
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10 Sec : 10-1.8	☒	☐	☐	
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
3.12	Hook is not bent or twisted. Max. bending or twisting not to exceed 10 degrees from plane of unbent hook or as per manufacturer recommendations.	ASME B30.10 Sec : 10-1.10.5 (f)	☒	☐	☐	
3.13	Hook is not distorted in the throat opening. .Max allowable throat opening is 5% not to exceed 1/4 in.(6mm) compared to new hook,or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (g)	☒	☐	☐	
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (e)	☒	☐	☐	
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10 Sec : 10-1.10.5 (d)	☒	☐	☐	
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10 Sec : 10-1.10.5 (h)	☐	☐	☒	
3.17	Inoperative latch (if provided) $\frac{1}{2}$ any damaged latch or malfunctioning latch that does not close the hooks throat	ASME B30.10 Sec : 10-1.10.5 (i)	☒	☐	☐	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5 Sec:5-1.7.4	☒	☐	☐	
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5 Figure 5-1.7.3-1	☒	☐	☐	
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loopback termination	ASME B30.5 Figure 5-1.7.3-1	☒	☐	☐	
3.21	Reverse travel alarm is operational.	General	☒	☐	☐	
3.22	Turning signals and indicators are working correctly	General	☒	☐	☐	
3.23	Road lighting, including spotlights, are in good condition and operable	General	☒	☐	☐	
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	☒	☐	☐	
4.0	CRAWLER CRANE					
4.1	Track pads are undamaged	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.2	Drive sockets and tumblers are serviceable	ASME B30.5 Sec: 5-2.1.3 (h)	☐	☐	☒	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

ITEM. NO	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	Remarks
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.5	Back boom stops are functioning	ASME B30.5 Sec: 5-1.9.1 (a)	☐	☐	☒	
4.6	Back A-Frame is in good condition	ASME B30.5 Sec: 5-2.1.3 (a)	☐	☐	☒	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.8	Power low lowering is operational	ASME B30.5 Sec: 5-1.9.1 (a-2)	☐	☐	☒	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)	☐	☐	☒	
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5 Sec: 5-2.1.3	☐	☐	☒	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)	☐	☐	☒	
4.12	Pendant ropes are showing no broken wires (see no. 48)	ASME B30.5 Sec: 5-2.4.2	☐	☐	☒	
4.13	Operation of steering brakes is satisfactory	ASME B30.5 Sec: 5-1.5.3	☐	☐	☒	
4.14	Main machinery guarding is in place	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.15	Main clutch is fully operational	ASME B30.5 Sec: 5-1.6.4	☐	☐	☒	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5 Sec: 5-1.3.2(a-1)	☐	☐	☒	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER SAIC-U-7007	ISSUE DATE 1-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES				
PROJECT TITLE		WBS/BI/JO NUMBER DMM/02-26/022	INSPECTION COMPANY ECI	

EQUIPMENT ID NUMBER SRC-RT-080-050 / 2525 ZAA	EQUIPMENT DESCRIPTION/TYPE ROUGH TERRAIN		SERIAL NO RC0080CF0560	REPORT No 031445
CAPACITY (SWL) 80 t	MANUFACTURER SANY		FACILITY / LOCATION RIYAZ NGL SITE , JUBAIL	
REQUESTED INSPECTION DATE 16-Feb-2026	RFI No	TASK COMPLETED DATE 16-Feb-2026	EQUIPMENT OWNER SUDHIR EQUIPMENT RENTAL COMPANY	

Remarks:	
Reference Documents 1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes 2- ASME B30.10 - 2019 Issue: Hooks 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification	
Load Tested By (if Applicable): Name, Signature, & Date:	
Inspected Witnessed by 3rd Party Certified Inspector: Name, Signature, Certificate No. & Company:	
ABDUL KHADER, 80019238	
User Representative: Name, Signature, & Date:	
A.r.siddiq & 16-Feb-2026	



Engineering Corner for Inspection Co. Ltd. (ECI)

P.O.Box 235 Rastanura 31941 Kingdom of Saudi Arabia

Tel.:(013)667-6999 / 667-6895 - Fax:(013)667-6894

E-mail: eci@eccgroupksa.com

No. **ECI - 32793**

EQUIP.S.N.: RC0080CF0560

EQUIP. NO.: SRC-RT-080-050 / 2525 ZAA

EQUIP SWL: 80 t

INSPECTION DATE : 16-Feb-2026

NEXT INSPECTION DATE : 15-May-2026

INSPECTOR NAME : ABDUL KHADER

SAP# : 80019238

"S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY"

	ENGINEERING CORNER for INSPECTION		Doc. No.	ECIR- LFT - 105
			Rev. No	01
	CUSTOMER FEEDBACK FORM - LFT & ELEV		Rev. Date	1 NOV 2025
			Page No.	1 of 1

Issue Number : 02 & Issue Date : 03 FEB 2020

Feedback Form Number: 031445

Customer Details:

Client Name	BIG CRANE ARABIA COMPANY	Contact Person Name	A.r.siddiq
Client Address	RIYAZ NGL SITE , JUBAIL	Department	163
Email ID	Info@bigcrane-arabia.com	Contact Number	0540926436
Inspection Date	16/02/2026	Inspector Name	ABDUL KHADER

Dear Sir/Madam,

We request you to kindly put a 'TICK' mark in the respective boxes against each aspect described below and to assess your feedback with respect to the service we have provided so far. Any other suggestion or remarks please indicate the same to improve further. Thank you for taking your time for giving your valuable feedback to us.

Description	Yes	No	Remarks
Did the Service provider Co. provide the right inspector with a valid qualification card?	☒		
Did the Service provider Co. respond for inspection within the expected time frame?	☒		
Was the inspector wearing the required personal protective equipment (PPE) during the inspection?	☒		
Did the inspection conducted safely and in accordance with Aramco's standards?	☒		
How satisfied are you with the overall service provided? * * * * *			
Would you consider using this Service Provider again for future inspections? * * * * *			
For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)			

Any suggestions for improvement or additional services required?	Feedback given by (Customer Representative)
	