

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	Crane
Brand / Make	SANY
Asset ID	SRC-RT-080-054
Model Number	SRC800T
Serial Number	RC0080CF0565
Capacity	80 TON
Type	ROUGH TERRAIN CRANE
Manufacturing Year	2025

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Rajesh Thakur
Plant Manager
Sudhir Equipment Rental Company



KINGDOM OF SAUDI ARABIA
MINISTRY OF INTERIOR

رخصة سير
VEHICLES REGISTRATION

المملكة العربية السعودية
وزارة الداخلية

المالك شركة سودهير لتأجير المعدات شركة الشخص الواحد

المستخدم

هوية المالك ٧٠١٦١٥٨٣٣٤

رقم الهيكل LFCNR54D3S3000342

رقم اللوحة ٢٥٢٩ م أ أ

نوع التسجيل اثنغال عامه 2529 Z A A

طراز المركبة كرين

حمولة المركبة ٢

سنة الصنع ٢٠٢٥

اللون ابيض

الرقم التعريفي ٥١٠٥٢٩١٢٠



بهذا نشهد بأننا أصدرنا وثيقة تأمين للمركبة الموصوف ببياناتها أدناه بموجب أحكام وشروط
تأمين المسؤولية المدنية تجاه الغير في المملكة العربية السعودية

This is to certify we issued a motor policy of below referred vehicle in
accordance with terms and conditions of Third Party Liability in Kingdom of
Saudi Arabia

Product ID A-GIGR-1-C-13-002

CERTIFICATE OF MOTOR VEHICLE

INSURANCE NO : 5/VX/31062/0/0

INSURED NAME : SUDHIR EQUIPMENT RENTAL COMPANY

MOTOR VEHICLE DETAILS :

- Registration No : AAZ 2529
- Chassis No : LFCNR54D3S3000342
- Make : Sany CRANE
- Year : 2025
- Custom Card ID :

PERIOD OF INSURANCE :

- Commencement date : 12/06/1447 (H)
- Expiry date : 16/05/1448 (H)
- Corresponding to : From 03/12/2025 To 28/10/2026

Subject always to the Limits of Liability of 10,000,000 S.R. as
provided in the Policy arising out of the use of the insured Motor
Vehicle within Saudi Arabia .

This Certificate is deemed to be a guarantee for payment for all
amounts which the Insured Owner and/or the Authorized Driver at
the time of the accident shall become legally liable to pay as
compensation for

- (a) Death or bodily injury sustained by any person including
passengers of the vehicle
- (b) Damage to third party property outside the Insured Vehicle

شهادة تأمين السيارة رقم :

5/VX/31062/0/0

إسم المؤمن له : شركة سودهير لتأجير المعدات

تفاصيل السيارة :

رقم اللوحة : 2529 ١١ م
رقم الهيكل : LFCNR54D3S3000342
نوع السيارة : CRANE <SANY>
الموديل : 2025
رقم البطاقة الجمركية :

مدة التأمين :

تاريخ الإبتداء : 12/06/1447 هجرية
وينتهي في : 16/05/1448 هجرية
12/06/1447 (H) 16/05/1448 (H)

وذلك ضمن حدود المسؤولية 10,000,000 رس المبينة في الوثيقة والناجمة
لإستخدام السيارة المؤمنة داخل المملكة العربية السعودية
وتعتبر هذه الشهادة كضمان لدفع كافة المبالغ التي يكون الملك المؤمن له أو
السائق المخول في وقت الحادث مسؤولين قانونا عن دفعها كتعويض عن
1. الوفاة أو الإصابة البدنية التي تحدث لأي شخص بما في ذلك ركاب
السيارة
2. تلف ممتلكات أي طرف ثالث خارج المركبة المؤمنة

SIGNED :

التوقيع :



IMPORTANT

- This certificate of Insurance and Policy is valid only for the
Insured Owner and the authorized Driver at the time of
Accident and is NOT transferable without prior consent
of the Insurance Company.
- Any Accident must be notified to the Insurance
Company as soon as possible by visiting our website
<https://www.gig.sa/ar/claim-form>
or by contacting us on 920008477 or visiting our outlets

ملاحظات هامة

- إن شهادة التأمين هذه صالحة فقط للمالك المؤمن له والسائق المخول له
بالقيادة في حالة وقوع حادث وهي غير قابلة للتحويل بدون موافقة
مسبقة من قبل شركة التأمين
- عند وقوع أي حادث يجب إخطار الشركة في أسرع وقت ممكن
من خلال زيارة موقعنا الإلكتروني:
<https://www.gig.sa/ar/claim-form>
أو بالإتصال على الرقم 920008477 أو بزيارة أحد منافذنا

8007

蓝白黑

VIN/发动机号确认表格

VIN/Engine Number Verification Form

车辆编码 Vehicle identification	RC0080CF0565	空调 air conditioner	电装
发动机型号 engine model	QSB6.7-C260-31	发动机号 engine identification	93398360
轮胎型号 tire model	29.5-25	排放标准 emission standards	国三



★LFCNR54D3S30000342★

VIN 号码



★LFCNR54D3S30000342★

发动机号拓 印 Engine Number Rubbing	刘亮 1.23
提交人/日 期 Submitted by/Date	

1. Certification No 合格证编号	WDE02025201036		2. Date of Issue 发证日期	2025-02-20	
3. Manufacture 车辆制造企业名称	SANY AUTOMOBILE MANUFACTURING CO., LTD 三一汽车制造有限公司				
4. Make / Category 车辆品牌/车辆名称	Sany 三一牌		Rough Terrain Crane 越野轮胎起重机		
5. Crane Model 车辆型号	SRC800T		6. Vehicle Identification No. 车辆识别代号	LFCNR54D3S3000342	
7. Chassis Type 底盘型号	SRC800T		8. Vehicle Color 车身颜色	BLUE/WHITE/BLACK	
9. Engine Model 发动机型号	QSB6.7		10. Engine No. 发动机号	93398360	
11. Applicable Fuel 燃料种类	DIESEL 柴油		12. Displacement / Rate Power 排量 and 功率 (ml/kW)	6690	194
13. Emission Standard 排放标准	EU STAGE III				
14. Crane Overall-dimension (mm)	14600	3340	3930	15. Plates of Leaf Spring 钢板弹簧片数	/
16. Tires Specifications 轮胎规格	29.5-25		17. Qty of Tires 轮胎数	4	
18. Tires Span (mm) 轮距 (前/后) (mm)	2520	2520		19. Wheelbase (mm) 轴距 (mm)	4265
20. Axle Load 轴荷 (kg)	27530/24535				
21. Qty of Axles 轴数	2		22. Steering Application 转向形式	STEERING WHEEL 方向盘	
23. Overall Weight (kg) 总质量	52,065		24. Equipment Quality 整备质量 (kg)	52,000	
25. Driver-cabin Passengers Allowed 驾驶室准乘人数	1		26. QR Code 条码		
27. Nominal Max Speed (km/h) 最高设计车速	36		28. Fabrication Date 车辆制造日期	2025-01-31	
Remarks					
Upon all due inspection the above-specified crane conforms to the standards of Q/OKTW 052-2025 <Rough Terrain Crane>. Certification is hereby issued for ready delivery. 本产品经过检验,符合Q/OKTW 052-2025《越野轮胎起重机》的要求,准予出厂,特此证明 Manufacture Name: Sany Automobile Manufacturing Co., Ltd. 车辆生产单位名称: 三一汽车制造有限公司 Manufacture Address: Sany Crane Industrial Park, No.168, Jinzhou Avenue, Changsha City, Hunan Province, People's Republic of China. 车辆生产单位地址: 长沙市宁乡市金洲大道西168号 Internal Vehicle Identification Code 内部编号: RC0080CF0565					





SANY

Certificate No. (证书编号) : RC0565-1
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0565
Part No. (物料编码) : 12838070

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN1677-2:2000+A1:2008.

Name of Product : 80 t hook
Hook Serial No : TQ25018005012
Safety Working Load : 80 metric tons
Test Load : 100 metric tons
Hook Ass'y Weight : 800 kg
Hook Material : 35CrMo

Certified by:



2025-02-20

Date of inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0565-2
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0565
Part No. (物料编码) : 132702010194A

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN1677-2:2000+A1:2008.

Name of Product : 8 t hook
Hook Serial No : ZX25010034
Safety Working Load : 8 metric tons
Test Load : 10 metric tons
Hook Ass'y Weight : 180 kg
Hook Material : 35CrMo

Certified by:



2025-02-20

Date of inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting

Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0565-1
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0565
To Messers (主机公司) : Sany Automobile Hoisting Machinery Co., Ltd.
Manufacturer (生产厂商) : Juli Sling Co., Ltd.

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN 12385-4. (兹证明下列产品依据 EN 12385-4 标准检验合格)。

Construction (结构) : 35W×K7
Lay (绞丝方式) : Right hand, Lang lay (右旋, 同向捻)
Grade of Strength (强度级别) : 2160N/mm²
Length (长度) : 250m
Total Mass of the Rope (总重) : 469.6kg

Diameter (直径)	Nominal (设计值) : 20mm Actual (实测值) : 20.7mm
Breaking Load (断裂载荷)	Nominal (设计值) : 368kN Actual (实测值) : 386kN

Certified by:

2025-02-20

Date of Inspection



* Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting
Machinery Co., Ltd.



SANY

Certificate No. (证书编号) : RC0565-2
Model No. (车辆型号) : SRC800T
Crane serial No. (整车编号) : RC0080CF0565
To Messers (主机公司) : Sany Automobile Hoisting Machinery Co., Ltd.
Manufacturer (生产厂商) : Juli Sling Co., Ltd.

INSPECTION CERTIFICATE

This is to certify that the following product has been duly inspected and passed in accordance with EN 12385-4. (兹证明下列产品依据 EN 12385-4 标准检验合格)。

Construction (结构) : 35W×K7
Lay (绞丝方式) : Right hand, Lang lay (右旋, 同向捻)
Grade of Strength (强度级别) : 2160N/mm²
Length (长度) : 145m
Total Mass of the Rope (总重) : 272.4kg

Diameter (直径)	Nominal (设计值) : 20mm Actual (实测值) : 20.7mm
Breaking Load (断裂载荷)	Nominal (设计值) : 368kN Actual (实测值) : 386kN

Certified by:

2025-02-20

Date of Inspection

Chief Inspector

Quality Assurance Dept.

Sany Automobile Hoisting
Machinery Co., Ltd.

吊载测试证明
Certificate of Load Test证书编号
Certificate NO.

3G01202502200010

设备编号
Crane Serial No.

RC0080CF0565

制造单位名称 Manufacture Name		三一汽车制造有限公司 Sany Automobile Manufacturing Co., LTD							
序号 No	工作条件 Working Condition	臂长(米) Boom Length (unit: m)	吊载重量 (吨) Load Weight (unit: t)	幅度半径(米) Amplitude Radius (unit: m)	倍率 Ratio of Line	支腿 Outrigger	配重 counterweigh t	吊载测试 Load test	备注 Remark
1	基本臂 Base Boom	12.2	33.5	8	6	全伸支腿 Full- Extended	全配重 Full Counterweigh t	合格 Qualified	大臂位于侧面 和后方 Boom is over side and rear
2	中间臂 Mid-extended boom	27.6	29.5	5.5	6			合格 Qualified	
3	全伸臂 Full-extended boom	47	11.5	11	4			合格 Qualified	
4	主臂+副臂 Main boom + jib	47+17.5	2.9	主臂 78° , 副臂 0° , Main boom angle 78° and jib offset 0°	1			合格 Qualified	
5	吊载行驶 (≤4 km/h) Travel with Load	12.2	9.5	6.0	4	不伸支腿 Not- Extending	全配重 Full Counterweigh t	合格 Qualified	吊臂在正面 Boom is over front

根据公司内部吊载试验结果, 该产品具备相关起重性能, 吊载精度符合 GB/T 12602, EN 13000, SAEJ159 相关标准。

According to the results of the company's internal loading test, the product has the relevant loading performance, and the loading accuracy meets the relevant standards of GB/T 12602, EN 13000, SAEJ159.

特此颁发证书。

Certification is hereby issued.





CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 2035989	Date of Examination: 07/09/2025	Sticker No.: 24-7789 LOAD TEST
---------------------------	--	---------------------------------------

Name & address of owner of the equipment		Sudhir Equipment Rental Company			
Inspection requested by		Sudhir Equipment Rental Company			
Place of inspection		DMM Yard.			
Type of inspection		LOAD TEST			
Relevant regulation / Standard		ASME B30.5			
Date of previous inspection / load test					
Identification & Description of the Equipment	Manufacturer name	SANY			
	Equipment Type	RT Mobile Crane			
	Nature of power	DEISEL POWERED			
	Model / Year	SRC800T/ 2025			
	Serial number	RC0080CF0565			
	Owner ID / Registration number	SRC-RT-080-054			
	Rated Capacity (maximum)	80 Ton			
	Present Configuration	Main hoist current capacity: 80 Ton with 6 FALLS			
		Auxiliary hoist current capacity: 8 Ton with 1 Falls			
	Radius (Mini / Max)	Minimum: 3 Mtr; Maximum: 34 Mtr			
	Length of Boom	Minimum: 12.2 Mtr; Maximum: 47.5 Mtr			
	Counterweight (mass)	Standard from Manufacturer			
	Wire rope specification	20 mm			
	Complementary devices	Fly Jib Was Stowed			

Description of test: Visual & Function Test inspection was carried out, followed by full functional testing. 100 % Of SWL Load Test Was Carried Out	Length of boom (m)	Radius (m)	Reeving (No. of falls)	Test Load	Safe Working Load
	27.6 M	20 M	6 Falls	4800 Kg	4800 Kg
	-	-	-	-	-
	-	-	-	-	-

Result of Examination:

The above mentioned equipment has been found satisfactory at the time of inspection and is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

This is to certify that the Competent Person did attend at the said premises on said date to witness proof load test and/or to carry out thorough examination of the equipment described herein and that all particulars described above were correct at the time of examination. This Certificate becomes void in case of any major repair, modification and /or alteration being un-authorized by issuer of hereof.

Next Proof Load Test Due: 06/09/2030 or After Major Repair/Modifications	Next Inspection Due is on or before: 06/12/2025
---	--

Issued at Al Khobar on 13/09/2025

Inspector to Bureau Veritas
Signature:



Name: MOHAMED OMARA
Position: Senior Inspector



Reviewed by
Signature:



Name: Ahmed Elabady
Position: Reviewer

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This not is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacture, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



CHECKLIST OF TEST & THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 2035989	Date of Examination: 07/09/2025
---------------------------	--

SECTION	CONDITION	REMARKS
1. ACCESS		
1.1 Access to the cabin/control station	Satisfactory	
1.2 Access for maintenance operation	Satisfactory	
2. CHASSIS		
2.1 Chassis	Satisfactory	
2.2 Traveling device (tire, crawler)	Satisfactory	
2.3 Outriggers	Satisfactory	
2.4 Outrigger sole (shoe or pad)	Satisfactory	
2.5 None return valve on outrigger	Satisfactory	
2.6 Locking of suspensions	Satisfactory	
2.7 Locking of outriggers rest position	Satisfactory	
3. STRUCTURE OF EQUIPMENT		
3.1 Structure, A frame	Satisfactory	
3.2 Jib, fly jib	Satisfactory	
3.3 Pendants	Satisfactory	
3.4 Counter weight	Satisfactory	
4. MECHANISM		
4.1 Main Hoisting mechanism	Satisfactory	
4.2 Aux. Hoisting mechanism	Satisfactory	
4.3 Hydraulic system	Satisfactory	
4.4 Cylinders	Satisfactory	
4.5 Hoisting brake system	Satisfactory	
4.6 Limitation of the lowering speed	Satisfactory	
4.7 Telescoping mechanism	Satisfactory	
4.8 Luffing mechanism	Not applicable	
4.9 Pivoting joints	Satisfactory	
4.10 Brake of slewing motion	Satisfactory	



4.11 Traveling Brake	Satisfactory	
4.12 Guards for moving parts	Satisfactory	
4.13 Motor	Satisfactory	
4.14 Gear box	Satisfactory	
5. LIFTING SYSTEM		
5.1 Wire rope / chain	Satisfactory	
5.2 Wire/chain rope end termination	Satisfactory	
5.3 Drum, pulley, return pulley	Satisfactory	
5.4 Hooks & hook blocks	Satisfactory	
5.5 Other load handling devices	Satisfactory	
6. ENERGY		
6.1 Main switch locking	Satisfactory	
6.2 Equipment and cabling	Satisfactory	
6.3 Protection of live parts/enclosure	Satisfactory	
6.4 Lighting of the crane/site	Satisfactory	
7. CABIN / CONTROL STATION		
7.1 Structure	Satisfactory	
7.2 Visibility / windows	Satisfactory	
7.3 Heating / AC system	Satisfactory	
7.4 Seat	Satisfactory	
7.5 Fire extinguisher	Satisfactory	
7.6 Identification of the controls	Satisfactory	
7.7 Control dead man type	Satisfactory	
7.8 General stopping device by key	Satisfactory	
7.9 Emergency stop button	Satisfactory	
7.10 Level indicator	Satisfactory	
7.11 Angle Indicator	Satisfactory	
7.12 Horn	Satisfactory	
7.13 Traffic lights	Satisfactory	
7.14 Direction Indicators	Satisfactory	
8. SAFETY DEVICES		



BUREAU
VERITAS



8.1 Hoisting limiter/Anti Two Blocks	Satisfactory	
8.2 Luffing limiter	Not applicable	
8.3 Telescopic limiter	Satisfactory	
8.4 Slewing limiter	Satisfactory	
8.5 Load limiter	Satisfactory	
8.6 Level limiter	Satisfactory	
8.7 Rated capacity indicator (RCI) / ASLI	Satisfactory	
8.8 None return valve on piston	Satisfactory	
8.9 Other limiter or indicator	Satisfactory	
9. MISCELLANEOUS REQUIREMENTS		
9.1 Maker plate	Satisfactory	
9.2 Load chart	Satisfactory	
9.3 Wire rope certificate	Satisfactory	
9.4 General Safety Requirements	Satisfactory	
Notes :		
Next Proof Load Test Due: 06/09/2030 or After Major Repair/Modifications		Next Inspection Due is on or before: 06/12/2025

Inspector to Bureau Veritas
Signature:



Name: MOHAMED OMARA
Position: Senior Inspector



Bureau Veritas, Saudi Arabia

8th Floor, Danah Business Tower, Olaya District, Al Khobar, Kingdom of Saudi Arabia

Tel No : +966 13 882 1071

Web : <https://middle-east.bureauveritas.com>



Report No.: 249204

LIFTING EQUIPMENT INSPECTION REPORT	RPO NO. N/A		CRM NO. -		Report No. 249204	
	Area DAMMAM	Inspection Date 25/02/2026		Inspection Time 8:00	Previous Sticker	
					No.BV-3939	Issue By BV
Department / Contractor SUDHIR EQUIPMENT RENTAL CO.	Equipment Number SRC-RT-080-054	Equipment Location DMM YARD		Inspection Result Pass	New Sticker No. BV-3863	
Manufacturer SANY	Model SRC800T	Capacity 80 TON	Type Mobile Crane	Equipment Serial Number RC0080CF0565	Sticker Expiration Date 24/05/2026	

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's, ASME and API Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

Corrective action taken column.

No.	DEFICIENCIES / NOTES	Corrective Action Taken		
1	-PERIODIC INSPECTION AND FUNCTION TEST FOR RT MOBILE CRANE AS PER AS S.ARAMCO GI 7.030 AND ASME B30.5 -MAIN HOOK BLOCK S/N: T025018005012 ,SWL: 80 TON @ 6 FALLS - AUX HOOK S/N:ZX25010034 ,SWL: 8 TON @ 1FALL - FLY JIB WAS STOWED -PLATE#2529 ZAA -EQUIPMENT WAS FOUND SATISFACTORY AT THE TIME OF INSPECTION -FOLLOW PROPER PM REGULARL	-		
Receiver's Name : ARIF		Badge No : -	Technical Reviewer Name : MAHMOUD EL NAHAS Received Date: 25/02/2026	Inspector Name : MOHAMED OMARA
Telephone No: 055 222 8031		Receiver Signature : 	Signature: Reviewed Date: 25/02/2026 	Inspector's Signature : 

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

SAUDI ARAMCO INSPECTION CHECKLIST			SAIC NUMBER SAIC-U-7007	ISSUE DATE 12-Jan-23	DISCIPLINE ELEVATING/LIFTING EQUIPMENT
MOBILE / CRAWLER CRANES					
PROJECT TITLE			WBS/BI/JO NUMBER	INSPECTION COMPANY Bureau Veritas, Saudi Arabia	
EQUIPMENT ID NUMBER : SRC-RT-080-054	EQUIPMENT DESCRIPTION/TYPE : Mobile Crane		SERIAL NO. : RC0080CF0565	REPORT No.: 249204	
CAPACITY (SWL) : 80 TON	MANUFACTURER : SANY		FACILITY / LOCATION : DMM YARD		
REQUESTED INSPECTION DATE :	RFI No.	TASK COMPLETED DATE : 25/02/2026	EQUIPMENT OWNER : SUDHIR EQUIPMENT RENTAL CO.		

ACCEPTANCE CRITERIA

1.0 GENERAL REQUIREMENTS

		REFERENCE	PASS	FAIL	NA	REMARKS
1.1	Equipment documentation is available	ASME B30.5	✓			
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	✓			
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	✓			
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	✓			
1.5	Durable load chart is provided in an accessible location	ASME B30.5	✓			
1.6	Work areas chart is available	ASME B30.5	✓			
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025	✓			
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	G.I. 7.030	✓			
1.9	Crane is painted safety yellow	SAES-B067			✓	

		REFERENCE	PASS	FAIL	NA	REMARKS
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067			✓	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067	✓			
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5	✓			
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5	✓			
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5	✓			

2.0 INSPECTION POINTS (MOBILE & CRAWLER CRANES)

		REFERENCE	PASS	FAIL	NA	REMARKS
2.1	Load- holding check valve for boom is operational	ASME B30.5	✓			
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5	✓			
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5	✓			
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5	✓			
2.5	Travel controls are properly operating/functioning	ASME B30.5	✓			
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5			✓	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5			✓	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5	✓			
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5			✓	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5	✓			
2.12	Sheave guards are in place on the lower block	ASME B30.5	✓			
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5	✓			
2.14	All cab glazing's are safety glazing material	ASME B30.5	✓			
2.15	Verify cab doors functionality and condition	ASME B30.5	✓			
2.16	Seat belt is fitted and in good condition	ASME B30.5	✓			
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5	✓			
2.18	Guard rails are fitted for crawler cranes	ASME B30.5			✓	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5			✓	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5			✓	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5	✓			
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5	✓			
2.23	Boom shut-off or hydraulic relief is provided for high angle boom condition	ASME B30.5	✓			
2.24	Boom length indicator is fitted for telescoping booms and is working	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5	✓			
2.26	Operation and accuracy of the fitted LMI (compare with load chart over a range of angles and radii)	ASME B30.5	✓			
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.28	Outriggers and jacks are not leaking oil	ASME B30.5	✓			
2.29	Jack is in good operating condition at each outrigger	ASME B30.5	✓			
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5	✓			
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5	✓			
2.32	Outrigger jack bolts are fully secure	ASME B30.5	✓			
2.33	All road wheel nuts are fully secure	ASME B30.5	✓			
2.34	All tyres are serviceable and without damage or excess wear	ASME B30.5	✓			
2.35	Fuel tank supports and straps are secure	ASME B30.5	✓			
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5	✓			
2.37	Underside of chassis shows no obvious faults	ASME B30.5	✓			
2.38	Outrigger boxes are not cracked	ASME B30.5	✓			
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5	✓			
2.40	Track rod end joints are not worn and are secure	ASME B30.5	✓			
2.41	Axle bolts and nuts are fully secure	ASME B30.5	✓			
2.42	Wheel hub oil seals are not leaking	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.43	Brake linings are not oil contaminated	ASME B30.5	✓			
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5	✓			
2.45	All chassis cross members are not cracked or corroded	ASME B30.5	✓			
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5	✓			
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5	✓			
2.48	Ring gear bolts are fully secure	ASME B30.5	✓			
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5	✓			
2.50	Engine shows no major oil leakage	ASME B30.5	✓			
2.51	Radiator does not leak water	ASME B30.5	✓			
2.52 (a)	Rope is free of damages: 1 broken wire protruding from the core Wear of 1/3 of the original diameter of outside individual wires Kinking, crushing, birdcaging or other distortion	ASME B30.5	✓			
2.52 (b)	For running ropes: Max of 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay, For rotation resistance ropes: 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters	ASME B30.5	✓			
2.52(c)	Evidence of any heat damage from any cause Reduction below nominal diameter	ASME B30.5	✓			
2.53	Main hoist drum mounting bolts are secure	ASME B30.5	✓			
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5	✓			
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5	✓			
2.56	Center swivel coupling pipes and hoses do not leak	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.57	Center swivel coupling bolts are all secure	ASME B30.5	✓			
2.58	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5	✓			
2.59	Swing gearbox mounting bolts are secure	ASME B30.5	✓			
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5	✓			
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5	✓			
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5	✓			

3.0 CRANE CAB

		REFERENCE	PASS	FAIL	NA	REMARKS
3.1	Horn and wind speed anemometer are working	ASME B30.5	✓			
3.2	Crane level indicator is fitted and working	ASME B30.5	✓			
3.3	Engine gauges and associated indicators are working	ASME B30.5	✓			
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5	✓			
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5	✓			
3.7	Hook assemblies are equipped with safety latches	ASME B30.5	✓			
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10	✓			
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.10	✓			
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10	✓			
3.12	Hook is not bent or twisted	ASME B30.10	✓			
3.13	Hook is not distorted in the throat opening - Max. allowable throat opening is 15% compared to new hook, or as per manufacturer recommendations	ASME B30.10	✓			
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10	✓			
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10	✓			
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10			✓	
3.17	Inoperative latch (if provided) — any damaged latch or malfunctioning latch that does not close the hook's throat	ASME B30.10 Sec : 10-1.10.5 (i)	✓			
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5	✓			
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5	✓			
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5	✓			
3.21	Reverse travel alarm is operational	ASME B30.5	✓			
3.22	Turning signals and indicators are working correctly	ASME B30.5	✓			
3.23	Road lighting, including spotlights, are in good condition and operable	ASME B30.5	✓			
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	✓			

4.0 CRAWLER CRANE

		REFERENCE	PASS	FAIL	NA	REMARKS
4.1	Track pads are undamaged	ASME B30.5			✓	
4.2	Drive sockets and tumblers are serviceable	ASME B30.5			✓	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5			✓	
4.4	Track idlers are serviceable	ASME B30.5			✓	
4.5	Back boom stops are functioning	ASME B30.5			✓	
4.6	Back A-Frame is in good condition	ASME B30.5			✓	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5			✓	
4.8	Power low lowering is operational	ASME B30.5			✓	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)			✓	
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5			✓	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)			✓	
4.12	Pendant ropes are showing no broken wires (see 2.0.55)	ASME B30.5			✓	
4.13	Operation of steering brakes is satisfactory	ASME B30.5			✓	
4.14	Main machinery guarding is in place	ASME B30.5			✓	
4.15	Main clutch is fully operational	ASME B30.5			✓	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5			✓	

REMARKS

-

REFERENCE DOCUMENTS:

- 1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes
- 2- ASME B30.10 - 2019 Issue: Hooks
- 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 5- SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

Signature

Inspected / Witnessed by 3rd Party Certified Inspector

Name MOHAMED OMARA

Signature



Certificate No. 80019106

Company Bureau Veritas

Telephone No 055 078 7628

User Representative

Name	ARIF
Signature	
Date	25/02/2026
Badge	-
Telephone No:	055 222 8031



Sticker No:
BV-3863

Bureau Veritas
Tel.: + 966 013 822
1071
Fax: + 966 013 822
1072
Al Khobar, Saudi
Arabia



EQUIP .S.N: RC0080CF0565

EQUIP .NO : SRC-RT-080-054

EQUIP.SWL : 80 TON

INSPECTION DATE : 25/02/2026

NEXT INSPECTION DATE :24/05/2026

INSPECTOR NAME: MOHAMED OMARA

SAP # 80019106

SA INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY

Client Satisfaction and Service Feedback

Survey questions

		Answers	Remarks
1	Did the Service provider Co. provide the right inspector with a valid qualification card?	Yes	
2	Did the service provider Co. respond for inspection within the expected time frame?	Yes	
3	Was the inspector wearing the required personal protective equipment (PPE) during the inspection?	Yes	
4	Did the inspection conducted safely and in accordance with Aramco's standards?	Yes	

For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)

1765452402240

2025-12-11

7016158334

شركة سودهير لتأجير

الرقم المرجعي :

تاريخ إصدار القائمة :

رقم العميل:

اسم العميل:

عدد المركبات في التقرير 1													
تقرير المركبات													
رقم اللوحة	نوع التسجيل	نوع الهيكل	وضع المركبة	الماركة	الطراز	سنة الصنع	الرقم التسلسلي	رقم الهيكل	اللون الأساسي	تاريخ الملكية	تاريخ انتهاء رخصة السير	حالة التأمين	هوية المستخدم الفعلي
أ أ م 2529	معدات ثقيلة		صالحة	ساني	كرين	2025	510529120	LFCNR54D3S3000342	ازرق	1446-11-17	1449-11-17	ساري المفعول	اسم المستخدم الفعلي



الشركة العالمية لخدمات التفتيش المحدودة

UNIVERSAL INSPECTION CO. LTD.

CR No. 2055011643

س.ت ٢٠٥٥٠١١٦٤٣

INSTRUMENT & EQUIPMENT CALIBRATION DIVISION

CERTIFICATE OF CALIBRATION

CERTIFICATE NO : UIC/DAM/82032

This certifies that the instrument below has been tested/calibrated using equipment traceable to National/International Standards or verified by ratio type measurements using self calibrating techniques.

Information on the calibration process and the results are produced below and given in the accompanying sheets of this document.

All related traceable documents are on file at **UNIVERSAL INSPECTION CO. LTD.** and may be examined on request

Customer	Sudhir Equipment Rental Company		
Address	Dammam, Kingdom of Saudi Arabia		
Description	Crane Anemometer		
Manufacture	SANY		
Model	N/A		
Serial. No.	72413010146		
Plate/ID No.	2529 ZAA /SRC-RT-080-054	Calibration Date	: 26-Feb-26
Location	Dammam	Calibration Due Date	: 25-Aug-26

The instrument was calibrated using the following reference, maintained at UIC Instrument & Equipment Calibration division conforming to ISO/IEC 17025:2017 requirements

Reference Standard Equipment Used

Description	Cert. No.	Serial No	Due Date
Mini Wind Tunnel	SA178189-224892	221221	25-Jan-27

Calibrated By



Calibration Engineer



UIC-QP-7.8-24 F02, REV 0

Approved By

QA/QC Engineer

The measurement results pertain only to the instrument calibrated.

This certificate and the attached measurement result sheets shall not be reproduced except in full without the prior permission

P.O. Box No. 2072, Jubail - 31951, K.S.A.

Tel.: +966 13 344 8882 / Fax: +966 13 344 8881

Tel.: +966 13 367 0515

www.ui.com.sa

ص.ب ٢٠٧٢، الجبيل ٣١٩٥١ - المملكة العربية السعودية

هاتف ٨٨٨٢ ١٣ ٣٤٤ / فاكس ٨٨٨١ ١٣ ٣٤٤ +٩٦٦

هاتف ٠٥١٥ ٣٦٧ ١٣ ٣٦٦ +٩٦٦

CERTIFICATE NO : UIC/DAM/82032

Page

2 of 2

Customer **Sudhir Equipment Rental Company**
Address Dammam, Kingdom of Saudi Arabia

Description	Crane Anemometer	Calibration Date	26-Feb-26
Manufacturer	SANY	Calibration Due Date	25-Aug-26
Model	N/A	Temperature	43.6°C
Serial. No.	72413010146	Relative Humidity	RH 36%
Plate/ID No.	2529 ZAA /SRC-RT-080-054		

Calibration Test Data

Function Tested	Setting Range in Master	UUT Readings	Error of Indication	% Error (FS)
<u>Air Velocity</u> (m/s)	(m/s)	(m/s)	(m/s)	(m/s)
0 to 40	0.00	0.00	0.000	0.000
	2.50	2.40	-0.100	-0.250
	5.00	4.90	-0.100	-0.250
	10.00	9.90	-0.100	-0.250
	15.00	14.90	-0.100	-0.250
	10.00	9.80	-0.200	-0.500
	5.00	4.90	-0.100	-0.250
	2.50	2.40	-0.100	-0.250
	0.00	0.00	0.000	0.000

General Information about the Calibration

The Crane Anemometer has been Calibrated on the function of Air.

Physical Condition of the UUT

The Unit Under Test is in Good Physical Condition.

Stability

The readings given are the results at the time of calibration and do not carry any implication regarding the Long-term Stability of the instrument.



Calibrated By: _____
 Calibration Engineer



UIC-QP-7.8-24 F02, REV 0

Approved by: _____
 QA/QC Engineer