

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	Crane
Brand / Make	SANY
Asset ID	SRC-RT-090-023
Model Number	SRC900T
Serial Number	RC0090CE0556
Capacity	90 TON
Type	Rough Terrain Crane
Manufacturing Year	2024

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Ajay Koul
General Manager
Sudhir Equipment Rental Company



بهذا نشهد بأننا أصدرنا وثيقة تأمين للمركبة الموصوف ببياناتها أدناه بموجب أحكام وشروط
تأمين المسؤولية المدنية تجاه الغير في المملكة العربية السعودية

This is to certify we issued a motor policy of below referred vehicle in
accordance with terms and conditions of Third Party Liability in Kingdom of
Saudi Arabia

Product ID A-GIGR-1-C-13-002

CERTIFICATE OF MOTOR VEHICLE

INSURANCE NO : 5/VX/31062/0/0

INSURED NAME : SUDHIR EQUIPMENT RENTAL COMPANY

MOTOR VEHICLE DETAILS :

- Registration No : AAA 3778
- Chassis No : LFCNR54D3P3200502
- Make : Sany CRANE
- Year : 2024
- Custom Card ID :

PERIOD OF INSURANCE :

- Commencement date : 12/06/1447 (H)
- Expiry date : 16/05/1448 (H)
- Corresponding to : From 03/12/2025 To 28/10/2026

Subject always to the Limits of Liability of 10,000,000 S.R. as provided in the Policy arising out of the use of the insured Motor Vehicle within Saudi Arabia .

This Certificate is deemed to be a guarantee for payment for all amounts which the Insured Owner and/or the Authorized Driver at the time of the accident shall become legally liable to pay as compensation for

- (a) Death or bodily injury sustained by any person including passengers of the vehicle
- (b) Damage to third party property outside the Insured Vehicle

شهادة تأمين السيارة رقم :

5/VX/31062/0/0

إسم المؤمن له : شركة سودهير لتأجير المعدات

تفاصيل السيارة :

رقم اللوحة : 3778 111

رقم الهيكل : LFCNR54D3P3200502

نوع السيارة : CRANE <SANY>

الموديل : 2024

رقم البطاقة الجمركية :

مدة التأمين :

تاريخ الإبتداء : 12/06/1447 هجرية

وينتهي في : 16/05/1448 هجرية

12/06/1447 (H) 16/05/1448 (H)

وذلك ضمن حدود المسؤولية 10,000,000 رس المبينة في الوثيقة والناجمة
لإستخدام السيارة المؤمنة داخل المملكة العربية السعودية

وتعتبر هذه الشهادة كضمان لدفع كافة المبالغ التي يكون الملك المؤمن له أو
السائق المخول في وقت الحادث مسؤولين قانونا عن دفعها كتعويض عن

1 . الوفاة أو الإصابة البدنية التي تحدث لأي شخص بما في ذلك ركاب
السيارة

2 . تلف ممتلكات أي طرف ثالث خارج المركبة المؤمنة

SIGNED :

التوقيع :



IMPORTANT

- This certificate of Insurance and Policy is valid only for the Insured Owner and the authorized Driver at the time of Accident and is NOT transferable without prior consent of the Insurance Company.
- Any Accident must be notified to the Insurance Company as soon as possible by visiting our website <https://www.gig.sa/ar/claim-form> or by contacting us on 920008477 or visiting our outlets

ملاحظات هامة

- إن شهادة التأمين هذه صالحة فقط للمالك المؤمن له والسائق المخول له بالقيادة في حالة وقوع حادث وهي غير قابلة للتحويل بدون موافقة مسبقة من قبل شركة التأمين
- عند وقوع أي حادث يجب إخطار الشركة في أسرع وقت ممكن من خلال زيارة موقعنا الإلكتروني: <https://www.gig.sa/ar/claim-form> أو بالإتصال على الرقم 920008477 أو بزيارة أحد منافذنا

KINGDOM OF SAUDI ARABIA
MINISTRY OF INTERIOR

رخصة سير
VEHICLES REGISTRATION

المملكة العربية السعودية

وزارة الداخلية

المالك شركة سودهير لتأجير المعدات شركة الشخص الواحد

المستخدم

هوية المالك ٧٠١٦١٥٨٣٣٤ هوية المستخدم

رقم الهيكل LFCNR54D3P3200502

رقم اللوحة ٣٧٧٨ أ أ أ

نوع التسجيل اشغال عامة

3778 A A A

طراز المركبة كرين

ماركة المركبة ساني

حمولة المركبة ٢

وزن المركبة ٥٤٦٠٠

سنة الصنع ٢٠٢٤

اللون / البيج

الرقم التسلسلي ١٠٧٢٧٩٠٢٠





CERTIFICATE OF TEST AND THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 1697446	Date of Examination: 07/07/2024	Sticker No.: 24-1342 LOAD TEST
---------------------------	--	---------------------------------------

Name & address of owner of the equipment		SUDHIR EQUIPMENT RENTAL CO.			
Inspection requested by		SUDHIR EQUIPMENT RENTAL CO.			
Place of inspection		DMM YARD			
Type of inspection		TEST & THOROUGH EXAMINATION			
Relevant regulation / Standard		ASME B30.5			
Date of previous inspection / load test		07/07/2024 Not applicable			
Identification & Description of the Equipment	Manufacturer name	SANY			
	Equipment Type	RT MOBILE CRANE			
	Nature of power	DEISEL POWERED			
	Model / Year	SRC900T			
	Serial number	E0556			
	Owner ID / Registration number	SRC-RT-090-023			
	Rated Capacity (maximum)	90 t			
	Present Configuration	Main hoist current capacity: 90 t with 6 FALLS Auxiliary hoist current capacity: 6.5 t with 1			
	Radius (Mini / Max)	Minimum: 2.5 m; Maximum: 38 m			
	Length of Boom	Minimum: 12.2 m; Maximum: 47 m			
	Counterweight (mass)	Standard from Manufacturer			
	Wire rope specification	21 mm			
	Complementary devices	N/A			

Description of test: -Visual inspection was carried out, followed by full functional testing. -100% OF LOAD TEST LOAD TEST WAS APPLIED Note: "This certificate does not cover the use of the equipment for Personnel/Man riding purposes".	Length of boom (m)	Radius (m)	Reeving (No. of falls)	Test Load	Safe Working Load
	16.6 m	6 m	6 falls	30000 kg	30000 kg
	20.9 m	10 m	6 falls	21000 kg	21000 kg
	25.3 m	16 m	6 falls	10600 kg	10600 kg

Result of Examination:

The above mentioned equipment has been found satisfactory at the time of inspection and is considered to be safe for further use, subject to continuous maintenance being applied and qualified operator being employed.

This is to certify that the Competent Person did attend at the said premises on said date to witness proof load test and/or to carry out thorough examination of the equipment described herein and that all particulars described above were correct at the time of examination. This Certificate becomes void in case of any major repair, modification and / or alteration being un-authorized by issuer of hereof.

Next Proof Load Test Due: 06/07/2029 or After Major Repair/Modifications	Next Inspection Due is on or before: 06/10/2024
---	--

Issued at Al Khobar on 08/07/2024

Inspector to Bureau Veritas
Signature:



Name: Mohamed OMARA
Position: Senior Inspector



Reviewed by
Signature:



Name: Abdullah SHEHRI
Position: Operations Manager

The technical conclusions thus expressed may have to be reconsidered in light of any modifications or alterations that would invalidate the data shown in the present certificate. These conclusions would become null & void should Bureau Veritas not be kept informed of such modifications or alterations with specific reference to the present certificate.

Any person not a party to the contract pursuant to which this document is delivered may not assert a claim against Bureau Veritas for any liability arising out of errors or omissions which may be contained in said document, or for errors of judgement, fault or negligence committed by the personnel of the Society or of its Agents in the establishment or issuance of this document, and in connection with any activities for which it may provide.

This is NOT an indication that the item(s) is (are) fit for any specific purpose and does not release the manufacturer, supplier and any party from their respective duty, guarantee, obligation and/or indemnity relating to, without limitation patents, workmanship, materials, safety, performance in operation and/or reliability.



CHECKLIST OF TEST & THOROUGH EXAMINATION OF MOBILE CRANE

Cert. No.: 1697446	Date of Examination: 07/07/2024	
SECTION	CONDITION	REMARKS
1. ACCESS		
1.1 Access to the cabin/control station	Satisfactory	
1.2 Access for maintenance operation	Satisfactory	
2. CHASSIS		
2.1 Chassis	Satisfactory	
2.2 Traveling device (tire, crawler)	Satisfactory	
2.3 Outriggers	Satisfactory	
2.4 Outrigger sole (shoe or pad)	Satisfactory	
2.5 None return valve on outrigger	Satisfactory	
2.6 Locking of suspensions	Satisfactory	
2.7 Locking of outriggers rest position	Satisfactory	
3. STRUCTURE OF EQUIPMENT		
3.1 Structure, A frame	Satisfactory	
3.2 Jib, fly jib	Satisfactory	STOWED
3.3 Pendants	Not applicable	
3.4 Counter weight	Satisfactory	
4. MECHANISM		
4.1 Main Hoisting mechanism	Satisfactory	
4.2 Aux. Hoisting mechanism	Satisfactory	
4.3 Hydraulic system	Satisfactory	
4.4 Cylinders	Satisfactory	
4.5 Hoisting brake system	Satisfactory	
4.6 Limitation of the lowering speed	Satisfactory	
4.7 Telescoping mechanism	Satisfactory	
4.8 Luffing mechanism	Not applicable	
4.9 Pivoting joints	Satisfactory	
4.10 Brake of slewing motion	Satisfactory	



4.11 Traveling Brake	Satisfactory	
4.12 Guards for moving parts	Satisfactory	
4.13 Motor	Satisfactory	
4.14 Gear box	Satisfactory	
5. LIFTING SYSTEM		
5.1 Wire rope / chain	Satisfactory	
5.2 Wire/chain rope end termination	Satisfactory	
5.3 Drum, pulley, return pulley	Satisfactory	
5.4 Hooks & hook blocks	Satisfactory	
5.5 Other load handling devices	Satisfactory	
6. ENERGY		
6.1 Main switch locking	Satisfactory	
6.2 Equipment and cabling	Satisfactory	
6.3 Protection of live parts/enclosure	Satisfactory	
6.4 Lighting of the crane/site	Satisfactory	
7. CABIN / CONTROL STATION		
7.1 Structure	Satisfactory	
7.2 Visibility / windows	Satisfactory	
7.3 Heating / AC system	Satisfactory	
7.4 Seat	Satisfactory	
7.5 Fire extinguisher	Satisfactory	
7.6 Identification of the controls	Satisfactory	
7.7 Control dead man type	Satisfactory	
7.8 General stopping device by key	Satisfactory	
7.9 Emergency stop button	Satisfactory	
7.10 Level indicator	Satisfactory	
7.11 Angle Indicator	Satisfactory	
7.12 Horn	Satisfactory	
7.13 Traffic lights	Satisfactory	
7.14 Direction Indicators	Satisfactory	
8. SAFETY DEVICES		



BUREAU
VERITAS



8.1 Hoisting limiter/Anti Two Blocks	Satisfactory	
8.2 Luffing limiter	Not applicable	
8.3 Telescopic limiter	Satisfactory	
8.4 Slewing limiter	Satisfactory	
8.5 Load limiter	Satisfactory	
8.6 Level limiter	Satisfactory	
8.7 Rated capacity indicator (RCI) / ASLI	Satisfactory	
8.8 None return valve on piston	Satisfactory	
8.9 Other limiter or indicator	Satisfactory	
9. MISCELLANEOUS REQUIREMENTS		
9.1 Maker plate	Satisfactory	
9.2 Load chart	Satisfactory	
9.3 Wire rope certificate	Satisfactory	
9.4 General Safety Requirements	Satisfactory	
Notes : - Maintain proper housekeeping & preventive maintenance.		
Next Proof Load Test Due: 06/07/2029 or After Major Repair/Modifications		Next Inspection Due is on or before: 06/10/2024

Inspector to Bureau Veritas
Signature:



Name: Mohamed OMARA
Position: Senior Inspector



الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.

NDT DIVISION

Business Executive Centre, P.O.Box # 2072, Jubail -31951, Kingdom of Saudi Arabia.

Tel. : 00966 3 344 8882 / Fax :00966 3 344 8881 / Email : info@ui.com.sa / Website : www.ui.com.sa

MAGNETIC PARTICLE EXAMINATION REPORT

Report NO.:	INSPECTION DATE:	NEXT INSPECTION DATE	Page 1 of 2
JUB-3557	29-07-2024	28-07-2025	

Client: Sudhir Equipment rental company		Location: DAMMAM	
Reference Code: AWS D1.1		Procedure No. with Rev.: ASTM E -709	
Surface Temperature: 36	Surface Condition: SMOOTH	UV Light Intensity: N/A	White Light Intensity:>100FC

INSPECTION MEDIUM MAKE

Particle Mfg.	Particle P/N.	Batch No.	Color.	White Paint Mfg.:	White Paint P/N:	Batch No.
MR CHEMIE	MR76S	2310013	BLACK	MR CHEMIE	MR72	2311037

METHOD DESCRIPTION

Visible Method ☒	Dry ☐	Magnetic Current Used	Magnetic Field Direction	Demagnetization
Fluorescent Method ☐	Wet ☒	AC ☐ DC ☐ PER. ☒	Circular ☐ Longitudinal ☒	Yes ☒ No ☐ Amp.:

MPE EQUIPMENT DETAILS

Yoke Mfg.:	PARKER	Due Date of Yoke:	15-Oct-24	Portable ☒	Prod ☐	Clamps ☐
Model:	PM-50	Due Date of Lux meter	23-Aug-24	Mobile ☐	Coil ☐	Leeches ☐
Sr.No:	4806	Due Date of UV light	N/A	Stationary ☐	Yoke ☒	C.C ☐

FIELD OF APPLICATION

Piping ☐	Raw Material ☐	Bevel ☐	1st Pass ☐	Final Pass ☐
Tank/Silos ☐	Equipment ☒	Before PWHT ☐	After PWHT ☐	After Hydro ☐

Piece Description:

CRANE DETAILS: MAIN HOOK & AUX HOOK

INSPECTION PART: HOOKS

CRANE NO	QTY.	DESCRIPTION	Exam Result		Remarks
			Accept	Reject	
SRC-RT-090-023	1	MAIN HOOK			
		ID NO : SRC-RT-090-023	Accept	--	--
	1	AUX HOOK			
		ID NO : SRC-RT-090-023	Accept	--	--

Sketch/Description:

The above mentioned Hooks are tested by Magnetic Particle Test (MPT) method and No relevant indication observed. Hooks are Acceptable as per code, Refer Page 2 for Images of Testing.

Tested By: NDT Level II Technician/Inspector:	Reviewed By: UIC Rep. / Client	Approved By: Owner/Consultant/T.P.I
Name J SALMAN	Name	Name
Date 29-7-2024	Date	Date



NOT VALID WITHOUT UIC STAMP



الشركة العالمية لخدمات التفتيش المحدودة
UNIVERSAL INSPECTION CO. LTD.

NDT DIVISION

Business Executive Centre, P.O.Box # 2072, Jubail -31951, Kingdom of Saudi Arabia.
Tel. : 00966 3 344 8882 / Fax :00966 3 344 8881 / Email : info@ui.com.sa / Website : www.ui.com.sa

MAGNETIC PARTICLE EXAMINATION REPORT

Report NO.:	INSPECTION DATE:	NEXT INSPECTION DATE	Page 2 of 2
JUB-3557	29-07-2024	28-07-2025	

IMAGE-1 OF JOB ↓





IMAGE-2 OF JOB ↓



Tested By: NDT Level II

Technician/Inspector:

Name J SALMAN

Date 29-07-2024

Reviewed By:

UIC Rep. / Client

Name

Date

Approved By :

Owner/Consultant/T.P.I

Name

Date



AUTHORIZED ONLY WITH UIC STAMP

رقم هوية المالك	7016158334	تاريخ بداية الملكية					
تاريخ اصدار رخصة السير	1445-12-27	تاريخ إنتهاء رخصة السير	1448-12-27				
رقم الفرع		اسم الفرع					
رقم هوية المستخدم الفعلي		اسم المستخدم الفعلي					
نوع تسجيل اللوحة	معدات ثقيلة	معلومات اللوحة	<table><tr><td>٣٧٧٨</td><td>١١١</td></tr><tr><td>3778</td><td>AAA</td></tr></table>	٣٧٧٨	١١١	3778	AAA
٣٧٧٨	١١١						
3778	AAA						
الرقم التسلسلي	107279020	صانع المركبة	ساني				
طراز المركبة	كرين	لون المركبة	ازرق				
الحمولة	2	الوزن	54600				
سنة الصنع	2024	حالة التحفظ	غير متحفظ				
رقم الهيكل	LFCNR54D3P3200502	حالة المركبة	صالحة				
حالة الفحص الدوري	لا يوجد	تاريخ انتهاء الفحص الدوري بالهجري					
حالة التأمين	ساري المفعول	تاريخ إنتهاء التأمين	2024-11-15				
تاريخ بدء المستخدم الفعلي							



SGS INSPECTION SERVICES SAUDI ARABIA CO LTD

شركة اس جي اس لخدمات الفحص العربيّة السعوديّة المحدوده

P.O Box 0725, Jubail, Saudi Arabia - 31951
Tel : + 966133400044 / Fax : + 966133420212
Email : info@sgs.com

CUSTOMER SATISFACTION SURVEY

Blue Sticker Inspection	RFI No SGS-RFI-08956	Inspection date 07-Apr-2026
Client Sudhir Equipment Rental Co.	Report No SGS-2026-SA-285	Inspector Name Mikecle Araneta
WO No	CRM No NIL	RPO No NA

S.No	Questions	Answer	Remarks
1	Did the Service provider Co. provide the right inspector with a valid qualification card?	Yes	
2	Did the service provider Co. respond for inspection within the expected time frame?	Yes	
3	Was the inspector wearing the required personal protective equipment (PPE) during the inspection?	Yes	
4	Did the inspection conducted safely and in accordance with Aramco's standards?	Yes	

For any enquiry or concern, please contact: Inspection Dept. - ISSD Crane Inspection Unit (CIU)

InspectionDeptOIDCranelInspectionUnitCIU@Exchange.Aramco.com.sa

Client Rep Signature

Imran
Ahmed

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
1	GENERAL REQUIREMENTS					
1.1	Equipment documentation is available	ASME B30.5 Sec:5-2.1.5	✓			
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	✓			
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	✓			
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	✓			
1.5	Durable load chart is provided in an accessible location	ASME B30.5 Sec: 5-1.1.3 (b)	✓			
1.6	Work areas chart is available	G.I. 7.025 ASME B30.5 Sec 5-1.1.3(2)	✓			
1.7	Operator is certified (for the inspected crane type/ model) and licensed	G.I. 7.025 ASME B30.5 Sec: 5-3.1.1	✓			
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	SAES-B067 Sec:4.4	✓			
1.9	Crane is painted safety yellow	SAES-B067 Sec:4.4			✓	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067 Sec:4.4			✓	
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067 Sec:4.4	✓			
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5 Sec: 5-3.4.10	✓			
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5 Sec:5-1.6.1-1 Sec:5-1.6.1-2	✓			
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5 Sec:5-1.2.1	✓			
2	INSPECTION POINTS (MOBILE & CRAWLER CRANES)					
2.1	Load- holding check valve for boom is operational	ASME B30.5 Sec:5-1.3.1 (d)	✓			
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5 Sec:5-1.3.1	✓			
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5 Sec:5-1.4.1	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5 Sec: 5-1.4.2	✓			
2.5	Travel controls are properly operating/functioning	ASME B30.5 Sec: 5-1.1.3	✓			
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5 Sec: 5-1.5.1			✓	
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3			✓	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5 Sec: 5-1.5.3	✓			
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5 Sec: 5-1.6.3			✓	
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5 Sec: 5-1.7.2			✓	
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5 Sec: 5-1.7.4	✓			
2.12	Sheave guards are in place on the lower block	ASME B30.5 Sec: 5-1.7.4	✓			
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5 Sec: 5-1.7.4 (d)	✓			
2.14	All cab glazing are safety glazing material	ASME B30.5 Sec: 5-1.8.1	✓			
2.15	Verify cab doors functionality and condition	ASME B30.5 Sec: 5-1.8.1	✓			
2.16	Seat belt is fitted and in good condition	ASME B30.5 Sec: 5-1.8.1 (f)	✓			
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5 Sec: 5-1.8.2	✓			
2.18	Guard rails are fitted	ASME B30.5 Sec: 5-1.9.7			✓	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1			✓	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5 Sec: 5-1.9.1	✓			
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5 Sec: 5-1.9.1			✓	
2.23	Boom shut-off or hydraulic reliefs provided for high angle boom condition	ASME B30.5 Sec: 5-1.9.1 (d)	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.24	Boom length indicator is fitted for telescoping booms ,and is working	ASME B30.5 Sec: 5-1.9.1	✓			
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5 Sec: 5-3.2.3	✓			
2.26	Operation and accuracy of the fitted Load Indicator, RCI or RCL (compare with load chart)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.28	Outriggers and jacks are not leaking oil	ASME B30.5 Sec:5-2.1.3	✓			
2.29	Jack is in good operating condition at each outrigger	ASME B30.5 sec: ASME B30.5 Sec:5-2.1.3 (d)	✓			
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5 Sec: 5-1.9.3 (c)			✓	
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5 Sec: 5-1.9.3 (c)	✓			
2.32	Outrigger jack bolts are fully secure	ASME B30.5 Sec: 5-1.9.3 (b)	✓			
2.33	All road wheel nuts are fully secure	ASME B30.5 Sec: 5-2.1.3(b)	✓			
2.34	All tires are serviceable and without damage or excess wear	ASME B30.5 Sec: 5-2.1.3(k)	✓			
2.35	Fuel tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5 Sec: 5-2.1.3(g)	✓			
2.37	Underside of chassis shows no obvious faults	ASME B30.5 Sec: 5-2.1.3	✓			
2.38	Outrigger boxes are not cracked	ASME B30.5 Sec: 5-2.1.3	✓			
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.40	Track rod end joints are not worn and are secure	ASME B30.5 Sec: 5-2.1.3			✓	
2.41	Axle bolts and nuts are fully secure	ASME B30.5 Sec: 5-2.1.	✓			
2.42	Wheel hub oil seals are not leaking	ASME B30.5 Sec: 5-2.1.3	✓			
2.43	Brake linings are not oil contaminated	ASME B30.5 Sec: 5-2.1.3	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5 Sec: 5-2.1.3	✓			
2.45	All chassis cross members are not cracked or corroded	ASME B30.5 Sec: 5-2.1.3	✓			
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5 Sec: 5-2.1.3	✓			
2.48	Ring gear bolts are fully secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5 Sec: 5-2.1.2	✓			
2.50	Engine shows no major oil leakage	ASME B30.5 Sec: 5-2.1.3	✓			
2.51	Radiator does not leak water	ASME B30.5 Sec: 5-2.1.3	✓			
2.52	Rope is free of kinking, crushing, birdcaging, or any other damage resulting in distortion of the rope structure • No more 1 broken wire protruding from the core • There are no reductions from nominal rope diameter of more than 5% For running ropes: • No more than 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay For rotation resistance ropes • No more than 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters • Evidence of any heat damage from any cause.	ASME B30.5 Sec: 5-2.4.3	✓			
2.53	Main hoist drum mounting bolts are secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5 Sec: 5-2.1.3	✓			
2.56	Boom heel pin bushes are not worn (rock boom up and down to check this)	ASME B30.5 Sec: 5-2.1.3	✓			
2.57	Center swivel coupling pipes and hoses do not leak	ASME B30.5 Sec: 5-2.1.3	✓			
2.58	Center swivel coupling bolts are all secure	ASME B30.5 Sec: 5-2.1.3	✓			
2.59	Boom lift cylinder anchor bolts and bushings are	ASME B30.5 Sec:	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
	secure	5-2.1.3				
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3	✓			
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5 Sec: 5-1.7.3(b)	✓			
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5 Sec: 5-1.6.1(e)	✓			
3	CRANE CAB					
3.1	Horn and wind speed anemometer are working	ASME B30.5 Sec: 5-3.2.1.6	✓			
3.2	Crane level indicator is fitted and working	ASME B30.5 Sec: 5-1.9.10.6	✓			
3.3	Engine gauges and associated indicators are working	ASME B30.5 Sec: 5-2.1.3 (g)	✓			
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5 Sec: 5-1.9.12(g)	✓			
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5 Sec: 5-2.1.3 (c)	✓			
3.6	Dead end rope anchor is correctly made with a suitable wedge socket and loop-back termination	ASME B30.5 Sec: 5-1.7.3 (d)	✓			
3.7	Hook assemblies are equipped with safety latches	ASME B30.5 Sec: 5-1.7.6	✓			
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10 Sec : 10-1.8	✓			
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.10 Sec: 10-1.10.5 (b)	✓			
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10 Sec : 10-1.8	✓			
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10 Sec : 10-1.10.5 (d)	✓			
3.12	Hook is not bent or twisted	ASME B30.10 Sec : 10-1.10.5 (f)	✓			
3.13	Hook is not distorted in the throat opening • Max. allowable throat opening is 5% not to exceed 1 1/4 in. (6 mm) compared to new hook, or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (g)	✓			
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10 Sec : 10-1.10.5 (e)	✓			

SAUDI ARAMCO INSPECTION CHECKLIST	SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES	SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2	WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10 Sec : 10-1.10.5 (d)	✓			
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10 Sec : 10-1.10.5 (h)			✓	
3.17	Inoperative latch (if provided) – any damaged latch or malfunctioning latch that does not close the hook's throat	ASME B30.10 Sec : 10-1.10.5 (i)			✓	
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5 Sec:5-1.7.4	✓			
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5 Figure 5-1.7.3-1	✓			
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5 Figure 5-1.7.3-1	✓			
3.21	Reverse travel alarm is operational.	General	✓			
3.22	Turning signals and indicators are working correctly	General	✓			
3.23	Road lighting, including spotlights, are in good condition and operable	General	✓			
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	✓			
4	CRAWLER CRANE					
4.1	Track pads are undamaged and drive chain are tensioned	ASME B30.5 Sec: 5-2.1.3 (h)			✓	
4.2	Drive sockets and drive chain tumblers are serviceable	ASME B30.5 Sec: 5-2.1.3 (h)			✓	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.4	Track idlers are serviceable	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.5	Back boom stops are functioning	ASME B30.5 Sec: 5-1.9.1 (a)			✓	
4.6	Back A-Frame is in good condition	ASME B30.5 Sec: 5-2.1.3 (a)			✓	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5 Sec: 5-1.9.1 (a-2)			✓	
4.8	Power low lowering is operational	ASME B30.5 Sec: 5-1.3.2(a-1)			✓	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)			✓	

SAUDI ARAMCO INSPECTION CHECKLIST		SAIC NUMBER	ISSUE DATE	DISCIPLINE	
MOBILE / CRAWLER CRANES		SAIC-U-7007	12-Jan-23	ELEVATING/LIFTING EQUIPMENT	
PROJECT TITLE Zuluf Project Package 1&2		WBS/BI/JO NUMBER	INSPECTION COMPANY SGS Inspection Services Saudi Arabia Co Ltd		

EQUIPMENT ID NUMBER SRC-RT-090-023	EQUIPMENT DESCRIPTION/TYPE RT-H	SERIAL NO. RC0090CE0556	REPORT No.: SGS-2026-SA-285
CAPACITY (SWL) 90 t	MANUFACTURER SANY	FACILITY / LOCATION PACKAGE 1 & 2 (320 Area)	
REQUESTED INSPECTION DATE 01-Apr-2026	RFI No SGS-RFI-08956	TASK COMPLETED DATE 07-Apr-2026	EQUIPMENT OWNER Sudhir Equipment Rental Co.

ITEM	ACCEPTANCE CRITERIA	REFERENCE	PASS	FAIL	N/A	RE-INSP DATE
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5 Sec: 5-2.1.3			✓	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)			✓	
4.12	Pendant ropers are showing no broken wires (see no. 48)	ASME B30.5 Sec: 5-2.4.2			✓	
4.13	Operation of steering brakes is satisfactory	ASME B30.5 Sec: 5-1.5.3			✓	
4.14	Main machinery guarding is in place	ASME B30.5 Sec: 5-1.6.4			✓	
4.15	Main clutch is fully operational	ASME B30.5 Sec: 5-1.6.4			✓	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5 Sec: 5-1.3.2(a-1)			✓	

REFERENCE DOCUMENTS:

- 1.ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes
- 2.ASME B30.10 - 2019 Issue: Hooks
- 3.SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 4.SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 5.SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

Load Tested By (If Applicable):

Name	Signature	Date

✓ Inspected ☐ Witnessed by 3rd Party Certified Inspector:

Name	Signature	Certificate No. & Company:
Mikecle Araneta		80019274 & SGS Inspection Services Saudi Arabia Co Ltd

User Representative:

Name	Signature	Date
------	-----------	------

Imran Ahmed

07-Apr-2026

**SGS**

شركة اس جي اس لخدمات الفحص العربية السعودية المحدودة

SGS Inspection Services Saudi Arabia Co Ltd

Address : P.O Box 0725, Jubail, Saudi Arabia - 31951

Tel : +966133400044 / Fax : + 966133420212

Website : www.sgs.com

STICKER N.O. : **SGS-PASS-5939**

EQUIP S.N. : **RC0090CE0556**

EQUIP.N.O. : **SRC-RT-090-023**

EQUIP SWL : **90 t**

INSPECTION DATE : **07-Apr-2026**

NEXT INSPECTION DATE : **06-Jul-2026**

INSPECTOR NAME : **Mikecle Araneta**

SAP # : **80019274**

"S.A. INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY"

NOTE: "THIS STICKER IS INTENDED AND VALID FOR ARAMCO PREMISES AND PROJECTS ONLY"



SGS INSPECTION SERVICES SAUDI ARABIA CO LTD

شركة اس جي اس لخدمات الفحص العربيّة السعوديّة المحدوده

P.O Box 0725, Jubail, Saudi Arabia - 31951
Tel : + 966133400044 / Fax : + 966133420212
Email : info@sgs.com

Report No: SGS-2026-SA-285



LIFTING EQUIPMENT INSPECTION REPORT	RPO No NA	CRM No NIL	Inspection date 07-Apr-2026	Inspection time 10:00	Previous sticker No TUV-SUD-12360	Issued By TUV
Department / Contractor Sudhir Equipment Rental Co.	Equipment No. SRC-RT-090-023	Equipment Location PACKAGE 1 & 2 (320 Area)	Area ZULUF PROJECT	Inspection Result PASS	New Sticker No. SGS-PASS-5939	
Manufacturer SANY	Model SRC900T	Capacity 90 t	Type RT-H	Equipment Serial Number RC0090CE0556	Sticker Expiration Date 06-Jul-2026	

Above Equipment was inspected by **SGS Inspection Services Saudi Arabia Co Ltd** in accordance with applicable Saudi Aramco GI's, ASME & API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No	NOTES / DEFICIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic visual inspection and functional test been carried out as per G.I.7.030 & ASME B30.5 and found OK at the time of inspection.	
*	Boom Length: 12.2 M - 47.0 M, Five Boom Section, Max. boom angle: 80.0°.	
*	Main Hook, SWL:90 t, Weight:830 KG, Serial #: HCZ2490030 Main Hoist Diameter: 20 MM, # of Fall: 06.	
*	Aux Hook, SWL:08 t, Weight: 160 KG Aux Hoist Diameter: 20 MM, # of Fall: 01.	
*	Fly jib stowed during the inspection.	
*	Plate #: 3778 AAA (Year Model: 2024)	
*	Maintain PM service and lubricate all moving parts.	
*	Auxiliary hook serial number should be mark legible.	

User Name	Badge No.	Telephone No.	Technical Reviewer Name	SGS Inspector Name	Certificate No.	Telephone No.
Imran Ahmed	CAC15386	0572304246	aqeel hashmi	Mikecle Araneta	80019274	+966-566714453
Signature			Signature		Signature	

When re-inspection is requested, a complete copy of this report should be ready to be reviewed by the inspector.

Distribution: Original - Proponent, 1st copy - Inspection Agency, 2nd copy - Inspector

Control Report Number : SGS/JBL/M-26/292 WO:-