

OWNERSHIP CERTIFICATE

To Whom It May Concern

This is to certify that the following equipment listed below is the sole property of Sudhir Equipment Rental Company:

Equipment	Crane
Brand / Make	SANY
Asset ID	SRC-STC-080-016
Model Number	STC800T5
Serial Number	TC2080CD0620
Capacity	80 TON
Type	Sany Truck Crane
Manufacturing Year	2023

This certification is issued to confirm the ownership status of the aforementioned equipment. Sudhir Equipment Rental Company holds full legal ownership rights over the listed equipment and retains all associated benefits and responsibilities. Should there be any queries or requests for verification regarding the ownership of the mentioned equipment, please do not hesitate to contact us at : Info@sudhirrentals.com

Sincerely,

Rajesh Thakur
Plant Manager
Sudhir Equipment Rental Company



KINGDOM OF SAUDI ARABIA
MINISTRY OF INTERIOR

رخصة سيار
VEHICLES REGISTRATION

المملكة العربية السعودية
وزارة الداخلية

المالك شركة سودهير لتأجير المعدات شركة الشخص الواحد
المستخدم

هوية المالك ٧٠١٦١٥٨٣٣٤ هوية المستخدم

رقم الهيكل LFCNPG6P3P3200315

رقم اللوحة ٣٧٧٣ أ أ أ

نوع التسجيل اشغال عامة

3773 A A A

طراز المركبة كرين

ماركة المركبة سماني

حمولة المركبة ١

وزن المركبة ٤٥٨٧٠

سنة الصنع ٢٠٢٣

اللون اصفر

٣٩٣٣٩٠٢٠

الترقيم التسلسلي



بهذا نشهد بأننا أصدرنا وثيقة تأمين للمركبة الموصوف ببياناتها أدناه بموجب أحكام وشروط
تأمين المسؤولية المدنية تجاه الغير في المملكة العربية السعودية

This is to certify we issued a motor policy of below referred vehicle in
accordance with terms and conditions of Third Party Liability in Kingdom of
Saudi Arabia

Product ID A-GIGR-1-C-13-002

CERTIFICATE OF MOTOR VEHICLE

INSURANCE NO : 5/VX/31062/0/0

INSURED NAME : SUDHIR EQUIPMENT RENTAL COMPANY

MOTOR VEHICLE DETAILS :

- Registration No : AAA 3773
- Chassis No : LFCNPG6P3P3200315
- Make : Sany CRANE
- Year : 2023
- Custom Card ID :

PERIOD OF INSURANCE :

- Commencement date : 12/06/1447 (H) هجـ تاريخ الإبتداء : 12/06/1447
- Expiry date : 16/05/1448 (H) هجـ وينتهي في : 16/05/1448
- Corresponding to : From 03/12/2025 To 28/10/2026 16/05/1448 (H) 12/06/1447 (H)

Subject always to the Limits of Liability of 10,000,000 S.R. as provided in the Policy arising out of the use of the insured Motor Vehicle within Saudi Arabia .

This Certificate is deemed to be a guarantee for payment for all amounts which the Insured Owner and/or the Authorized Driver at the time of the accident shall become legally liable to pay as compensation for

- (a) Death or bodily injury sustained by any person including passengers of the vehicle
- (b) Damage to third party property outside the Insured Vehicle

وذلك ضمن حدود المسؤولية 10,000,000 رس المبينة في الوثيقة والناجمة
لإستخدام السيارة المؤمنة داخل المملكة العربية السعودية
وتعتبر هذه الشهادة كضمان لدفع كافة المبالغ التي يكون الملك المؤمن له أو
السائق المخول في وقت الحادث مسؤولين قانونا عن دفعها كتعويض عن
1. الوفاة أو الإصابة البدنية التي تحدث لأي شخص بما في ذلك ركاب
السيارة
2. تلف ممتلكات أي طرف ثالث خارج المركبة المؤمنة

SIGNED :

التوقيع :



IMPORTANT

- This certificate of Insurance and Policy is valid only for the Insured Owner and the authorized Driver at the time of Accident and is NOT transferable without prior consent of the Insurance Company.
- Any Accident must be notified to the Insurance Company as soon as possible by visiting our website <https://www.gig.sa/ar/claim-form> or by contacting us on 920008477 or visiting our outlets

ملاحظات هامة

- إن شهادة التأمين هذه صالحة فقط للمالك المؤمن له والسائق المخول له بالقيادة في حالة وقوع حادث وهي غير قابلة للتحويل بدون موافقة مسبقة من قبل شركة التأمين
- عند وقوع أي حادث يجب إخطار الشركة في أسرع وقت ممكن من خلال زيارة موقعنا الإلكتروني: <https://www.gig.sa/ar/claim-form> أو بالإتصال على الرقم 920008477 أو بزيارة أحد منافذنا



LOAD TEST WITNESS CERTIFICATION

Certificate No : ECI/SA/LT-40218/24
Rev. No.: 00

S.O.# : 1807
Date of Issue: 01-Jul-2024

COMPANY NAME : SUDHAIR RENTALS
LOCATION : SUDHIR YARD, DAMMAM
EQUIPMENT / TYPE : MOBILE CRANE / TRUCK MOUNTED
EQUIPMENT ID NO. : SRC-STC-080-016
EQUIPMENT SERIAL NO. : TC2080CD0620
MODEL : STC 800T5
CAPACITY / SWL : 80.0 t
MANUFACTURER : SANY
APPLIED STANDARD : ASME B30.5 - 2021

PART I : PRE-EXAMINATION.

PART II : PERCENTAGE OF LOAD TEST(100%)

We hereby certify that the equipment mention above was thoroughly undergone Visual Inspection and Functional test done by the competent inspector according to Engineering Corner For Inspection(E.C.I) in accordance with ASME/ANSI/API/BS Standards.

SERIAL NO	QTY	EQUIPMENT DESCRIPTION	CAPACITY(SWL)	APPLIED TEST LOAD
TC2080CD0620	1	MOBILE CRANE/TRUCK MOUNTED	80.0 t	N/A
		Load Test Configuration Boom Length: 21.9 m Radius: 10m	21.60 t	21.60 t

PART III : POST EXAMINATION.

REMARK: Found this item in good condition with adequate strength and free from apparent defects that affects safe operation at time of inspection, with provision of regular maintenance. Any modification / repair / re-installation of the mention equipment shall be re-inspected.

LOAD TEST WITNESS DATE : 01-Jul-2024



REPORT NO : 96967

*****END OF CERTIFICATE*****

INSPECTED BY : GODOFREDO

REVIEWED & APPROVED BY : QA/QC Dept

SIGNATURE :

KSA Office: Registered Saudi Aramco Vendor Registration Number10041478, Saudi Basic Industries Corporation (SABIC) Vendor number 505616, Saudi Electric Company Number 32930, Lifting Equipment Engineers Association membership (LEEA)-Cert.1876, ISO 9001:2015 Cert. 170121016621, ISO 14001:2015 Cert. 170123026621, ISO 45001:2018 Cert. 170123036621, Royal Commision: RCJ000339.

Doc. No. : ECIR-LFT-003, Issue No.: 02, Rev. No. : 001, Rev. Date : 05-FEB-2023

Page 1/1





Bureau Veritas, Saudi Arabia

8th Floor, Danah Business Tower, Olaya District, Al Khobar, Kingdom of Saudi Arabia

Tel No : +966 13 882 1071

Web : <https://middle-east.bureauveritas.com>



Report No.: 247682

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAM	Inspection Date 28/10/2025		Inspection Time 11:00	Previous Sticker	
					No.922	Issue By STANDARD ARABIA
Department / Contractor SUDHIR EQUIPMENT RENTAL CO.	Equipment Number SRC-STC-080-016	Equipment Location DMM YARD		Inspection Result Pass	New Sticker No. BV-2439	
Manufacturer SANY	Model STC800T5	Capacity 80 TON	Type Mobile Crane	Equipment Serial Number TC2080CD0620	Sticker Expiration Date 27/01/2026	

Above Equipment was inspected by **Bureau Veritas** in accordance with applicable Saudi Aramco GI's, ASME and API Standards. Deficiencies that require corrective action are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFICIENCIES / NOTES	Corrective Action Taken
1	-PERIODIC NSPECTION AND FUNCTION TEST FOR MOBILE CRANE AS PER AS S.ARAMCO GI 7.030 AND ASME B30.5 -MAIN HOOK BLOCK S/N:HCZ2380082, SWL: 80t @ 6 FALLS - AUX HOOK S/N: YM2022113001, SWL: 6.7 TON @ 1FALL - FLY JIB WAS STOWED -PLATE#2773 AAA -EQUIPMENT WAS FOUND SATISFACTORY AT THE TIME OF INSPECTION -FOLLOW PROPER PM REGULARLY	
Receiver Name : ARIF		Inspector Name : MOHAMED OMARA
Badge No.: -	Telephone No.: -	Telephone : 055 078 7628

When re-inspection is requested, a complete copy of this report should be ready review by the inspector.

SAUDI ARAMCO INSPECTION CHECKLIST				SAIC NUMBER SAIC-U-7007		ISSUE DATE 12-Jan-23		DISCIPLINE ELEVATING/LIFTING EQUIPMENT	
MOBILE / CRAWLER CRANES									
PROJECT TITLE				WBS/BI/JO NUMBER		INSPECTION COMPANY Bureau Veritas, Saudi Arabia			
EQUIPMENT ID NUMBER : SRC-STC-080-016		EQUIPMENT DESCRIPTION/TYPE : Mobile Crane			SERIAL NO. : TC2080CD0620		REPORT No.: 247682		
CAPACITY (SWL) : 80 TON		MANUFACTURER : SANY			FACILITY / LOCATION : DMM YARD				
REQUESTED INSPECTION DATE :		RFI No.	TASK COMPLETED DATE : 28/10/2025			EQUIPMENT OWNER : SUDHIR EQUIPMENT RENTAL CO.			

ACCEPTANCE CRITERIA

1.0 GENERAL REQUIREMENTS

		REFERENCE	PASS	FAIL	NA	REMARKS
1.1	Equipment documentation is available	ASME B30.5	✓			
1.2	Preventive Maintenance is established and updated records are maintained	ASME B30.5 Sec:5-2.3.1	✓			
1.3	Daily pre-operational inspection checklists are checked	GI 7.030 Para: 5.1.2	✓			
1.4	Vehicle government registration card (ISTIMARA) and Government periodic inspection are maintained and valid at all times for equipment that has a vehicle plate.	GI 7.030 Para: 7.1.2 Note:5	✓			
1.5	Durable load chart is provided in an accessible location	ASME B30.5	✓			
1.6	Work areas chart is available	ASME B30.5	✓			
1.7	Operator is certified (for the inspected crane type/model) and licensed	G.I. 7.025	✓			
1.8	A sign is posted warning the operator not to rely solely on any automatic device as a substitute for safe operating practice	G.I. 7.030	✓			
1.9	Crane is painted safety yellow	SAES-B067			✓	
1.10	Crane is painted safety yellow-and-black stripes on offshore facilities	SAES-B067			✓	

		REFERENCE	PASS	FAIL	NA	REMARKS
1.11	Rated capacity of crane is marked (Arabic & English)	SAES-B067	✓			
1.12	Fire extinguisher is in place with minimum rating 10 BC	ASME B30.5	✓			
1.13	Markings and direction of all control levers are clearly displayed	ASME B30.5	✓			
1.14	Crane backward stability is in accordance with manufacturers standard (minimum radius and no load condition)	ASME B30.5	✓			

2.0 INSPECTION POINTS (MOBILE & CRAWLER CRANES)

		REFERENCE	PASS	FAIL	NA	REMARKS
2.1	Load- holding check valve for boom is operational	ASME B30.5	✓			
2.2	Two (2) full wraps of rope remain on the drum when hook is in the extreme low position	ASME B30.5	✓			
2.3	Swing control is smoothly operating on acceleration and deceleration	ASME B30.5	✓			
2.4	Swing braking operates, as well as positive locking devices (manual and auto)	ASME B30.5	✓			
2.5	Travel controls are properly operating/functioning	ASME B30.5	✓			
2.6	Auxiliary travel controls function correctly for multiple control- station cranes	ASME B30.5	✓			
2.7	Travel brakes and locks for crawler cranes are correctly operating	ASME B30.5			✓	
2.8	Travel brakes and locks for wheel-mounted cranes are correctly operating	ASME B30.5	✓			
2.9	Power plant controls of superstructure -mounted power plant working properly	ASME B30.5	✓			
2.10	Rotation-resistant and fiber-core ropes are not used for boom hoist reeving	ASME B30.5			✓	

		REFERENCE	PASS	FAIL	NA	REMARKS
2.11	Sheave grooves have surface smoothness without any defects	ASME B30.5	✓			
2.12	Sheave guards are in place on the lower block	ASME B30.5	✓			
2.13	All sheaves can be lubricated (except permanently lubricated types)	ASME B30.5	✓			
2.14	All cab glazing's are safety glazing material	ASME B30.5	✓			
2.15	Verify cab doors functionality and condition	ASME B30.5	✓			
2.16	Seat belt is fitted and in good condition	ASME B30.5	✓			
2.17	Walking platforms and areas of structure are skid-resistance	ASME B30.5	✓			
2.18	Guard rails are fitted for crawler cranes	ASME B30.5			✓	
2.19	Fixed or telescoping bumper for boom stop is functional (if fitted)	ASME B30.5			✓	
2.20	Shock absorbing bumper for boom stop is functional (if fitted)	ASME B30.5			✓	
2.21	Hydraulic boom elevating cylinder, used as boom stop, is functional (if fitted)	ASME B30.5	✓			
2.22	Boom angle indicator is fitted, operable, and can be read from the operator station	ASME B30.5	✓			
2.23	Boom shut-off or hydraulic relief is provided for high angle boom condition	ASME B30.5	✓			
2.24	Boom length indicator is fitted for telescoping booms and is working	ASME B30.5	✓			
2.25	Anti-two-blocking devices are fitted and working (main and auxiliary)	ASME B30.5	✓			
2.26	Operation and accuracy of the fitted LMI (compare with load chart over a range of angles and radii)	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.27	LMI is fitted, operational and accurate for bool length, rated load, angle, radius, etc. (for 3 ton cranes or more)	ASME B30.5 Sec: 5-1.9.10.2	✓			
2.28	Outriggers and jacks are not leaking oil	ASME B30.5	✓			
2.29	Jack is in good operating condition at each outrigger	ASME B30.5	✓			
2.30	Each outrigger jack locking device is functional (if fitted)	ASME B30.5	✓			
2.31	No leakage from each jack seal when the crane is jacked up	ASME B30.5	✓			
2.32	Outrigger jack bolts are fully secure	ASME B30.5	✓			
2.33	All road wheel nuts are fully secure	ASME B30.5	✓			
2.34	All tyres are serviceable and without damage or excess wear	ASME B30.5	✓			
2.35	Fuel tank supports and straps are secure	ASME B30.5	✓			
2.36	Hydraulic oil tank supports and straps are secure	ASME B30.5	✓			
2.37	Underside of chassis shows no obvious faults	ASME B30.5	✓			
2.38	Outrigger boxes are not cracked	ASME B30.5	✓			
2.39	Front and rear steering cylinder anchor points and pins are secure	ASME B30.5	✓			
2.40	Track rod end joints are not worn and are secure	ASME B30.5	✓			
2.41	Axle bolts and nuts are fully secure	ASME B30.5	✓			
2.42	Wheel hub oil seals are not leaking	ASME B30.5	✓			
2.43	Brake linings are not oil contaminated	ASME B30.5	✓			
2.44	Brake hoses have not deteriorated, e.g. cracks, splits, leaks, etc.	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.45	All chassis cross members are not cracked or corroded	ASME B30.5	✓			
2.46	Transmission mounting bolts and bushings are secure	ASME B30.5	✓			
2.47	All drive shaft bolts and universal joints are not worn	ASME B30.5	✓			
2.48	Ring gear bolts are fully secure	ASME B30.5	✓			
2.49	All hydraulic hoses under chassis have not deteriorated (cracks , splits , leaks)	ASME B30.5	✓			
2.50	Engine shows no major oil leakage	ASME B30.5	✓			
2.51	Radiator does not leak water	ASME B30.5	✓			
2.52 (a)	Rope is free of damages: 1 broken wire protruding from the core Wear of 1/3 of the original diameter of outside individual wires Kinking, crushing, birdcaging or other distortion	ASME B30.5	✓			
2.52 (b)	For running ropes: Max of 6 randomly broken wires in 1 lay or 3 broken wires in 1 strand of 1 lay, For rotation resistance ropes: 2 randomly distributed broken wires in six rope diameters or 4 randomly distributed broken wires in 30 rope diameters	ASME B30.5	✓			
2.52(c)	Evidence of any heat damage from any cause Reduction below nominal diameter	ASME B30.5	✓			
2.53	Main hoist drum mounting bolts are secure	ASME B30.5	✓			
2.54	Rear telescope side and top wear pads are serviceable	ASME B30.5	✓			
2.55	Bottom and side wear pads of telescope sections are serviceable	ASME B30.5	✓			
2.56	Center swivel coupling pipes and hoses do not leak	ASME B30.5	✓			
2.57	Center swivel coupling bolts are all secure	ASME B30.5	✓			
2.58	Boom lift cylinder anchor bolts and bushings are secure	ASME B30.5	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
2.59	Swing gearbox mounting bolts are secure	ASME B30.5	✓			
2.60	Swing gearbox bottom oil seal and drive gear are in a serviceable condition (Should be well lubricated)	ASME B30.5	✓			
2.61	Wire rope clips shall be drop-forged steel of the single saddle U bolt or doubled saddle type clip for end termination.	ASME B30.5	✓			
2.62	Emergency switch / Power take off switch need to be verified	ASME B30.5	✓			

3.0 CRANE CAB

		REFERENCE	PASS	FAIL	NA	REMARKS
3.1	Horn and wind speed anemometer are working	ASME B30.5	✓			
3.2	Crane level indicator is fitted and working	ASME B30.5	✓			
3.3	Engine gauges and associated indicators are working	ASME B30.5	✓			
3.4	The warning sign stating power line required clearances is visible to the operator	ASME B30.5	✓			
3.5	Load block sheaves turn freely and are undamaged	ASME B30.5	✓			
3.7	Hook assemblies are equipped with safety latches	ASME B30.5	✓			
3.8	Hook assembly labeling and manufacturer data is clearly marked	ASME B30.10	✓			
3.9	Hook's weight is clearly marked/printed on the hook	ASME B30.10	✓			
3.10	Safe working load of hook is clearly marked on the item	ASME B30.10	✓			
3.11	Hook does not show defects such as nicks, cracks and gouges	ASME B30.10	✓			
3.12	Hook is not bent or twisted	ASME B30.10	✓			

		REFERENCE	PASS	FAIL	NA	REMARKS
3.13	Hook is not distorted in the throat opening - Max. allowable throat opening is 15% compared to new hook, or as per manufacturer recommendations	ASME B30.10	✓			
3.14	Maximum wear in the hook bowl is not exceeding 10% (compared to new hook) or as per manufacturer recommendations	ASME B30.10	✓			
3.15	Hook is not cracked, gouged or shows nicks	ASME B30.10	✓			
3.16	Hook can lock (if it is a self-locking hook)	ASME B30.10			✓	
3.17	Inoperative latch (if provided) — any damaged latch or malfunctioning latch that does not close the hook's throat	ASME B30.10 Sec : 10-1.10.5 (i)	✓			
3.18	Rope guards and locked in position with pins (hook block)	ASME B30.5	✓			
3.19	Dead end rope anchor is fitted with a lock pin (hook block)	ASME B30.5	✓			
3.20	Dead end rope anchor is correctly made with a suitable wedge socket and loop- back termination	ASME B30.5	✓			
3.21	Reverse travel alarm is operational	ASME B30.5	✓			
3.22	Turning signals and indicators are working correctly	ASME B30.5	✓			
3.23	Road lighting, including spotlights, are in good condition and operable	ASME B30.5	✓			
3.24	Dry friction brakes and clutches shall be protected against rain and other liquids such as oil and lubricants	ASME B30.5 Sec 5-1.9.8	✓			

4.0 CRAWLER CRANE

		REFERENCE	PASS	FAIL	NA	REMARKS
4.1	Track pads are undamaged	ASME B30.5			✓	
4.2	Drive sockets and tumblers are serviceable	ASME B30.5			✓	
4.3	Top and bottom swing rollers and tracks are in good overall condition (Should be well lubricated)	ASME B30.5			✓	
4.4	Track idlers are serviceable	ASME B30.5			✓	
4.5	Back boom stops are functioning	ASME B30.5			✓	
4.6	Back A-Frame is in good condition	ASME B30.5			✓	
4.7	Boom cut-out (at maximum angle) is operable	ASME B30.5			✓	
4.8	Power low lowering is operational	ASME B30.5			✓	
4.9	Boom hoist safety auxiliary ratchet / pawl lock is engaging	ASME B30.5 Sec: 5-1.3.1(c)			✓	
4.10	Boom chords and lacings are undamaged (bent)	ASME B30.5			✓	
4.11	Sheave grooves are free from surface defects that could cause rope damage.	ASME B30.5 Sec: 5-1.7.4 (a)			✓	
4.12	Pendant ropes are showing no broken wires (see 2.0.55)	ASME B30.5			✓	
4.13	Operation of steering brakes is satisfactory	ASME B30.5			✓	
4.14	Main machinery guarding is in place	ASME B30.5			✓	
4.15	Main clutch is fully operational	ASME B30.5			✓	
4.16	Main boom and hoist drum brakes are fully functional	ASME B30.5			✓	

REMARKS

--

REFERENCE DOCUMENTS:

- 1- ASME B30.5 - 2021 Issue: Mobile & Locomotive Cranes
- 2- ASME B30.10 - 2019 Issue: Hooks
- 3- SAES-B067 - 2020 Issue: Safety Identification and Safety Colors
- 4- SA GI 7.025-2018 Issue: Heavy Equipment Operator and Rigger Testing and Certification
- 5- SA GI 7.030 - 2023 Issue: Inspection and Testing Requirements for Elevating/Lifting Equipment

Signature

Inspected / Witnessed by 3rd Party Certified Inspector

Name MOHAMED OMARA

Signature



Certificate No. 80019106

Company Bureau Veritas

User Representative

Name ARIF

Signature



Date 29/10/2025



Sticker No:
BV-2439

Bureau Veritas

Tel.: + 966 013 822
1071
Fax: + 966 013 822
1072
Al Khobar, Saudi
Arabia



EQUIP .S.N: TC2080CD0620

EQUIP .NO : SRC-STC-080-016

EQUIP.SWL : 80 TON

INSPECTION DATE : 28/10/2025

NEXT INSPECTION DATE :27/01/2026

INSPECTOR NAME: MOHAMED OMARA

SAP # 80019106

SA INSPECTION DEPARTMENT APPROVED CONTRACTOR AGENCY