



مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



Certificate of Thorough Visual and Functional Examination of Spider Crane

Certificate No: JHI-4872-25-C3

Date of Inspection: 23-10-2025

Name of the owner company: SUDHIR EQUIPMENT RENTAL COMPANY		Location: YANBU - KSA	
Equipment Details: SPIDER CRANE			
Reference Regulations: SASO-ISO-20297-1,BS EN 7121-2-4:2013		Maker & Date of Manufacture: XCMG & 2021	
Traffic Plate No: N/A	Owner No. SSC3-001	Model No. MC305CRME-3	Crane Serial No. D3192
Sticker No. 009815	Hook Block Capacity. 1.45t	SWL. 3.0 ton	

Max rated capacity – 3.0 ton

Description of Test: Outriggers fully extended

Wire rope Dia : 8.0mm

Part Line : 4

Note: Visual and Functional Test Were Satisfactory.

Date of Last Examination

N/A

Date of Next Examination

22-10-2026

RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory

IMAGES FOR SPIDER CRANE



*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: M.SHEIK ALLAVUDEEN

Authorized Signature:

Surveyor's Name: RIFAY

Surveyor's Signature:

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh, Al Malaz Dist. Po. 12831
CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com

Annex to Certificate of Test and Thorough Examination

Certificate No.: JHI-4872-25-C3

Date of Inspection: 23-10-2025

No.	DESCRIPTION	CONDITION
1.	Safe load indicator	Satisfactory
2.	Duty chart	
3.	Boom structure	Satisfactory
4.	Hoist wire ropes	Satisfactory
5.	Level indicator	Satisfactory
6.	Boom lift cylinder	Satisfactory
7.	Outriggers	Satisfactory
8.	Rope termination	
09.	Crane control	Satisfactory
10.	Swing machinery	Satisfactory
11.	Hydraulic system	Satisfactory
12.	Electrical system	Satisfactory
13.	Fire extinguisher	Satisfactory
14.	Steering & brakes	Satisfactory
15.	Carrier	
16.	Maintenance/repair	Satisfactory
COMMENTS: At the time of inspection, the equipment was found satisfactory		

Surveyor's Name: RIFAY



Surveyor's Signature: