



CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)
09-Nov-2025	11-Nov-2025	TUR-L-0432	TUR/001324
Next Examination Due Date	Date of last thorough Examination	Reference Standard	Order No
08-May-2026	N/A	ASME B30.23	W.O-TUR-LIF-11112025-001
Name and Address of Customer		Address of Examination	
Sudhir Equipment Rental Company WAS, AL-TURAIIF		AL-TURAIIF, Kingdom of Saudi Arabia	
Description and identification of the equipment		Equipment ID	Safe Working Load
MANLIFT Type: Articulating Boom Lift Manufacturer : JLG Model : 800 AJ Gross Weight : 15980 kg Horizontal Outreach: 51 ft Max Platform Height: 80 ft Year of Manufacturer : 2017		ID: S26AJ-152 Serial No. : 0300236861	230 kg
Is this first Examination after installation or assembly at new site or location?		NO	Was the Examination carried out within an interval of 6 months? YES
Has the equipment been installed correctly?		YES	Was the Examination carried out within an interval of 12 months? NO
In accordance with an Examination Scheme?		NO	After the occurrence of exceptional circumstances? NO
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
N/A			
Is the above an existing or imminent danger to persons?			NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)			NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
N/A			
Particulars of any tests carried out as part of the examination. And standard applied.			
Visual Inspection And Functional Check According to ASME B30.23			
Load Test(s): N/A			
IS THIS EQUIPMENT SAFE TO OPERATE?		YES	
Name and Signature of the person issue this certificate.		Name and Signature of the person authenticating this certificate.	
Name: MOHAMED ALAAELDIN		Name: MOHAMED NOORUL AMEEN	
Signature:		Signature:	
Comments: At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.			



Checklist

Certificate/Report Number: TUR-L-0432
Sticker Number(s): TUR/001324

INSPECTION POINTS	Pass	Fail	N/A	INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection Certificate	☒	☐	☐	Air filter	☒	☐	☐
Last Third-party inspection sticker	☒	☐	☐	Steering oil and steering system/Joystick	☒	☐	☐
Operator Iqama/License/ Third Party	☒	☐	☐	Brakes and brake system (including parking brake)	☒	☐	☐
Tire and air pressure	☒	☐	☐	Fuel level and check for leaks in fuel system	☒	☐	☐
Level Indicators	☒	☐	☐	Coolant	☒	☐	☐
Lights (include beacon light)	☒	☐	☐	Radiator and hoses	☒	☐	☐
Horn/ Reverse alarm	☒	☐	☐	Fan belts and pulleys	☒	☐	☐
Electrical switches and gauges	☒	☐	☐	Hoses and fittings	☒	☐	☐
Emergency lowering system	☒	☐	☐	Battery	☒	☐	☐
Safety signs, labels and stickers	☒	☐	☐	Air Conditioner/Heater	☒	☐	☐
Platform condition	☒	☐	☐	Boom lift, Boom extension & retraction (deflection)	☒	☐	☐
Greasing & lubrication of boom	☒	☐	☐	Lever controls & pedals	☒	☐	☐
Safe Access & Egress	☒	☐	☐	Slewing mechanism	☒	☐	☐
Fire extinguisher in good condition & valid	☒	☐	☐	Boom cylinder/Lifting cylinder	☒	☐	☐
Engine oil level, check system for damage, leak	☒	☐	☐	Identification & SWL Marking	☒	☐	☐
Hydraulic oil level, check system for leaks	☒	☐	☐	Hydraulic system	☒	☐	☐
Transmission oil	☒	☐	☐	Operation	☒	☐	☐

Comments/Remarks:

Reference Documents:

ASME B30.23

Inspected & witnessed by: MOHAMED ALAAELDIN

Signature:



Approved by: MOHAMED NOORUL AMEEN

Signature:

