



CERTIFICATE OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Certificate	Certificate number	Sticker Number(s)
26-Jan-2026	26-Jan-2026	TUR-L-0711	TUR/002150
Next Examination Due Date	Date of last thorough Examination	Reference Standard	Order No
25-Jan-2026	N/A	ASME B30.23	W.O-TUR-LIF-26012026-004
Name and Address of Customer		Address of Examination	
BRANCH OF SUDHIR GENSETS LIMITED AL-TURAIIF		WAS,AL-TURAIIF	
Description and identification of the equipment		Equipment ID	Safe Working Load
MANLIFT Make : JLG Model : 860SJ Gross vehicle weight : 17043 kg Year of manufacture : 2024		ID NO : S28SJ-1616 Serial NO : B300027587	227 KG
Is this first Examination after installation or assembly at new site or location?	YES	Was the Examination carried out within an interval of 6 months?	NO
Has the equipment been installed correctly?	YES	Was the Examination carried out within an interval of 12 months?	YES
In accordance with an Examination Scheme?	YES	After the occurrence of exceptional circumstances?	NO
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
N/A			
Is the above an existing or imminent danger to persons?			NO
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when)			NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
N/A			
Particulars of any tests carried out as part of the examination. And standard applied.			
Visual Test and Functional Check According to ASME B30.23			
Load Test(s): N/A			
IS THIS EQUIPMENT SAFE TO OPERATE?		YES	
Name and Signature of the person issue this certificate.		Name and Signature of the person authenticating this certificate.	
Name: NOUFAL SHEREEF		Name: MOHAMED NOORUL AMEEN	
Signature: 		Signature: 	
			
Comments: At the time of inspection, the equipment was found satisfactory and free from any defects or damage and found safe for use. UNIVERSAL INSPECTION CO. LTD. holds no responsibility for any damage occurring after the inspection date due to improper use pertaining to operation as per the manufacturer's manual, maintenance, and servicing. This Thorough Examination was within the limits of Client's specifications.			



Checklist

Certificate/Report Number: TUR-L-0711

Sticker Number(s): TUR/002150

INSPECTION POINTS	Pass	Fail	N/A	INSPECTION POINTS	Pass	Fail	N/A
Last Third-party inspection sticker	☒	☐	☐	Transmission oil	☒	☐	☐
Tire and air pressure	☒	☐	☐	Air filter	☒	☐	☐
Lights (include beacon light)	☒	☐	☐	Fuel level and check for leaks in fuel system	☒	☐	☐
Reverse alarm	☒	☐	☐	Hoses and fittings	☒	☐	☐
Electrical switches and gauges	☒	☐	☐	Battery	☒	☐	☐
Emergency System	☒	☐	☐	Boom lift, Boom extension & retraction (deflection)	☒	☐	☐
Platform condition	☒	☐	☐	Slewing mechanism	☒	☐	☐
Greasing & lubrication of boom	☒	☐	☐	Boom cylinder/Lifting cylinder	☒	☐	☐
Overload Indicator	☒	☐	☐	Identification & SWL Marking	☒	☐	☐
Fire extinguisher in good condition	☒	☐	☐	Hydraulic system	☒	☐	☐
Engine oil level, check system for damage, leak	☒	☐	☐	Outrigger Jacks	☒	☐	☐
Hydraulic oil level, check system for leaks	☒	☐	☐	Operation	☒	☐	☐

Comments/Remarks:

Reference Documents:

ASME B30.23

Inspected & witnessed by: NOUFAL SHEREEF

Signature:



Approved by: MOHAMED NOORUL AMEEN

Signature: