




مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



Certificate of Thorough Visual and Functional Examination of  
Manlift (MEWP)

Certificate No: JHI-2544-25-C3

Date of Inspection: 14-05-2025

Name of the owner company:  
SUDHIR EQUIPMENT RENTAL COMPANY

Location:  
AMALA - KSA

Equipment Details: MOBILE ELEVATING WORK PLATFORM – TELESCOPIC BOOM LIFT (MEWP)  
Type: DIESEL POWERED TELESCOPIC BOOM PLATFORM LIFT

Reference Regulations:

Maker & Date of Manufacture:

BS EN 280-1 & 2-2022 & SASO GSO EN 280

JLG & 2024

Traffic Plate No./ ID

Owner No.

Model No.

Chassis No. / Serial No.

N/A

S28SJ-1722

860SJ

B300027799

Sticker No:

Max. Platform Height.

Max. Horizontal Reach.

007870

26.2m

N/A

Max. Rated Capacity(SWL): 227Kg(2 Persons )+ (Equipment)

Description of Test:

Note: Visual and Functional Test Were Satisfactory.

Date of Last Examination

Date of Next Examination

16-11-2024

13-11-2025

RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory.

IMAGES FOR MANLIFT



\*Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: M.SHEIK ALLAVUDEEN

Surveyor's Name: ZEESHAN MAQSOOD

Authorized Signature:

Surveyor's Signature:

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to release any designer, manufacturer, seller, supplier, importer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor the Engineer be liable for any injury or damage to any person or property occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person or party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may be used. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damages/losses associated to the equipment/material

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh, Al Malaz Dist. Po. 12831  
CR No: 1010927177, Tel: 0112334900, Email: [info@jhinspection.com](mailto:info@jhinspection.com), [www.jhinspection.com](http://www.jhinspection.com)

# Annex to Certificate of Thorough Examination

Certificate No.: JHI-2544-25-C3

Date of Inspection: 14-05-2025

| No. | DESCRIPTION                      | CONDITION    | REMARKS |
|-----|----------------------------------|--------------|---------|
| 1.  | EQUIPMENT DOCUMENTS              | SATISFACTORY |         |
| 2.  | IDENTIFICATION ON CONTROL LEVERS | SATISFACTORY |         |
| 3.  | REFLECTIVE TAPE AND MARKINGS     | SATISFACTORY |         |
| 4.  | WORKING PLATFORM                 | SATISFACTORY |         |
| 5.  | ELECTRICAL SYSTEM                | SATISFACTORY |         |
| 6.  | HYDRAULIC SYSTEM                 | SATISFACTORY |         |
| 7.  | TYRES & WHEELS / TRACKS          | SATISFACTORY |         |
| 8.  | POWER UNIT CONTROL PANAL – UPPER | SATISFACTORY |         |
| 9.  | POWER UNIT CONTROL PANAL – LOWER | SATISFACTORY |         |
| 10. | OVER LOAD WARNING                | SATISFACTORY |         |
| 11. | EMERGENCY DESCENT                | SATISFACTORY |         |
| 12. | BRAKES                           | SATISFACTORY |         |
| 13. | BATTERY CONDITION                | SATISFACTORY |         |
| 14. | HORNS                            | SATISFACTORY |         |
| 15. | FIRE EXTINGUISHER                | SATISFACTORY |         |
| 16. | OVER ALL BODY CONDITION          | SATISFACTORY |         |
| 17. | GUARD RAILS                      | SATISFACTORY |         |
| 18. | MAINTENANCE RECORDS              | SATISFACTORY |         |

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: **ZEESHAN MAQSOOD**



Surveyor's Signature: