



BUREAU
VERITAS

BV No. 0108402

LIFTING EQUIPMENT INSPECTION REPORT	Area HAWTHA	Inspection Date MARCH 06, 2023	Inspection Time 9:00	Previous Sticker No. 5526 Issued By Zamil
Department / Contractor SUDHAR	Equipment Number S20AG-410	Equipment Location R36-218	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-6050
Manufacturer GENSE	Model Z-62/40	Capacity 227KG	Type MEWP	Equipment Serial Number Z62D-209
				Sticker Expiration Date SEP 05, 2023

Above Equipment was inspected by Bureau Veritas in accordance with applicable Saudi Aramco GI's ASME and API Standards. Deficiencies that require corrective actions are listed below. Specific repairs to correct each deficiency should be noted in the corrective action taken column.

No.	DEFECIENCIES	CORRECTIVE ACTION TAKEN
*	Periodic Inspection was overdue test per	
	Beam SUPPORTED elevating work platform	
	AS PER S. ARAMCO GTF-03, PART 92.5	
	"PASS"	
*	Follow PREPARED PM.	

RECEIVER NAME: P. Razak	SIGNATURE: [Signature]	INSPECTOR NAME: M. [Signature]
BADGE#:	TELEPHONE No.:	TELEPHONE No.: 18009

When re-inspection requested, a complete copy of this report should be ready review by the inspector.

Distribution: Original-Proponent, 1st Copy-2nd Copy - Inspector Agency