



Previous Sticker
No. 21-7754 Issued By R

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. 21-7754 Issued By BU
	SALMON	SEP 27, 2023		12:00	
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHAR	SIBAT-415	KOLIN		☒ Pass ☐ Fail	BU-21-9573
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	S20AJ	5000 LB	MEWP	E300005184	MARCH 26, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic inspection AND Function test for Beam supported elevating work platform. AS PER AS S. O. RANCO G57.03c, ANSI 92.5 "ROSS"	

RECEIVER NAME: ARIF SIGNATURE: [Signature] INSPECTOR NAME: Mono
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 8-1966