



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY (REVISION 2)

Date of thorough examination : 03-07-2025		Date of issue : 03-07-2025		Report No. : ESICO-LFT-R25-4639	
Name & Address of employer		Location		Sticker No	
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh		6291	
Standards		SASO ISO EN 280			
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name	
S20AG-427 OR Z62D-350	MAN LIFT TYPE: ARTICULATED MODEL:600AJ Max.platform height: 60ft Max.horizontal reach: 36.3ft Max.wind speed:12.5m/s Max.manual force:400N Max. occupation person : 2	RATED LOAD: 227KG	2018	GENIE	
Is this the first examination after installaton or assembly at a new site or location?		Yes		No	
If the answer to the above question is YES, has the equipment been installed correctly?		Yes		No	
Was the examination carried out within an interval of?		- 6 Months			
In accordance with an examination scheme?		Yes		No	
After the occurence of exceptional circumstances?		Yes		No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE					
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?				N/A	
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)				Yes by : N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A					
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE					
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory					



For confirmation scan QR code
search with report number : **ESICO-LFT-R25-4639**



Safe to operate

Next Inspection : 02-01-2026

Inspected by : Mohamed Askar Ali

