



BUREAU
VERITAS

BV No. 239236

LIFTING EQUIPMENT INSPECTION REPORT	Area RAS ARKHAIR	Inspection Date FEB 11, 2024	Inspection Time 10:30	Previous Sticker No. BV-21-8644 Issued By [Signature]
	Department / contractor SHO AIR	Equipment Number S385JP-441	Equipment Location MOP	Equipment Result ☒ Pass ☐ Fail
Manufacturer JLG	Model 1200SJP	Capacity 5000LBS	Type MEWP	Equipment Serial Number 0300226980
				New Sticker No. BV-23-0893
				Sticker Expiration Date AV 6/10/2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection was function test for	
	Beam supports clearing work platform	
	As per AS S 1900 6.3.1 and 6.3.2	
	Pass	

RECEIVER NAME: [Signature] SIGNATURE: [Signature] INSPECTOR NAME: [Signature]
 BADGE#: TELEPHONE NO.: TELEPHONE NO.: [Signature]