

INSPECTION CERTIFICATE

SPIDER BOOM LIFT

CLIENT NAME : SUDHIR EQUIPMENT RENTAL CO		WORK ORDER : WR-YAS-333	
EQUIPMENT DESCRIPTION : DIESEL POWERED SPIDER BOOM LIFT WITH 26 METER BOOM AND THE CAPACITY OF 230 KG		CERTIFICATE NO : YAS-CRT-1187	
		STICKER NO : 13025	
DATE OF INSPECTION : 30-Mar-2026		NEXT INSPECTION DUE : 29-Sep-2026	
PREVIOUS INSPECTION : 06-Oct-2025		PREVIOUS INSPECTION DETAILS : YAS-CRT-622	
MANUFACTURER : JLG		MODEL/TYPE : X26JP	
SERIAL NO : C170001316		OWNER ID : S26SPJ-448	
CHECKLIST NO. : 0966		MANUFACTURED YEAR : 2017	
TYPE OF INSPECTION : PERIODIC AND FUNCTIONAL INSPECTION		LOCATION : RIYADH	
REFERENCE STANDARDS : BS EN 280-1:2022			
CAPACITY / SWL:	230 KG		
NO OF PERSONS:	2 PERSON+80 KG EQUIPMENT		
TEST LOAD:	N/A		
MAX HORIZONTAL REACH:	132.75 M		
PLATFORM HEIGHT:	20.2 M		
OUTRIGGER:	SATISFACTORY		
Is this the first examination after installation or assembly at a new site or location ?	☐ Yes ☒ No	Within an interval of Months?	☒ 6 ☐ 12
If the answer to the above question is YES has the equipment been installed correctly ?	☐ Yes ☒ No	In accordance with an examination scheme ?	☐ Yes ☒ No
After the occurrence of exceptional circumstances ?		☐ Yes ☒ No	
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)		NONE	
Is the above a defect which is of immediate danger to persons		☐ Yes ☒ No	
Is the above a defect which is not yet but could become a danger to persons:(If YES state the date by when)		NONE	
Particulars of any tests carried out as part of the examination: (If none state NONE)		NONE	
RESULT:	☒ PASS ☐ FAIL	IS THIS EQUIPMENT FIT FOR PURPOSE?	☒ Yes ☐ No
REMARKS/RECOMMENDATION THIS IS TO CERTIFY THAT THE SPIDER BOOM LIFT HAS BEEN FUNCTIONALLY INSPECTED IN ACCORDANCE WITH INTERNATIONALLY RECOGNISED STANDARDS ON THE INSPECTION DATE. THE EQUIPMENT IS FREE FROM EXTERNAL DAMAGE, AND THE EQUIPMENT IS FOUND TO BE IN SATISFACTORY CONDITION.			
Date Of Report: 30/3/2026			

Approved By : BELAL MOHAMMED

Authorized Inspector : AHAMED

WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187
WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187
WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187



WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187
WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187
WORKORDER NO : WR-YAS-333
CERTIFICATE NO : YAS-CRT-1187

Note : This certificate becomes void if the equipment is altered, repaired, or modified without authorization. The equipment owner is solely responsible for safe operation and maintenance. The company accepts no liability for damages or failures arising from negligence, poor maintenance, or conditions not detectable during routine inspection.