





BV No. 237172

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	DORMAN	OCT 02, 2023		14130	No. 5262 Issued By RV
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SINAI JR	S435JP-456	DMM YARD		☒ Pass ☐ Fail	80-21-9581
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	13505JP	5000 LB	MEWP	0300269512	APRIL 01, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
X	Periodic Insulation and Function test for Boom supported Elevating work platform As per AS 3081.6 G170.30 AMS 192.5 "PASS" 	
RECEIVER NAME: <u>ARJH</u> SIGNATURE: <u></u> INSPECTOR NAME: <u>M. J. Jones</u>		
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: <u>80049606</u>		