



BV No. 235627

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	RAJAKHAR	MAY 09, 2023		13:30	No. 21-6449 issued By BV
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUDHIR	S385JP-467	MYDP		☒ Pass ☐ Fail	BV-21-9611
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
JLG	1200 SJP	500LBS	MEWP	0300235512	NOV 08, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Periodic inspection and function test for Beam supported Clevises were not done AS per AS SARANC GJ7.0 3410-8592.5	
	Pass	

RECEIVER NAME: THASSEN SIGNATURE: [Signature] INSPECTOR NAME: [Signature]
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 180-0000