



Previous Sticker
No. 21-8198 Issued By RL

LIFTING EQUIPMENT INSPECTION REPORT	Area R05 R2KAWR	Inspection Date OCT 11, 2023		Inspection Time 13:30	Previous Sticker No. 21-8198 Issued By RV
	Department / contractor SUDAR	Equipment Number S26AJ-483	Equipment Location MYOP	Equipment Result ☒ Pass ☐ Fail	New Sticker No. RV-21-9715
Manufacturer JLG	Model 800AJ	Capacity 5000BS	Type MEWP	Equipment Serial Number 0300236060	Sticker Expiration Date APRIL 10, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for Beam supported (ceiling) work not done. As per S-0006 G 6.7.03a MS1925 PASS	

RECEIVER NAME: ABR SIGNATURE: [Signature] INSPECTOR NAME: 11010101

BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 80019106