



BUREAU
VERITAS

BV No. 235210

LIFTING EQUIPMENT INSPECTION REPORT	Area DAMMAN	Inspection Date APRIL 04, 2023	Inspection Time 12:00	Previous Sticker No. 21-5663 Issued By BV
Department / contractor SUDHAR	Equipment Number S2856-489	Equipment Location DMM YARD	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-7761
Manufacturer GENIE	Model S85	Capacity 227KG	Type MEWP	Equipment Serial Number S85D-710
				Sticker Expiration Date OCT 03, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic inspection and function test for	
	Beam support elevating work platform.	
	As per AS 5687.6 G5703, 10819.5	
	Pass	

RECEIVER NAME: THAJEER	SIGNATURE: [Signature]	INSPECTOR NAME: M. Al-Murad
BADGE#:	TELEPHONE NO.:	TELEPHONE NO.: 180009