



شركة مساندة الإعمار للفحص Emaar Support Inspection Co.

6888, King Faisal Bin Abdul Aziz St, Ad Danah, Ras Tannurah, Saudi Arabia 32817

Tel : +966 507259023, +966 136670779, 055 8889186, 050 0484444

Email : info@esico.com.sa Website : www.esico.com.sa C.R : 2054100036

CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY (REVISION 2)

Date of thorough examination : 08-07-2025	Date of issue : 08-07-2025	Report No. : ESICO-LFT-R25-4653
---	----------------------------	---------------------------------

Name & Address of employer		Location	Sticker No	Standards
SUDHIR EQUIPMENT RENTALS COMAPNY		Riyadh	6305	SASO ISO EN 280
Equipment Identification No	Equipment Description	Safe Working Load(s)	Date of Manufacture	Manufacturer Name
SG12SL-514 OR GS90D-687	SCISSOR LIFT TYPE: DIESEL FUEL MODEL: GS3390 Nominal power: 48.7hp/36.3kW Max Working Height 39 ft Max.number of occupatans: 7 Max.wind speed: 28/mph	RATED LOAD: 1134 KG	2017	GENIE

Is this the first examination after installaton or assembly at a new site or location?	Yes ☐ - ☐ No ☒	Was the examination carried out within an interval of?	- 6 Months
If the answer to the above question is YES, has the equipment been installed correctly?	Yes ☐ - ☐ No ☐	In accordance with an examination scheme?	Yes ☒ No ☐
		After the occurence of exceptional circumstances?	Yes ☐ - ☐ No ☒

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE	
Is the above an existing or imminent danger to persons, Note: This is a reportable defect?	N/A
Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)	Yes by : N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A	
Particulars of any tests carried out as part of the examination (if none state NONE) : NONE	
Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory	



For confirmation scan QR code
search with report number : ESICO-LFT-R25-4653

☒ Safe to operate

Next Inspection : 07-01-2026

Inspected by : Mohamed Askar Ali

