




Previous Sticker
No. 21-2908 Issued By *Bu*

LIFTING EQUIPMENT INSPECTION REPORT	Area JUBA52	Inspection Date MAY 01, 2023		Inspection Time 14:30	Previous Sticker No. 21-2908 Issued By Bu
	Department / contractor SUAH5R	Equipment Number S28 S6-S21	Equipment Location VEDWA	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BU-21-6377
Manufacturer GENIE	Model S-85	Capacity 227KG	Type MFMP	Equipment Serial Number S850-1330	Sticker Expiration Date OCT 31, 2023

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
x	Periodic inspection and function test for Beam supported Clevises were met for AS per AS 3086 G17.3 or AS192.5	
		

RECEIVER NAME: THAS GER SIGNATURE: [Signature] INSPECTOR NAME: M. [Signature]
BADGE#: TELEPHONE NO.: TELEPHONE NO.: 18-0009