

BV No. 237216

LIFTING EQUIPMENT INSPECTION REPORT	Area JAFORS	Inspection Date OCT 19 2023		Inspection Time 13:00	Previous Sticker No. 21-6379 Issued By R
Department / contractor SUDAIR	Equipment Number S28SJ-S26	Equipment Location Sine Hydro		Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-21-9724
Manufacturer JLG	Model 860SJ	Capacity 5000LBS	Type MEWP	Equipment Serial Number B300002720	Sticker Expiration Date APR 21 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's ,ASME And API Standard Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column

[illegible]

When re-inspection requested, a Complete Copy of This Report Should Be Ready For Review By The Inspector.

Distribution: Original-Proponent, 1st Copy - second 2nd Copy - Inspector Agee