

## CERTIFICATE OF THOROUGH EXAMINATION AND / OR TEST OF LIFTING APPLIANCE OR ACCESSORY

|                                                                                                                                                                        |                                                                                                                                                           |                                                                   |                     |                                        |                 |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------|---------------------|----------------------------------------|-----------------|
| Date of thorough examination : 30-06-2025                                                                                                                              |                                                                                                                                                           | Date of issue : 30-06-2025                                        |                     | Report No. : <b>ESICO-LFT-R25-4629</b> |                 |
| Name & Address of employer                                                                                                                                             |                                                                                                                                                           | Location                                                          |                     | Sticker No                             | Standards       |
| SUDHIR EQUIPMENT RENTALS COMAPNY                                                                                                                                       |                                                                                                                                                           | Riyadh                                                            |                     | 6281                                   | SASO ISO EN 280 |
| Equipment Identification No                                                                                                                                            | Equipment Description                                                                                                                                     | Safe Working Load(s)                                              | Date of Manufacture | Manufacturer Name                      |                 |
| S22SG-542 OR S60D-1384                                                                                                                                                 | MAN LIFT<br>MODEL: S65<br>Max.allowable side force: 400N<br>Max.wind speed: 12.5m/s<br>Nominal power: 48hp Power : 36kW<br>Max.work platform height: 65ft | RATED WORK LOAD: 227 KG                                           | 2018                | GENIE                                  |                 |
| Is this the first examination after installaton or assembly at a new site or location?                                                                                 |                                                                                                                                                           | Was the examination carried out within an interval of? - 6 Months |                     |                                        |                 |
| <div>Yes</div> <div>-</div> <div>No</div> <div>✗</div>                                                                                                                 |                                                                                                                                                           | <div>Yes</div> <div>✓</div> <div>No</div> <div>-</div>            |                     |                                        |                 |
| If the answer to the above question is YES, has the equipment been installed correctly?                                                                                |                                                                                                                                                           | In accordance with an examination scheme?                         |                     |                                        |                 |
| <div>Yes</div> <div>-</div> <div>No</div> <div>-</div>                                                                                                                 |                                                                                                                                                           | <div>Yes</div> <div>✓</div> <div>No</div> <div>-</div>            |                     |                                        |                 |
|                                                                                                                                                                        |                                                                                                                                                           | After the occurence of exceptional circumstances?                 |                     |                                        |                 |
|                                                                                                                                                                        |                                                                                                                                                           | <div>Yes</div> <div>-</div> <div>No</div> <div>✗</div>            |                     |                                        |                 |
| Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (if none state NONE) : NONE             |                                                                                                                                                           |                                                                   |                     |                                        |                 |
| Is the above an existing or imminent danger to persons, Note: This is a reportable defect?                                                                             |                                                                                                                                                           |                                                                   |                     |                                        | N/A             |
| Is the above a defect which is not yet could become a danger to persons (if YES state the date by when)                                                                |                                                                                                                                                           |                                                                   |                     | Yes by : N/A                           |                 |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above : N/A                                                                  |                                                                                                                                                           |                                                                   |                     |                                        |                 |
| Particulars of any tests carried out as part of the examination (if none state NONE) : NONE                                                                            |                                                                                                                                                           |                                                                   |                     |                                        |                 |
| Observation/additional comments relative to this thorough examination : Visual and functions checks conducted at the time of inspection machine was found satisfactory |                                                                                                                                                           |                                                                   |                     |                                        |                 |



For confirmation scan QR code  
search with report number : ESICO-LFT-R25-4629



✓ Safe to operate

Next Inspection : 29-12-2025

Inspected by : Mohamed Askar Ali

