

CERTIFICATE OF INSPECTION - MANLIFT

Certificate No.	RY-26/103025	Field Inspection Report	53687
Inspection Date	March 15, 2026	Issue Date	March 15, 2026
Inspection Type	Thorough	Next Inspection Date	September 14, 2026
Equipment Owner	Sudhir Rental Equipment		
Work Location	Exit 18, Riyadh, Kingdom of Saudi Arabia		
Standard Reference	SASO GSO EN 280 – BS EN 280-1:2022- ISO 18893:2024		
Manufacturer Name	JLG	Year of Manufacture	2018
Serial No. / VIN	0300235497	Registration Plate No.	N/A
Model No.	800AJ	Company No.	S26AJ-545
Sticker No.	82519	Last Inspection Date	N/A
Description & Remarks			Rated Capacity
Max. Platform Height: 80 ft. Visual inspection and functional tests were Satisfactory and free from apparent defects. Any major repair will cause the cancelation of this certificate & equipment needs to be inspected again.			500 LBS
Reason For Examination			B
A 3-months	B 6-months	C 12-months	D Written Scheme
E Exceptional Circumstances		F Installation	
Result	Accepted ☒		Rejected ☐
Name & address of employer's person making and authenticating this report:			
Mr. Muhammad			


Declaration: I/We hereby declare that the above information is correct, and the equipment has been thoroughly inspected as far as possible in accordance with manufacturer/standard and found to be free from any apparent defect.

Inspected by


Muhammad Sajjad
Equipment Inspector



Approved by


Shahid Javed Muhammad
Technical Manager



Disclaimer: Tove Leeds is not liable for any failure, damage caused by misuse, improper installation, poor maintenance, environmental conditions and user errors etc.

Description	Condition	Corrective Actions
General Appearance, Unauthorized Modifications	Satisfactory	
Emergency Stop Button	Satisfactory	
Platform, Top rail/Mid rail, Gate, Chain & Latches	Satisfactory	
Pothole Protection system	Satisfactory	
Battery Fluid levels, Connections.	Satisfactory	
Hydraulic Fittings & lines & Scissors	Satisfactory	
Fire Extinguisher	Satisfactory	
Operating System, Electrical System, Alarm	Satisfactory	
Condition of Basket, Emergency Landing	Satisfactory	
Lighting System & Warning Lights, Beacon Light	Satisfactory	
Slewing System, Condition of Boom	Satisfactory	
Tyre & Wheel, Brakes System	Satisfactory	
Under Carriage Appearance, Emergency landing	Satisfactory	
Temp. Walkway Platform General Appearance Walking and Working Surfaces Guard Rails, Hinges, Wire Ropes Means of Access Any cracks, depressions, potholes Anchorage and Support Attachment to Manlift Bolts, Nuts and Clamps	Satisfactory	
Operation/Instruction Manual	Satisfactory	
Maintenance	-	Conduct regular planned preventive maintenance and maintain maintenance logs properly.

Inspected by


Muhammad Sajjad
Equipment Inspector



Approved by


Shahid Javed Muhammad
Technical Manager



Chartered Safety and
Health Practitioner

QMHCR
Registered Consultant