




LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker
	TAMAJOB	DEC 31, 2023		10:30	No. 21-9315 Issued By BU
Department / contractor	Equipment Number	Equipment Location		Equipment Result	New Sticker No.
SUNHAR	S43AG-578	PKG-10		☒ Pass ☐ Fail	BU-23-0090
Manufacturer	Model	Capacity	Type	Equipment Serial Number	Sticker Expiration Date
GENIE	Z-135	272kg	MEWP	Z 13511-1342	JUNE 30, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
4	Periodic inspection and function test for Base SUPPORTER (levelling) were not form AS per AS 5.0.3.03, 10.5.9.2.5 "PASS" 	

RECEIVER NAME: ARJ SIGNATURE: [Signature] INSPECTOR NAME: 1234567

BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 800 191 1111