




Previous Sticker
No. 21-6383 Issued By Bu

LIFTING EQUIPMENT INSPECTION REPORT	Area	Inspection Date		Inspection Time	Previous Sticker No. 21-6385
	Dammam	JAN 06, 2024		10:30	Issued By Bu
Department / contractor SUDAIR	Equipment Number 543AG-579	Equipment Location DMMARKO		Equipment Result ☒ Pass ☐ Fail	New Sticker No. Bu-23-0814
Manufacturer GENIE	Model Z-135	Capacity 272kg	Type MEWP	Equipment Serial Number Z13511-1463	Sticker Expiration Date JULY 05, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
6	Periodic Inspection and Function Test for Boom Supporter Clevises were not performed as per AS S-DRM 607.030 AMS 92.5 ROSS 	

RECEIVER NAME: AK SIGNATURE: [Signature] INSPECTOR NAME: McMab
BADGE#: _____ TELEPHONE NO.: _____ TELEPHONE NO.: 801966