



BUREAU
VERITAS

BV No. 239094

LIFTING EQUIPMENT INSPECTION REPORT	Area JUBAIL	Inspection Date JAN 22, 2024	Inspection Time 9:00	Previous Sticker No. 19782 Issued By Zawi
Department / contractor SUDHIR	Equipment Number S43A0-580	Equipment Location NSH	Equipment Result ☒ Pass ☐ Fail	New Sticker No. BV-23-0853
Manufacturer GENSG	Model Z-135	Capacity 272 KG	Type MEWP	Equipment Serial Number Z13511-1441
				Sticker Expiration Date JULY 21, 2024

Above Equipment Was Inspected By Bureau Veritas In Accordance With Applicable Saudi Aramco GI's , ASME And API Standards. Deficiencies That Require Corrective Actions Are Listed Below. Specific Repairs To Correct Each Deficiency Should Be Noted In The Corrective Action Taken Column.

No.	DEFICIENCIES	CORRECTIVE ACTION TAKEN
1	Periodic Inspection and Function test For	
	Boom supported Elevating work platform	
	AS PER AS S. ARAMCO 657.03.1.1.1.5	
	1 PASS	

RECEIVER NAME: ARSF	SIGNATURE: [Signature]	INSPECTOR NAME: M. Almar
BADGE#:	TELEPHONE NO.:	TELEPHONE NO.: 80019106