




مؤسسة جبال هيمالايا للفحص

JABAL HEMALAYA FOR INSPECTIONS



Certificate of Thorough Visual and Functional Examination of Dump Truck

Certificate No: JHI-9393-26-C1

Date of Inspection: 15-07-2026

Name of the owner company:
SUDHIR EQUIPMENT RENTAL COMPANY

Location:
NEW YARD- RIYADH- KSA

EQUIPMENT DETAILS: DUMP TRUCK

Reference Regulations:

Truck Maker & Date of Manufacture:

SASO ISO 20474-1, SASO-ISO-20474-6, BS EN 474-1& 6:2022

SINOTRUCK & 2026

Sticker No.	Owner Id :	Traffic Plate No.	Model No.	Serial No./ Chassis No.
019035	SDT-020-094	3608 GTA	ZZ3257V384JE1	LZZ1ELVD3TJ456821

Dumper Maker & Date of Manufacture.

Truck Capacity

Mass.

N/A

20 m³

32000Kg

Description of Test: Note: Visual and Functional Test Were Satisfactory.

Date of Last Examination

Date of Next Examination

N/A

14-01-2027

RECOMMENDATION / REMARKS

At the time of inspection, the equipment was found satisfactory.

IMAGES FOR DUMP TRUCK



***Certificate becomes invalid, if any alteration/major repair/modernization made on the Equipment in which case it must be re-examined and re-tested.**

THIS IS TO CERTIFY THAT the Undersigned, a competent representative, did, attend to examine this equipment in accordance to the aforementioned standard to ascertain its safe working load and that the examination indicated that the said equipment has no indigenous injury or sighted deformation and the safe working load of the said equipment as either identified or test proof loaded is shown. The equipment is satisfactory for its intended use within the limits specified and at the time of inspection was found to be satisfactory for further use, provided there is continuous maintenance applied, implementation of our remarks & recommendations and qualified operators employed.

Authorized Name: M.SHEIK ALLAVUDEEN

Surveyor's Name:

SUDHER SINGH

Authorized Signature:

Surveyor's Signature:

This certificate is granted subject to the condition that is understood and agreed that nothing herein contained shall be deemed to relieve any designer, manufacturer, seller, supplier, repairer or operator of any warranty, express or implied, and Jabal Hemalaya For Inspections liability shall be limited to the acts or omissions of its employees, agents and subcontractors. Under no circumstances whatsoever shall Jabal Hemalaya For Inspections nor their Engineer be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable by normally accepted standards and only those items actually inspected by Jabal Hemalaya For Inspections and which are covered only by this certificate. Any person not a party to the contract pursuant to which this document is delivered may not assert claim against Jabal Hemalaya For Inspections for any liability arising out of errors or omissions which may be contained in said document and in connection with any activities for which it may provide. This certificate shall not be reproduced except in full without the approval of Jabal Hemalaya For Inspections.

Disclaimer: This certificate is issued subject to the observation made at the time of inspection. The company (Jabal Hemalaya) will not be held liable for any damage/losses associated to the equipment/material

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628

CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com

Annex to Certificate of Thorough Examination

Certificate No.: JHI-9393-26-C1

Date of Inspection: 15-07-2026

S/No	Description	Condition / Remarks
1	Equipment Documents	Satisfactory
2	Control lever marking	Satisfactory
3	Linkage	Satisfactory
4	Attachment Fixing Pins / Locks	Satisfactory
5	Body	Satisfactory
6	Axles / Platform	Satisfactory
7	Gauges in Cab	Satisfactory
8	Doors	Satisfactory
9	ROPS/FOPS/TOPS	Satisfactory
10	Wind Shield	Satisfactory
11	Wipers	Satisfactory
12	Seat belt / Seat Bar	Satisfactory
13	Motion Warning Alarm / Horn	Satisfactory
14	Exhaust System	Satisfactory
15	Steering	Satisfactory
16	Rotating Warning Light / Reverse Alarm	Satisfactory
17	Operation Controls	Satisfactory
18	Electrical Cabling and Fittings	Satisfactory
19	Battery Condition / Connections	Satisfactory
20	Brakes	Satisfactory
21	Lights	Satisfactory
22	Fire Extinguisher	Satisfactory
23	Housekeeping	Satisfactory
24	Manufacturer's manuals	Satisfactory
25	Capacity Labels	Satisfactory
26	Machine Guard	Satisfactory
27	Hydraulic System	Satisfactory
28	Engine / Engine Compartment	Satisfactory
29	Spark Arrestor	Shall be fitted when operating in Highly explosive areas
30	Painting/Corrosion / General Status - Visual	Satisfactory
31	Maintenance Status record	Satisfactory
32	Record of Major Alterations or Repair	Nil
33	Is the machine less than 15 years old?	Satisfactory

COMMENTS: At the time of inspection, the equipment was found satisfactory.

Surveyor's Name: **SUDHER SINGH**



Surveyor's Signature: _____

Address: Est. Jabal Hemalaya for Inspections, Saudi Arabia, Riyadh. Po. 12628

CR No: 1010927177, Tel: 0112334900, Email: info@jhinspection.com, www.jhinspection.com