



شركة التفتيش الموحد المحدودة
UNIFIED INSPECTION COMPANY LTD.
P.O Box - 3689, Al Jubail - 35525, Kingdom of Saudi Arabia

U-LFT-C-04285/26
Date of Issue: 06-Sep-2026

CERTIFICATE OF THOROUGH EXAMINATION / LOAD TEST

Ref. No. U-WO-SEP 2026 -
186
Rev.No.: 00



This report complies with the Lifting Equipment Engineers Association Technical requirements.

Name & Address of the Owner : **Sudhir Equipment Rental Company**
Location at which the Examination was made : **ROSHAN SITE**

Serial No. : BTRC024F00235 **Model** : BT20CRT2
ID / Fleet No.: : S20SD-1594 **Manufacturer** : DINGLI / 2024
Date of Inspection : 06-Sep-2026 **Report No.** : 41280
Date of Next Inspection : 05-Mar-2027 **Sticker No.** : 44453

S.No.	Description of the Equipment	Qty.	Capacity / SWL	Applied Load(s):
1	BOOM SUPPORTED ELEVATING WORK PLATFORM (MAN LIFT/TELESCOPIC)	01	320 kg	-

Applicable Reference Standard(s) / Code(s) for which the item was examined : ANSI SIA A92.5: 2006 /-

Equipment's used for Measuring / Testing : -

Is this the first Examination after installation or assembly at a new site or location.? Yes ☐ No ☒
Was the Examination Carried out after the occurrence of exceptional circumstances? Yes ☐ No ☒
Was the Examination Carried out within an Interval of 6 months / 12 Months? 6 months ☒ 12 months ☐
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:(If none, state NONE): NONE
Particulars of any repair, renewal or alteration required to remedy the defect identified above -
Particulars of any tests carried out as part of examination: (if none, state NONE) NONE
Is this equipment safe to use Yes ☒ No ☐

We hereby certify that the equipment mentioned above was undergone Visual and Thorough Examination by the competent inspector according to standard operating procedure of Unified Inspection Company Ltd. based on relevant International / National Standards such as ASME/BS EN/ ANSI/API.

Remarks: The Inspection results reported in this certificate are valid at the time of Inspection. The report should not be produced either in full or in part without our permission in writing. Next due date, Id No., and end user address (If any) mentioned based on customer's request / reference evident only.

Name of Inspector:
Kasim Badusha



Reviewed & Approved By
Mohamed Bishwan



Doc. No. : U-LFT-IC 003, Issue No.: 02, Rev. No. : 00, Rev. Date : 01-JAN-2026.

Page Number : 1 of 1