

Urban Lake Pollution

Field Inspection Log prepared by GreenEarth Initiative

Inspection Date: 03 February 2025

Site: Bellandur Lake (South-East Zone)

City: Bengaluru, Karnataka

Coordinates: 12.9250, 77.6762

A routine environmental inspection at Bellandur Lake revealed significant pollution levels caused by untreated sewage inflow and solid waste dumping. The condition has worsened over the past month, with visible foam formation and foul odor spreading to nearby residential areas.

Observed Environmental Issues:

Thick white foam accumulation along lake edges

Continuous inflow of untreated sewage from 2 drainage points

Floating plastic and organic waste

Darkened water color indicating contamination

Strong odor affecting nearby residents

Decline in bird activity observed compared to previous month

Fish mortality reported by local fishermen

Vegetation along lake edges turning unhealthy

Possible long-term ecosystem damage if untreated

Residents reporting breathing discomfort and irritation

Reduced outdoor activity due to smell

Complaints from nearby apartments and offices

Affected lake stretch: ~2.8 km perimeter

Surrounding population impacted: ~2,500-3,000

Spread of foam seen up to nearby roads during peak conditions

Concerns:

Environmental degradation accelerating

Public health concerns emerging

Risk of waterborne contamination

Long-term ecological imbalance

Requested Interventions

Immediate containment of sewage inflow

cleanup drive for surface waste

Awareness campaigns for waste disposal

Lake cleanup initiatives