Synthetic sample document - fictional data for demos and evaluation only.

MOTOR INSPECTION REPORT
Document ID: RPT-MTR-330
Equipment: Motor M-330, 110 kW induction motor driving cooling tower fan F-330
Inspection Date: 2026-09-12. Inspector: Electrical Team B

1. Electrical Tests:
- Insulation resistance: 850 MOhm at 1000 V DC (minimum acceptable 100 MOhm).
- Polarization index: 3.2.
- Winding resistance phase imbalance: 0.8 percent.
- Running current: 182 A against a nameplate rating of 195 A.

2. Mechanical and Thermal Checks:
- Non-drive end (NDE) bearing temperature: 82 degC (alarm at 90 degC).
- Drive end (DE) bearing temperature: 71 degC.
- Overall vibration: 2.9 mm/s RMS.
- Thermography: hot spot of 64 degC on the terminal box connection of phase L2;
  a loose cable lug is suspected.
- Cooling fan cowl partially blocked with dust.

3. Findings and Recommended Actions:
- Re-torque the phase L2 terminal lug at the next planned shutdown.
- Clean the fan cowl and the cooling fins.
- Regrease the NDE bearing with 15 g of grease.
- Repeat thermography within 30 days.
- Overall condition rating: B (acceptable with minor defects). The motor is fit for continued service.