

Aquatrace Field Documentation Report

Title: Aquatrace leak detection field report

Tenant: aquatrace

Job: aquatrace-real-job-fielddocs-receipt

Findings:

- Skimmer throat dye test documented before repair.
- After photo attached for operator review.
- Report is native FieldDocs documentation only; no outbound delivery was performed.

Checklist:

- Confirm static water loss baseline: pending
- Inspect skimmers and throats: pass
- Inspect returns and fittings: pending
- Dye-test suspect penetrations: pass
- Inspect equipment pad and visible plumbing: pending
- Capture before and after photos: pass
- Record findings and repair recommendation: pass

Media:

- media_3a7e765a-4285-436e-82b1-3bc8b81c91d4: Uploaded photo tagged before, skimmer, dye-test.
- media_8b650c5a-63fe-4c4a-83d0-ea10b4be2172: Uploaded photo tagged after, skimmer, repair.

Compliance Blocks:

- Field documentation only; no engineering, legal, or regulatory determination.
- Photos, checklist notes, and findings remain subject to operator review.
- VGB documentation template language is informational and approval-gated before delivery.