

NexCam Field Report

Title: Aquatrace leak detection field report

Tenant: aquatrace

Job: aquatrace-real-job-fielddocs-receipt

Findings:

- Skimmer throat dye test documented before repair.
- After photo attached for operator review.
- Report is native NexCam documentation only; no outbound delivery was performed.

Checklist:

- Client, city/state, service date, and completion time: No note recorded
- Technician name(s): Skimmer throat inspected and dye-tested.
- Loss beyond evaporation present: pending
- Leak located: pass: Suspect penetration documented in photos.
- Free-text findings: No note recorded
- Annotated findings photos selected: No photos attached
- Site conventions and numbering notes: Repair recommendation recorded for operator review.
- Weather conditions: No note recorded
- Daily evaporation index: No value recorded
- Reported daily water loss: No value recorded
- Pre-existing site conditions: No note recorded
- Residential/commercial and inground/above-ground: No selection
- Construction type and special features: No note recorded
- Pool skimmer count: No value recorded
- Spa skimmer count: No value recorded
- Catch basin skimmer count: No value recorded
- Pool total gallons: No value recorded
- Spa total gallons: No value recorded
- Catch basin total gallons: No value recorded
- Filter type and water system: No note recorded
- Electrical, pumps, motors, and equipment-pad notes: No note recorded
- Testing procedures used: No note recorded
- Testing procedures successful: pending
- Structure pass/fail and issue description: pending
- Lights pass/fail and issue description: pending
- Plumbing pass/fail and issue description: pending
- Roof solar pass/fail and issue description: pending