

Aquatrace Field Documentation Report

Title: Deborah Justice Aquatrace Leak Detection Report

Tenant: aquatrace

Job: companycam-doc-18218446-deborah-justice

Findings:

- Deborah Justice leak detection report from CompanyCam checklist doc 18218446.
- Completion time: 3:10pm, Thursday July 2nd, 2026. Technicians: Chris and Logan.
- Pool measurements: 1,002.7 square feet, 626.69 gallons per inch, 37,602 total gallons.
- Finding: active water loss in spa circulation line and nearest spa main drain; pool main drain count kept separate from spa sec

Checklist:

- Client, city/state, service date, and completion time: pass
- Technician name(s): pass
- Loss beyond evaporation present: pending
- Leak located: pending
- Free-text findings: fail
- Annotated findings photos selected: pending
- Site conventions and numbering notes: pending
- Weather conditions: pending
- Water temperature, air temperature, and daily evap index: pending
- Reported daily water loss notation: pending
- Pre-existing site conditions: pending
- Residential/commercial and inground/above-ground: pending
- Construction type and special features: pending
- Pool skimmer, return, drain, light, and cleaner-port counts: pass
- Spa skimmer, return, drain, light, and cleaner-port counts: fail
- Catch basin skimmer, return, drain, light, and cleaner-port counts: pending
- Pool Measure used, square feet, average depth, gallons/inch, total gallons: pass
- Spa Measure used, square feet, average depth, gallons/inch, total gallons: pending
- Catch basin Measure used, square feet, average depth, gallons/inch, total gallons: pending
- Filter type and water system: pending
- Electrical, pumps, motors, and equipment-pad notes: pending
- Testing procedures used: pending
- Testing procedures successful: pending
- Structure pass/fail and issue description: pending
- Lights pass/fail and issue description: pending
- Plumbing pass/fail and issue description: fail