

GOVERNMENT OF TRIPURA
O/O. THE SUPERINTENDING ENGINEER
RD 2ND CIRCLE, UDAIPUR
GOMATI DISTRICT, TRIPURA


F.02(8)/ SE-II/GEN/Misc/2009-10/ 231

Dated 07 / 08 / 2018

School Building Safety Certificate

This is to certify that, St. John's High School possesses 4 (four) buildings, out of which 3 (three) are two storied and 1 (one) is a single storied building. These buildings have been constructed through the RD Engineering Department. I have thoroughly inspected all the buildings and have found that the condition of all the buildings are safe and in good condition. The building was constructed in the year 2010. The life of a building is normally 70 (seventy) to 80 (eighty) years.

The materials utilized in the constructions are of good quality and the foundations provided are also technically sound.


(Er. U. Jamatia)
Superintending Engineer
RD 2nd Circle, Udaipur
Gomati District, Tripura