



Inspection Number : INS/0724/00070
Inspection Date : 18 July 2024
Average Actual Point : 4.79
Fabric Name : 60% BCI COTTON 40% POLYESTER 32S/1SLUB JERSEY

ID Item : 1
Lot : 24060069
Status : PASS

Style : 245k0087-F
Color : SANGUINE 344

Form Number: FRM/0724/00206				Width: 0 Inch		Weight: 21.8 Kg	
Date: 2024-07-18				Gramage: 209		Inspector: FAJAR	
Fabric Supplier: LIAN - TA - HSING (VIETNAM) CO.LTD				Roll: C308		Machine No: 01	

Length	Defect Name	Code	Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width
1-10							69->68
11-20	(YAGORE/DIRTY)	K	2				
31-40	(HARIORE/BORKEN YARN)	C				1	
41-50							69->68
61-70	(HARIORE/BORKEN YARN)	C				1	
91-100							69->68

Barcode Length: 102 Yard				Remark:			
Actual Length: 100 Yard				Status: PASS			

Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width	Total Point	Actual Point
2	0	0	8	68	10	5.29

Form Number: FRM/0724/00207				Width: Inch		Weight: 21.12 Kg	
Date: 2024-07-18				Gramage: 209		Inspector: FAJAR	
Fabric Supplier: LIAN - TA - HSING (VIETNAM) CO.LTD				Roll: C299		Machine No: 01	

Length	Defect Name	Code	Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width
1-10							69->68
41-50	(ANA/HANE/HOLE)	A				1	
51-60							69->68
101-110	(DOTSOGI/CONTINOUSE FAB)	E				1	69->68

Barcode Length: 101 Yard				Remark:			
Actual Length: 99 Yard				Status: PASS			

Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width	Total Point	Actual Point
0	0	0	8	68	8	4.28