



Inspection Number	: INS/0724/00002	ID Item	: 1	Style	: 586067 hol 24
Inspection Date	: 01 July 2024	Lot	: 24050451	Color	: Interactive lime
Average Actual Point	: 4.94	Status	: PASS		
Fabric Name	: 60%COTTON 40% POLYESTER 32S/1 SLUB JERSEY				

Form Number: FRM/0724/00003				Width: 0 Inch		Weight: 20.72 Kg	
Date: 2024-07-01				Gramage: 209		Inspector: RIKI	
Fabric Supplier: LIAM-TA-HSING VIETNAM Co.LTD				Roll: C15		Machine No: 02	
Length	Defect Name	Code	Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width
1-10	(FUTOITO/SLUB)	D	1				72->70
11-20	(FUTOITO/SLUB)	D	1				
31-40	(FUTOITO/SLUB)	D	2				
41-50	(FUTOITO/SLUB)	D	2				72->70
61-70	(ANA/HANE/HOLE)	A				1	
81-90	(FUTOITO/SLUB)	D	1				72->70
Barcode Length: 99 Yard				Remark:			
Actual Length: 99 Yard				Status: PASS			
Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width	Total Point	Actual Point	
7	0	0	4	70	11	5.71	

Form Number: FRM/0724/00004				Width: Inch		Weight: 20.86 Kg	
Date: 2024-07-01				Gramage: 209		Inspector: RIKI	
Fabric Supplier: LIAM-TA-HSING VIETNAM Co.LTD				Roll: C27		Machine No: 02	
Length	Defect Name	Code	Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width
1-10							72->70
11-20	(ANA/HANE/HOLE)	A				1	
21-30	(FUTOITO/SLUB)	D	1				
41-50	(FUTOITO/SLUB)	D	2				72->70
71-80	(FUTOITO/SLUB)	D	1				
91-100							72->70
Barcode Length: 100 Yard				Remark:			
Actual Length: 99 Yard				Status: PASS			
Up To 3"	Over 3" - 6"	Over 6" - 9"	Over 9"	Width	Total Point	Actual Point	
4	0	0	4	70	8	4.16	