HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: Refer to : JKT-25-07-22-02

PART NAME: SEAL, OIL

POS / PART NO: SZ31185003

PROBLEM / DAMAGE: "0"

CHASSIS NO:	ENGINE NO:
X29001	J08EWDJ44717

KM (ODO):	OCCURRED:	REPAIR:
24.656 km	28/01/2026	02/05/2026

DTR NO: TRHMM0126002

TRHMM0126002

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-02-18-02

PART NAME: Brake Chamber R2

POS / PART NO: S49Q0EW010

PROBLEM / DAMAGE: "QPI Still Open"

CHASSIS NO:	ENGINE NO:
P16812	J08EWEJ23450

KM (ODO):	OCCURRED:	REPAIR:
21.907 km	29/01/2026	03/04/2026

DTR NO: TRHAM0126009

TRHAM0126009

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: Refer to : JKT-25-08-17-01

PART NAME: SEAL, OIL

POS / PART NO: SZ31185003

PROBLEM / DAMAGE: "0"

CHASSIS NO:	ENGINE NO:
M11286	J08EWDJ36632

KM (ODO):	OCCURRED:	REPAIR:
30.470 km	11/02/2026	03/04/2026

DTR NO: TRDCM0226003

TRDCM0226003

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: Refer to : JKT-25-08-20-01

PART NAME: SEAL, OIL

POS / PART NO: SZ319T0001

PROBLEM / DAMAGE: "0"

CHASSIS NO:	ENGINE NO:
X29137	J08EWDJ44911

KM (ODO):	OCCURRED:	REPAIR:
7.572 km	18/02/2026	03/04/2026

DTR NO: TRPPK0226002

TRPPK0226002

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-07-22-01

PART NAME: Ring Retainer

POS / PART NO: -

PROBLEM / DAMAGE: "QPI Still Open"

CHASSIS NO:	ENGINE NO:
500098	N04CWKJ10502

KM (ODO):	OCCURRED:	REPAIR:
174.426 km	21/07/2026	10/12/2026

DTR NO: TRDCM0726022

TRDCM0726022

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-07-22-02

PART NAME: Ring Retainer

POS / PART NO: -

PROBLEM / DAMAGE: "QPI Still Open"

CHASSIS NO:	ENGINE NO:
500086	N04CWKJ10387

KM (ODO):	OCCURRED:	REPAIR:
179.500 km	21/07/2026	10/12/2026

DTR NO: TRDCM0726021

TRDCM0726021

QC VERIFIED: [ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-08-12-06

PART NAME: Protection Valve

POS / PART NO: S445701430

PROBLEM / DAMAGE:
"QPI Still Open"

CHASSIS NO:	ENGINE NO:
X10202	E13CBJ 10570

KM (ODO):	OCCURRED:	REPAIR:
1.281 km	19/08/2026	09/10/2026

DTR NO: TRKMA0826001

TRKMA0826001

QC VERIFIED:
[ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-09-01-01

PART NAME: Protection Valve

POS / PART NO: S445701430

PROBLEM / DAMAGE:
"QPI Still Open"

CHASSIS NO:	ENGINE NO:
X10211	E13CBJ 12005

KM (ODO):	OCCURRED:	REPAIR:
1.010 km	28/08/2026	09/10/2026

DTR NO: TRKMA0826012

TRKMA0826012

QC VERIFIED:
[ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-10-06-01

PART NAME: Differential

POS / PART NO: 41201E0J10

PROBLEM / DAMAGE:
"QPI Still Open"

CHASSIS NO:	ENGINE NO:
P19730	J08EWEJ28037

KM (ODO):	OCCURRED:	REPAIR:
27.662 km	22/09/2026	10/08/2026

DTR NO: TRDMI0926004

TRDMI0926004

QC VERIFIED:
[ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI

HINO ORIGINAL FAILURE PART TAG
HMSI-FIELD QUALITY -> HMMI

QPI NO: JKT-26-10-09-01

PART NAME: Brake Chamber R2

POS / PART NO: S49Q0EW010

PROBLEM / DAMAGE:
"QPI Still Open"

CHASSIS NO:	ENGINE NO:
P18540	J08EWEJ26449

KM (ODO):	OCCURRED:	REPAIR:
37.001 km	01/10/2026	10/09/2026

DTR NO: TRHAM0926006

TRHAM0926006

QC VERIFIED:
[ ] HMSI-Field Quality

INSTRUKSI PENGIRIMAN:
Gantungkan/tempelkan tag ini pada fisik part OFP sebelum diserahkan ke Pabrik HMMI.

PT HINO MOTORS SALES INDONESIA HMSI -> HMMI