

CUSTOMER SERVICE REPORT

REPORT NUMBER
Not assigned

CUSTOMER Alround	DATE 15 & 17 Aug 2026
MACHINE Gweike 4020 GAIL Laser Cutter	TECHNICIAN Aaron
SERVICE STATUS Completed	DOCUMENT TYPE Customer copy

REASON FOR VISIT

General maintenance and inspection.

WORK COMPLETED

Cleaned and inspected the machine bellows; cleaned the rack and bearing-bellows areas and tested the Y-axis lubrication; checked the chiller water, which was clean and did not require replacement; and repaired the exchange-table chain connection.

FURTHER ACTION REQUIRED

Not applicable for this report.

PHOTOS

No photos supplied.