NATIONAL LIFT ESCALATOR TESTING AGENCY

NLETA ARCHIVE DOCUMENTATION

Controlled Engineering Certificate | Revision 1 (Rev.1)

PAT INSPECTION CERTIFICATE

Certificate generated from completed CHK-01 PAT Master Checklist

Certificate & Inspection Details	
Certificate No.	NLETA-PAT-CERT-2026-00195
Owner / Client	Tanish singh
Lift / Asset	TS-MP-116
Location	gadarwara
PSGA No.	C03092026
SAF No.	C03092026
Inspection Date	03 / 09 / 2026
Certificate Generated	03 / 09 / 2026 04:43 PM IST

Compliance Assessment

100.00%

Indicative Category: Excellent

★★★★★

Score Summary

Result	Count	Weight
C	123	100%
NC	0	0%
NA	13	Excluded
D	0	Pending

Certificate Declaration

This certificate is generated from the completed NLETA CHK-01 Rev.1 Periodic Assessment & Testing checklist. The compliance score is calculated as:

C ÷ (C + NC) × 100

Not Applicable (NA) checkpoints are excluded from the calculation. Deferred (D) checkpoints are treated as pending and must not remain unresolved at the time of certificate generation.

The star rating shown on this certificate is an automatically calculated Admin Certificate rating. It is not exposed in the client R01 report.

Inspector	NLETA	Admin Certification