NLETA

National Lift Escalator Testing Agency

Inspection & Testing Report

PAT – Partial Acceptance Test / Safety Inspection

Report No: **NLETA-RPT-20260831-00001**

Inspection Information

SERVICE	PAT – Partial Acceptance Test / Safety Inspection	ASSET / LIFT	TS-MP-103
LOCATION	TOWER A JABALPUR	INSPECTION DATE	30 / 08 / 2026
PSGA NO.	A30082026	SAF NO.	A30082026
OWNER	Tanish singh	TECHNICIAN	aman
REPORT REQUESTED	31 / 08 / 2026 04:28 PM IST	RECHECK	05 / 09 / 2026

Inspection Summary

12	0	0	0
Total Checkpoints	OK	NC	NA

Complete Checklist

Checkpoint	Section	Checkpoint Description	Result	Remarks
version	—	—	PAT-1.0	—
submitted_at	—	—	2026-08-30 11:56:24	—
technician_id	—	—	56	—
job_id	—	—	185	—
saf_id	—	—	4	—
final_status	—	—	CONDITIONAL PASS	—
results	—	—	—	—
section_remarks	—	—	—	—
floor_matrix	—	—	—	—
owner_approval	—	—	APPROVED	—
recheck_results	—	—	—	—
recheck_meta	—	—	—	—

Owner Report Request

Please prepare and send the final inspection report for this lift.

Report Information

REPORT NUMBER	**NLETA-RPT-20260831-00001**	GENERATED	**31 / 08 / 2026 05:05 PM IST**
REPORT STATUS	**Generated**	ADMIN APPROVAL	**Approved**

Technician

NLETA

Owner