PAT-R01 — PERIODIC ASSESSMENT & TESTING REPORT

Customer Report

Document Control

Archive No.	11
Document Code	PAT-R01
Revision	Rev.1
Classification	Customer Report
Previous Archive	10 — CHK-PAT
Next Archive	12 — PAT-C01

Inspection Summary

Client	Tanish singh	**Site**	TOWER A JABALPUR
Inspection ID	A30082026	**Lift ID**	TS-MP-103
Inspection Date	30 / 08 / 2026	**Inspector**	aman
AMC Agency	—	**Units Inspected**	1
PSGA No.	A30082026	**SAF No.**	A30082026
Service	PAT – Partial Acceptance Test / Safety Inspection		
Recheck Date	05 / 09 / 2026	**Report Requested**	31 / 08 / 2026 04:28 PM IST

Engineering Findings

Item	Section	Risk Status	Recommendation
PAT-A.01 General inspection requirement	Documentation	**NC**	—
PAT-A.02 Inspection documentation	Documentation	**NC**	—
PAT-A.03 Relevant certificates and records	Documentation	**NC**	—
PAT-A.04	—	**NC**	—
PAT-A.05	—	**NC**	—
PAT-A.06	—	**OK**	—
PAT-B.01 Machine room condition	Machine Room	**OK**	—
PAT-B.02 Machine condition	Machine Room	**OK**	—
PAT-B.03 Access and housekeeping	Machine Room	**OK**	—
PAT-B.04	—	**OK**	—

Item	Section	Risk Status	Recommendation
PAT-B.05	—	**OK**	—
PAT-B.06	—	**OK**	—
PAT-C.01 Drive equipment	Machine Room	**NC**	—
PAT-C.02 Brake system	Machine Room	**NC**	—
PAT-C.03 Motor condition	Machine Room	**NC**	—
PAT-C.04	—	**OK**	—
PAT-C.05	—	**OK**	—
PAT-C.06	—	**OK**	—
PAT-C.07	—	**OK**	—
PAT-C.08	—	**OK**	—
PAT-C.09	—	**OK**	—
PAT-C.10	—	**OK**	—
PAT-C.11	—	**OK**	—
PAT-D.01 Shaft condition	Lift Shaft	**OK**	—
PAT-D.02 Guide rails	Lift Shaft	**OK**	—
PAT-D.03 Counterweight	Lift Shaft	**OK**	—
PAT-D.04	—	**OK**	—
PAT-D.05	—	**OK**	—
PAT-E.01 Car condition	Car	**OK**	—
PAT-E.02 Car operating panel	Car	**OK**	—
PAT-E.03 Emergency alarm	Car	**OK**	—
PAT-E.04	—	**OK**	—
PAT-E.05	—	**OK**	—
PAT-E.06	—	**OK**	—
PAT-E.07	—	**OK**	—
PAT-E.08	—	**OK**	—
PAT-F.01 Landing doors	Doors	**OK**	—
PAT-F.02 Car doors	Doors	**OK**	—
PAT-F.03	—	**OK**	—
PAT-F.04	—	**OK**	—
PAT-F.05	—	**OK**	—
PAT-F.06	—	**OK**	—
PAT-F.07	—	**OK**	—
PAT-F.08	—	**OK**	—

Item	Section	Risk Status	Recommendation
PAT-G.01 Safety equipment	Safety	**OK**	—
PAT-G.02	—	**OK**	—
PAT-G.03	—	**OK**	—
PAT-G.04	—	**OK**	—
PAT-G.05	—	**OK**	—
PAT-G.06	—	**OK**	—
PAT-G.07	—	**OK**	—
PAT-G.08	—	**OK**	—
PAT-H.01 Electrical installation	Electrical	**OK**	—
PAT-H.02	—	**OK**	—
PAT-H.03	—	**OK**	—
PAT-H.04	—	**OK**	—
PAT-H.05	—	**OK**	—
PAT-H.06	—	**OK**	—
PAT-I.01 Earthing	Electrical	**OK**	—
PAT-I.02	—	**OK**	—
PAT-I.03	—	**OK**	—
PAT-I.04	—	**OK**	—
PAT-I.05	—	**OK**	—
PAT-I.06	—	**OK**	—
PAT-I.07	—	**OK**	—
PAT-I.08	—	**OK**	—
PAT-I.09	—	**OK**	—
PAT-I.10	—	**OK**	—
PAT-I.11	—	**OK**	—
PAT-I.12	—	**OK**	—
PAT-I.13	—	**OK**	—
PAT-I.14	—	**OK**	—
PAT-I.15	—	**OK**	—
PAT-I.16	—	**OK**	—
PAT-I.17	—	**OK**	—
PAT-I.18	—	**OK**	—
PAT-J.01 Safety device operation	Safety Devices	**OK**	—
PAT-J.02	—	**OK**	—
PAT-J.03	—	**OK**	—
PAT-J.04	—	**OK**	—
PAT-J.05	—	**OK**	—

Item	Section	Risk Status	Recommendation
PAT-J.06	—	**OK**	—
PAT-J.07	—	**OK**	—
PAT-J.08	—	**OK**	—
PAT-J.09	—	**OK**	—
PAT-K.01 Levelling accuracy	Lift Operation	**OK**	—
PAT-K.02 Starting and stopping	Lift Operation	**OK**	—
PAT-K.03 Acceleration	Lift Operation	**OK**	—
PAT-K.04 Running condition	Lift Operation	**NC**	—
PAT-K.05 Noise / vibration	Lift Operation	**NC**	—
PAT-K.06 Door operation	Lift Operation	**NC**	—
PAT-K.07 Load operation	Lift Operation	**NC**	—
PAT-K.08 General operation	Lift Operation	**NC**	—
PAT-L.01 No-load test	Testing	**NC**	—
PAT-L.02 Load test	Testing	**NC**	—
PAT-L.03 Brake test	Testing	**NC**	—
PAT-L.04 Safety gear test	Testing	**OK**	—
PAT-L.05 Governor test	Testing	**OK**	—
PAT-L.06 Limit switch test	Testing	**OK**	—
PAT-L.07 Emergency operation	Testing	**OK**	—
PAT-L.08 Final functional test	Testing	**OK**	—
PAT-M.01 Installation documents	Documentation	**OK**	—
PAT-M.02 Test certificates	Documentation	**OK**	—
PAT-M.03 Manufacturer documents	Documentation	**OK**	—
PAT-M.04 Other documents	Documentation	**OK**	—
PAT-N.01 Safety signage	Safety / Compliance	**OK**	—
PAT-N.02 Warning notices	Safety / Compliance	**OK**	—

Item	Section	Risk Status	Recommendation
PAT-N.03 Statutory requirements	Safety / Compliance	**OK**	—
PAT-N.04 Emergency instructions	Safety / Compliance	**OK**	—
PAT-N.05 Rescue instructions	Safety / Compliance	**OK**	—
PAT-N.06 Fire safety	Safety / Compliance	**OK**	—
PAT-N.07 Access control	Safety / Compliance	**OK**	—
PAT-N.08 Housekeeping	Safety / Compliance	**OK**	—
PAT-N.09 Maintenance records	Safety / Compliance	**OK**	—
PAT-N.10 Logbook	Safety / Compliance	**OK**	—
PAT-N.11 Certificates	Safety / Compliance	**OK**	—
PAT-N.12 Labels	Safety / Compliance	**OK**	—
PAT-N.13 Emergency contact	Safety / Compliance	**OK**	—
PAT-N.14 Safety equipment	Safety / Compliance	**OK**	—
PAT-N.15 Other compliance	Safety / Compliance	**OK**	—
PAT-O.01 Overall lift condition	Final Review	**OK**	—
PAT-O.02 Safety condition	Final Review	**OK**	—
PAT-O.03 Operational condition	Final Review	**OK**	—
PAT-O.04 Installation compliance	Final Review	**OK**	—
PAT-O.05 Test completion	Final Review	**OK**	—
PAT-O.06 Deficiencies identified	Final Review	**OK**	—
PAT-O.07 Corrective action requirement	Final Review	**OK**	—
PAT-O.08 Recommendations	Final Review	**OK**	—
PAT-O.09 Inspector comments	Final Review	**OK**	—
PAT-O.10 Final assessment	Final Review	**NC**	—

Inspection Result Summary

Total Checkpoints	130	**OK**	113
NC	17	**NA**	0
Pending Evidence	0	**Compliance Outcome**	Non-Compliant

Compliance Outcome

Compliant	☐
Compliant with Observations	☐
Non-Compliant	☒
Critical Safety Risk	☐

Report Generation Information

Report Number	PAT-R01-20260831-00001
Generated Date & Time	31 / 08 / 2026 05:40 PM IST
Report Status	Generated
Admin Approval	Approved

Inspector Declaration

I certify that this report is based on an independent engineering inspection supported by documented technical evidence.

Inspector

Name: aman
Date: 30 / 08 / 2026

National Lift Escalator Testing Agency

Authorized Signatory
Date: 31 / 08 / 2026

END OF ARCHIVE 11 — PAT-R01 (Rev.1)
Next Archive: 12 — PAT-C01