



DEPED DRRM

SCHOOL'S SUMMARIZATION OF FIRE SAFETY - BUILDINGS

Name of School: TABACUHAN ES
School ID: 107130

Name of School Head: AURORA S, LUNA
Name of School DRRM Coordinator: JESUS ARPON

BUILDING NUMBER	BUILDING NAME	NUMBER OF FLOOR	IS THE BUILDING WITH SECONDARY EXIT FOR (2-4 STOREY BUILDING)	NUMBER OF CLASSROOMS	NUMBER OF ROOMS WITHOUT SECONDARY EXIT	NUMBER OF LABORATORIES	NUMBER OF ADMINISTRATIVE OFFICE	NUMBER OF REQUIRED FIRE EXTINGUISHER	NUMBER OF ACTIVE FIRE EXTINGUISHER	SMOKE DETECTOR	ALARMS	REMARKS
01		2	Yes	6	1	0	0	3	FE 03 FPM, FE 04 FPM, FE 05 FPM	N/A	ALARM 01 M (Covering)	
02		1	N/A	1	2	1	0	2	1	N/A	ALARM 01 M	
03		1	N/A	1	0	0	0	1	0	N/A	ALARM 01 M (Covering)	
ANC 01	School Canteen	1	N/A	0	1	0	0	1	1	N/A	ALARM 01 M (Covering)	
04		2	Yes	10	3	0	2	6	FE 12 FPM	0	ALARM 01 M (Covering)	
05		1	N/A	1	0	0	0	1	0	N/A	ALARM 02 B (Covering)	
06		1	N/A	1	1	0	0	1	0	N/A	ALARM 02 B (Covering)	
07		1	N/A	3	0	0	1	2	FE 01 FPM, FE 02 FPM	1	ALARM 02 B	
08		2	Yes	6	0	0	0	2	0	N/A	ALARM 02 B (Covering)	

Prepared by:

Certified Correct:

JESUS ARPON

AURORA S, LUNA

School DRRM Coordinator

School Head / Principal



DEPED DRRM

FIRE ALARM SYSTEM INSPECTION AND COVERAGE DETAILS

Name of School: TABACUHAN ES

School ID: 107130

Name of School Head: AURORA S, LUNA

DRRM Coordinator: JESUS ARPON

ALARM CODE	ASSIGNED BUILDING	ALARM TYPE	STATUS	LAST DATE CHECKED	NEXT TEST DUE	REMARKS
ALARM 01	Installed: 02 Covering: 01, 03, ANC 01 (School Canteen), 04	Mechanical	ACTIVE	Apr 16, 2026	May 16, 2026	Change the location and add switches if possible have it labeled.
ALARM 02	Installed: 07 Covering: 05, 06, 08	Bell	ACTIVE	Apr 16, 2026	May 16, 2026	Please change the switch to pull down switch and have it labeled

Overall Purpose: This sheet is designed for monitoring the alarm's overall coverage of the school, its status, and the type of alarm system installed.

Prepared by:

Noted by:

School DRRM Coordinator

School Head / Principal



DEPED DRRM

FIRE EXTINGUISHER INSPECTION AND COVERAGE DETAILS

Name of School: TABACUHAN ES
School ID: 107130

Name of School Head: AURORA S, LUNA
DRRM Coordinator: JESUS ARPON

EXTINGUISHER CODE	BUILDING	ROOM COVERED / LOCATION	STATUS	DATE LAST CHECKED	TYPE	REMARKS
07	02	Room 1 (Room 102 taking cover)	ACTIVE	Apr 16, 2026	ABC	
FE 01	07	Room 3 (Room 101 & Room 103 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	
FE 02	07	Room 1 Principal's Office	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	
FE 03	01	SCHOOL CLINIC	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	Please hang the fire extinguisher and put label and instructions on how to use.
FE 04	01	Room 2 (Room 102 & Room 104 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	Please hang the fire extinguisher and put label and instructions on how to use.
FE 05	01	Room 5 (Room 201 & Room 203 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	Please hang the fire extinguisher and put label and instructions on how to use.
FE 10	ANC 01 (School Canteen)	School Canteen	ACTIVE	Apr 16, 2026	ABC	Please hang the fire extinguisher and put label and instructions on how to use.
FE 12	04	Room 2 (Room 101 & Room 103 taking cover)	FOR PREVENTIVE MAINTENANCE	Apr 16, 2026	ABC	
Summary	Existing / Needed: 8 / 19	Passed / Needed: 2 / 19	Needs Attention	—		
Status Totals	Active: 2	For Preventive Maintenance: 6	Used: 0	Missing: 0	For Purchase: 0	—

Overall Purpose: This sheet is designed for equipment-level tracking, allowing monitoring of maintenance schedules, operational readiness, placement coverage, and compliance documentation.

Prepared by:

Approved by:

School DRRM Coordinator

School Head / Principal



DEPED DRRM

BUILDING ROOM DETAILS & COVERAGE

Name of School: TABACUHAN ES

School ID: 107130

ROOM INFORMATION

#	ROOM CODE	ROOM NAME	BUILDING	FLOOR	ROOM TYPE	2ND EXIT	SMOKE DETECTOR	COVERED BY	REMARKS
1	102	Room 1	01	1	Classroom	Yes	N/A	FE 04	With more than the prescribed number of Electric Fans (7)
2	103	Room 2	01	1	Classroom	Yes	N/A	FE 04 (Center)	With more than the prescribed number of Electric Fans (5)
3	104	Room 3	01	1	Classroom	Yes	N/A	FE 04	—
4	101	SCHOOL CLINIC	01	1	Clinic	No	N/A	FE 03 (Center)	Secure circuit breaker
5	201	Room 4	01	2	Classroom	Yes	N/A	FE 05	With more than the prescribed number of Electric Fans (5)
6	202	Room 5	01	2	Classroom	Yes	N/A	FE 05 (Center)	—
7	203	Room 6	01	2	Classroom	Yes	N/A	FE 05	With more than the prescribed number of Electric Fans (7), 2 televisions and 1 water dispenser
8	101	Room 1	02	1	Laboratory	No	No	07 (Center)	Secure electrical connections and extension chords
9	102	Room 2	02	1	Classroom	No	N/A	07	—
10	101	Room 1	03	1	Classroom	Yes	N/A	Uncovered	For further assessment
11	101	School Canteen	ANC 01 - School Canteen	1	Canteen	No	N/A	FE 10 (Center)	—
12	106	HE ROOM	04	1	Administration	No	N/A	Uncovered	Please secure ventilation
13	101	Room 1	04	1	Classroom	Yes	N/A	FE 12	With more than the prescribed number of Electric Fans (6)
14	102	Room 2	04	1	Classroom	Yes	N/A	FE 12 (Center)	With more than the prescribed number of Electric Fans (7)
15	103	Room 3	04	1	Classroom	Yes	N/A	FE 12	—
16	104	Room 4	04	1	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (6)
17	105	Room 5	04	1	Classroom	Yes	N/A	Uncovered	For further assessment

#	ROOM CODE	ROOM NAME	BUILDING	FLOOR	ROOM TYPE	2ND EXIT	SMOKE DETECTOR	COVERED BY	REMARKS
18	ANC - 01	Guidance Office	04	2	Administration	No	No	Uncovered	—

#	ROOM CODE	ROOM NAME	BUILDING	FLOOR	ROOM TYPE	2ND EXIT	SMOKE DETECTOR	COVERED BY	REMARKS
19	205	Room 10	04	2	Classroom	Yes	N/A	Uncovered	—
20	201	Room 6	04	2	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (6)
21	202	Room 7	04	2	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (6)
22	203	Room 8	04	2	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (7)
23	204	Room 9	04	2	Classroom	Yes	N/A	Uncovered	—
24	ANC 02	School Reading Center	04	2	Library	No	N/A	Uncovered	—
25	101	Room 1	05	1	Classroom	Yes	N/A	Uncovered	—
26	101	Room 1	06	1	Classroom	No	N/A	Uncovered	For further assessment
27	101	Alive Center	07	1	Classroom	Yes	N/A	FE 01	—
28	104	Room 1 Principal's Office	07	1	Administration	Yes	Yes	FE 02 (Center)	Install Smoke Detectors
29	103	Room 2	07	1	Classroom	Yes	N/A	FE 01	With more than the prescribed number of Electric Fans (5)
30	102	Room 3	07	1	Classroom	Yes	N/A	FE 01 (Center)	With more than the prescribed number of Electric Fans (5)
31	101	Room 1	08	1	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (8)
32	102	Room 2	08	1	Classroom	Yes	N/A	Uncovered	—
33	103	Room 3	08	1	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (6)
34	203	Room 4	08	2	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (8)
35	202	Room 5	08	2	Classroom	Yes	N/A	Uncovered	With more than the prescribed number of Electric Fans (6)
36	201	Room 6	08	2	Classroom	Yes	N/A	Uncovered	—

Prepared by:

Approved by:

School DRRM Coordinator

School Head / Principal



Name of School: TABACUHAN ES
School ID: 107130

Name of School Head: AURORA S, LUNA
DRRM Coordinator: JESUS ARPON

School-Wide Evacuation Plan (Entire School)

No school-wide evacuation plan has been created yet.

Individual Building Evacuation Plans

No individual building evacuation plans have been created yet.

Overall Purpose: *This document serves as the official compilation of evacuation plans and assigned assembly parameters, providing critical action directives during emergencies.*

Prepared by:

Noted by:

School DRRM Coordinator

School Head / Principal

